

a Part target




24 s

b Assembly target

52 s

c Contact approach

128 s



● Pick / Screw

● Place / Push / Insert