Holy City Audio Forum

Former Home of SpinCAD Designer Skip to content

Search... Search
Advanced search

[Moderator Control Panel]

Cool guitar patch

Post a reply

Search this topic... Search

1 post • Page 1 of 1

- Edit post (./posting.php?mode=edit&f=30&p=1264)
- Delete post (./posting.php?mode=delete&f=30&p=1264)
- Report this post (./report.php?f=30&p=1264)
- Information (./mcp.php?i=main&mode=post_details&f=30&p=1264& sid=befaf904784df501ab581b011c284453)
- Reply with quote (./posting.php?mode=quote&f=30&p=1264)

Cool guitar patch (#p1264)

by Digital Larry » Sun May 12, 2013 1:51 pm

I made a state variable filter block that splits the input into low pass, band pass, and high pass.

Low pass goes to a ring modulator on pot 0. This adds a little background "grunge".

Band pass goes to a distortion.

High pass goes to chorus. MN3011 BBD simulator used for echo.

Check out the diagram and the code!

Edit: If you are wondering why some of the blocks have unconnected control inputs (those little circles on the left side of a block), every SpinCADBlock can assign a default value for whatever parameter that input is controlling, in the event that no control is actually connected. I haven't actually gotten to the point yet where you can adjust what the default value is for every SpinCADBlock, but this seems like a logical goal.

Image (http://imageshack.us/photo/my-images/824/spincadsvf.png/)

Uploaded with ImageShack.us (http://imageshack.us)

```
; Program: Render Block exported from SpinCAD Designer SOF 0.0,0.0

LDAX 20

RDAX 34,-1.0

RDAX 33,-1.0

WRAX 32,0.1

RDAX 33,1.0
```

1 of 4 11/26/2019, 7:21 AM

WRAX 33,0.1

RDAX 34,1.0

WRAX 34,0.1

RDAX 17,1.0

SOF 0.41,0.07

WRAX 35,0.0

SKP \$80000000,3

WRAX 36,0.0

SOF 0.0, -1.0

WRAX 37,0.0

RDAX 36,0.13

MULX 16

RDAX 37,1.0

WRAX 37,-0.13

MULX 16

RDAX 36,1.0

WRAX 36,1.0

MULX 34

WRAX 38,0.0

RDAX 33,0.25

SOF -2.0, 0.0

RDAX 39,0.9

WRAX 39,1.0

- - ,

SOF -2.0, 0.0

RDAX 40,0.3

WRAX 40,1.0

SOF -2.0,0.0

RDAX 41,0.7

WRAX 41,1.0

RDAX 42,-0.3

WRAX 42,0.3

WRAX 43,0.0

SKP \$80000000,1

WLDS 1,12,999

CLR

RDAX 35,1.999

SOF 1.9999,0.0

SOF 0.002,0.0

RDAX 47,0.998

WRAX 47,0.0

RDAX 35,0.05

SOF 0.002,0.0

RDAX 45,0.998

WRAX 45,0.0

RDAX 35,1.0

MULX 35

MULX 35

SOF 0.3,0.01

WRAX 2,0.0

RDAX 35,1.0

SOF -0.5, 0.999

WRAX 48,1.0

MULX 48

MULX 48

MULX 48

MULX 45

SOF 0.002,0.0

RDAX 46,0.998

WRAX 46,1.0

WRAX 3,0.0

RDAX 32,1.0

WRA 0,0.0

CHO RDA, 1, 06, 1000

CHO RDA, 1, 00, 1001

MULX 47

RDAX 32,1.0

WRAX 44,1.0

RDAX 44,0.5

SOF 0.002,0.0

RDAX 38,1.0

WRAX 50,0.0

RDAX 44,1.0

RDAX 50,1.0

. . . .

WRAX 49,0.0

RDAX 43,1.0 WRAX 52,0.0

RDAX 49,1.0

101111 15,1.0

RDAX 52,1.0

WRAX 51,0.0

SKP \$8000000,2

CLR

WRAX 53,0.0

RDAX 53,0.9550247081704994

RDAX 43,0.04497529182950055

WRAX 53,0.0

RDAX 53,1.0

RDAX 53,0.45

RDAX 54,0.25

RDFX 55,1.25

WRHX 55,1.0

WRA 2001, 0.75

RDA 3171,0.35

RDA 3956,0.35

RDA 5528,0.35

RDA 7099,0.051
RDA 10242,0.051
RDA 11832,0.051
WRAX 56,0.0
RDA 11832,0.25
WRAX 54,0.0
RDAX 56,1.0
WRAX 56,0.0
RDAX 51,1.0
WRAX 58,0.0
RDAX 56,1.0
MULX 18
RDAX 58,1.0
WRAX 57,0.0
RDAX 57,0.0
RDAX 57,1.0

Top

Post a reply

WRAX 22,0.0 RDAX 57,1.0 WRAX 23,0.0

1 post • Page **1** of **1**

Return to SpinCAD Designer patches

Jump to: SpinCAD Designer patches	Go
Quick-mod tools: Lock topic	Go

Who is online

Users browsing this forum: Digital Larry and 0 guests Powered by phpBB® Forum Software © phpBB Group

Administration Control Panel

4 of 4