



交通部航港局航船布告

中華民國 113 年 1 月 2 日

1 台馬第二海纜於112年12月29日至113年1月31日由Cable Retriever(IMO9063287)海纜船進行海纜維修作業。

依 據 內政部 112 年 12 月 28 日 台內地字第 1120149098 號函。
說 明

1. 依內政部112年12月28日台內地字第1120149098號函辦理。

2. 旨案作業位置坐標如附件。

位 置 北緯 26°05'57.6" ，東經 121°03'48.4" 。
北緯 26°04'36.8" ，東經 121°05'42.8" 。
北緯 26°05'38.6" ，東經 121°07'14.2" 。
北緯 26°06'58.8" ，東經 121°05'22.0" 。 *WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

January 2, 2024

1 Taiwan North e rn Waters — Submarine Cable Maintenance

Source Taiwan Ministry of Interior Letter No. 1120149098 dated December 28, 2023
Details Submarine cable maintenance work within area bounded by the following position
will be undertaken by Cable Retriever (IMO9063287 from December 29, 2023 to
January 31, 2024. Mariners are advised to navigate with caution in this area □
Positions Lat. 26°05'57.6" N., Long. 121°03'48.4" E.
Lat. 26°04'36.8" N., Long. 121°05'42.8" E.
Lat. 26°05'38.6" N., Long. 121°07'14.2" E.
Lat. 26°06'58.8" N., Long. 121°05'22.0" E. *WGS84

*Maritime and Port Bureau, MOTC, R.O.C.
Director General Yeh, Hsieh-Lung*