



1	2	3	4	5	6
A					
B	power File: power.kicad_sch polygon File: polygon.kicad_sch connectors File: connectors.kicad_sch galvo File: galvo.kicad_sch				
C					
D	Sheet: / File: LaserBrain.kicad_sch Title: Size: A4Date:KiCad E.D.A. 10.0.5 Rev:Id: 1/6				
1	2	3	4	5	6


Pump Inverter -5V




15V Jack




Galvo PSU Connections



Boost 24V




regulators



File: regulators.kicad_sch

Power Flags



Sheet: /power/
File: power.kicad_sch

Title:


Size: A4
KiCad E.D.A. 10.0.5

Date:


Rev:

Id: 5/6


Buck 12V




Buck 9V




Buck 6V




Buck 3.5V



Buck 5V



LDO 3.3V



Sheet: /power/regulators/
File: regulators.kicad_sch

Title:



Size: A4
KiCad E.D.A. 10.0.5

Date:


Rev:

Id: 6/6


Laser Board




Mounting Holes




OPB917BOCZ Connections




Pull Ups/Downs




PWM_POLYGON_BREAKOUT




POWER BREAKOUT



MANGO PI



PWM_FANS_CONNECTOR



Sheet: /connectors/
File: connectors.kicad_sch

Title:


Size: A4 Date:

KiCad E.D.A. 10.0.5


Rev:

Id: 3/6


DAC



Op-Amp



Galvo Connector



If skipping dac, we can do V_DAC to JST pin 1 and 3v3 + 10k resistor divider to pin 3

Sheet: /galvo/
File: galvo.kicad_sch

Title:


Size: A4 Date:

KiCad E.D.A. 10.0.5

Rev:

Id: 4/6

PWM 3V3->5V Logic



Sheet: /polygon/
File: polygon.kicad_sch

Title:

Size: A4 Date:

KiCad E.D.A. 10.0.5

Rev:

Id: 2/6

