# Interlockgo-XOCO



## Drive on the "Right Side" of the law Anson Cordeiro

3610 35TH AVENUE UNIT 7 EVANS, CO 80620 (970)515-5740









### **TRAINING VIDEOS**







**ENGLISH** 

### HANDSET



#### **BLOW**

THE DEVICE IS READY TO ACCEPT A BREATH TEST. HUM AND BLOW INTO THE DEVICE FOR ABOUT 5 SECONDS.

EL DISPOSITIVO ESTÁ LISTO PARA ACEPTAR UNA PRUEBA DE ALIENTO. TARAREE Y SOPLE EN EL DISPOSITIVO DURANTE UNOS 5 SEGUNDOS.

#### **WAIT**

THE DEVICE IS PREPARING TO ACCEPT A BREATH TEST. SOLID - HANDSET WARMING UP. FLASHING - PREPARING HANDSET FOR CALIBRATION. SOLID AFTER BLOW - ANALYZING BREATHE TEST.

EL DISPOSITIVO SE ESTÁ
PREPARANDO PARA ACEPTAR UNA
PRUEBA DE ALIENTO.
FIJO: EL AURICULAR SE ESTÁ
CALENTANDO.
PARPADEANDO: PREPARANDO EL
AURICULAR PARA LA CALIBRACIÓN.
FIJO DESPUÉS DE SOPLAR:
ANALIZANDO LA PRUEBA DE
ALIENTO.

#### **ABORT**

DEVICE COULD NOT ANALYZE BREATHE TEST. PLEASE TRY AGAIN THE DEVICE WILL RESET AND ADMINISTER ANOTHER BREATHE TEST. RESET TAKES UP TO 45 SECONDS.

EL DISPOSITIVO NO PUDO ANALIZAR LA PRUEBA DE ALIENTO. POR FAVOR INTÉNTELO DE NUEVO. EL DISPOSITIVO SE REINICIARÁ Y ADMINISTRARÁ OTRA PRUEBA DE ALIENTO. EL REINICIO PUEDE TARDAR HASTA 45 SEGUNDOS.

#### Pass Light (Green)

When the Device receives a proper breath sample the **PASS** light will glow and a triple tone will sound indicating a successful test.

You can start your vehicle!

BAC. 0.000 - 0.019

#### Warn Light (Orange)

The Device has detected the presence of alcohol on your breath below the FAIL level.

BAC. 0.020 - 0.024

#### Fail Light (Red)

The Device has detected the presence of alcohol above the preset **FAIL** level.

**BAC.** 0.025 +

#### Service Light (Red)

The Device will remind you several days before your program service due date by flashing the **SERVICE** light.

#### **LOCKOUT LIGHT OR LOCKOUT MODE**

THE HANDSET HAS DETECTED A VIOLATION. CALL MY SHOP IMMEDIATELY TO SCHEDULE AN APPOINTMENT FOR A RESET OF THE HANDSET. THE LOCKOUT LIGHT WILL FLASH FOR 5 DAYS, AFTER THAT, THE LIGHT WILL TURN SOLID AND YOU WILL NOT BE ABLE TO START YOUR VEHICLE. THE LONGER YOU WAIT TO SCHEDULE THE APPOINTMENT, THE LESS LIKELY I WILL BE ABLE TO ACCOMMODATE YOUR BUSY SCHEDULE.

#### LUZ DE BLOQUEO O MODO DE BLOQUEO

EL AURICULAR HA DETECTADO UNA INFRACCIÓN. LLAME A MI TALLER DE INMEDIATO PARA PROGRAMAR UNA CITA PARA RESTABLECER EL AURICULAR. LA LUZ DE BLOQUEO PARPADEARÁ DURANTE 5 DÍAS: DESPUÉS DE ESO, LA LUZ QUEDARÁ FIJA Y NO PODRÁ ENCENDER SU VEHÍCULO. CUANTO MÁS TARDE EN PROGRAMAR LA CITA, MENOS PROBABLE SERÁ QUE PUEDA ADAPTARME A SU APRETADA AGENDA.