

Aegis Series-7 Hydraulic Control System

Alarm Reference

Document AEG-AL-700 | Revision 5 (incorporates ECN-1058)

Alarm	Condition	Panel Indication	Possible Cause(s)	Required Action
A17	Hydraulic pressure below 150 bar	RED	1. IV-21 closed or partially closed 2. Low hydraulic fluid 3. Pressure sensor signal invalid	See Section 4 of the Maintenance Manual. If persistent > 10 s, run Shutdown Proc. 4.7*
A18	Hydraulic pressure above 220 bar	AMBER	1. Relief valve fault 2. Setpoint misconfiguration	Stop the HPU. Do not restart until pressure relief is verified.
A19	Pressure sensor signal invalid	RED	1. Sensor wiring fault 2. Sensor drift beyond tolerance (see ECN-1042)	Replace sensor per Maintenance Manual Section 6.

* Shutdown Procedure 4.7 applies only when A17 persists beyond 10 seconds. A transient A17 that clears on its own during normal valve transition does not require Procedure 4.7 (see Maintenance Manual AEG-MM-700, Section 4).

Note on sensor references: prior to Revision 5 of this document, the condition for A17 referenced sensor PS-04 by name. Per ECN-1058, the condition is evaluated against whichever pressure sensor is active for the installed software revision (PS-04 or PS-04A). The 150 bar and 220 bar thresholds shown above are unchanged by ECN-1058.

Continued: Alarm Reference (AEG-AL-700)

Alarms A01–A16 and A20–A34 (electrical, lubrication, and communications alarms) are documented in the companion Electrical Alarm Reference, AEG-AL-701, which is not part of this package.