
Trusted sensors
Motor: 6 currents
PCC: voltage/current
Window acquisition
2,000 samples
0.2 s at 10 kHz
LF / HF / TD
61 temporal steps
Normalize inputs
Selected model
Binary or severity
Alarm + logging
Whole recordings and all their episodes remain in one partition
Training recordings
Fit normalization + models
Validation recordings
Select model + rank features
Test recordings
Evaluate once per condition