

EXPT. NO.	NAME	M T W T F S S	Page No. 24	YOUVA
		Date		

metal

(c) Punch

A Punch is used in a bench work for marking out work, locating centres etc. in a more permanent manner than that of scriber usually.

Two types of Punches are used in fitting shop

(i)

(i) Pick Punch

It consists of a tapered portion sharply pointed having the angle of 40° . It is used for marking small marks on the line.

(ii) Centre Punch

It is used for marking the pick punch hole larger. Usually the centre holes for drilling are marked using centre punch. Its angle at the tip is usually 60° .

(d) V-Block

It is a steel block having a V shaped groove. It is used for marking or working on round end objects, so that that object can't move side-wise and also does not rotate easily.

(e) Try Square

It is a measuring and marking tool for 90° angle in practice, it is used for checking the squareness and many types of small works when

Teacher's Signature: _____