

EXPT. NO.	NAME	M T W T F S S	Page No.: 30	YOUVA
			Date:	

Precautions

- (i) Loose clothing should be avoided
- (ii) Tools should be placed in their respective places
- (iii) One must wear shoes while working in a fitting shop
- (iv) Sharp edge of the cutting tools should be covered when they are not in use
- (v) One must always wear goggles while chipping metal and while grinding edge on tool

Questions

Q1) What do you understand by draw fitting?
Working on components with handtools and instruments on work benches which includes marking, fitting, sawing, scraping, drilling, tapping, grinding etc. are called fitting.

Q2) Name the various fitting operations.
The various fitting operations are:-

- (i) Marking
- (ii) Sawing
- (iii) Chipping
- (iv) Filing
- (v) Scraping
- (vi) Boring
- (vii) Drilling
- (viii) Reaming
- (ix) Tapping
- (x) Dieing

Teacher's Signature: _____