

XPT.
ID.

NAME

M T W T F S S
Page No.: 35
Date: YOUVA

Q3) What is the main use of vernier in fitting shop?

A vernier caliper in a fitting shop is used for measuring external, internal and depth dimensions of components during fabrication and assembly.

Q4) How drill sizes are calculated for tapping?

Tap drill size is given by,

$d = \text{major dimension} - \text{pitch}$

Here, $d = x \times \frac{7}{8} - \frac{1}{32}$ (as per the tool used)

$$\begin{aligned} \text{drill size} = d &= \frac{3}{8} \times \frac{7}{8} - \frac{1}{32} \\ &= \frac{19}{64} \end{aligned}$$

$$\left[\text{Tap size}(x) = \frac{3}{8} \right]$$

Teacher's Signature: _____