

3) Chipping Hammer

It is used to remove slugs which form during welding

4) Ground Clamp

It is connected to the end of the ground cable. It is normally clamped to the welding table or the job itself to complete the electric circuit

5) Wire Brush

Cleans to surface for welding

6) Electrode Holder

Device used for mechanically holding the electrode and conducting current to it

Process sheet

Process	Description	Tools and Equipments
Prepare work pieces	Cut 2 flat pieces of mild steel of required dimensions and place them on table	Hammer, Chisel Scale
Machine Setup	Adjust welding machine parameters as per requirements	welding set Electrode Holder
Electrode selection	Choose suitable electrode size and fix it in the	Electrode Electrode Holder

Teacher's Signature: _____