

Job Removal Allow the joints to weld and inspect the weld. Dip the job on a bucket of water to let it cool

Tongs

Precautions

- Fire extinguisher should be available at the hand
- Working area and floor should be kept clean
- Wear shoes while working one shoe
- Welders should wear w and fire proof protective clothes
- If you have any accident, report it to your instructor immediately.

Questions:-

Q Describe the use of different types of flames?

Neutral Flames

It have a balanced fuel O₂ ratio and are used for most common metals

Carburizing Flame

These have extra fuel and are used for specific process like welding lead, add carbon to it

Oxidising Flame

These are hotter and are used for some metals like brass, zinc and create oxide film on surface