

EXPT.
NO.

NAME _____

M T W T F S S

Page No.: 26

Date: _____

YOUVA

These make slots wider than the blade from jamming. Blades are made of ~~the~~ high carbon steel or alloy steel.

(b) Chisels

Chisels are made up of carbon steel they are used chipping operations i.e. used for removing surplus metals or for cutting thin sheets. Chisels are annealed, hardened and tempered to produce a tough shock and hard cutting edge. Annealing relieves the stress in a metal. The cutting angle of chisel for general purpose is about 60° .

(c) Scrapers

They are used for scraping which is also a finishing tool of fitting shop. They contain very hard cutting edge and are made of forged steel. The cutting edge is hardened and tempered to make it able to scrape the material and to make the surface of the job plane.

(d) Files

Files are most widely used tool of the fitting shop. The different parts of the files are handle, tang, heel, face, point and edge. The files are made of high carbon steel tungsten steel by forging then the teeth are cut, hardened and tempered. The files used in fitting shops are classified on the basis of the following factors:-

Teacher's Signature: _____