Take this quiz after watching:

- J\_RBE\_2001\_SOLIDWORKS\_INTRO\_COLLISION\_DETECTION
- K\_RBE\_2001\_SOLIDWORKS\_INTRO\_EXPLODED\_ASSEMBLY

## **Question 1**

In the SolidWorks Exploded View function, multiple parts can be included in a single explode step.

ANS: True

## **Question 2**

It is important to plan the order of your explode steps carefully, because once the steps are created, the order of the steps and the position of the parts cannot be changed.

ANS: False

## **Question 3**

In general, when choosing the orientation for an exploded view you should choose a standard isometric view orientation or an orientation in which the assembly appears to be sitting level.

ANS: True