Reducing Complicated Block Diagrams:

O. Move summation and take-eff post to destable persons stagend


1. Combine all carcade blocks (multiply) (6,62) hops)


2. Combine all parallel blocks (add) (6,42)


J. Fliminale all feedback loops (6)

1. Fliminale all feedback loops (7)

## Block Diagram Transformations







Modeling Mechanical Systems: \* "ALL MODELS ARE WRONG, BUT Some ARE WATPUL!" L. Hox law: F=mj (2nd order system) un jung jang (Double integrator) A Common method to standardize: State-space form

State-Space Form

$$\overrightarrow{x} = A \overrightarrow{x} + B \overrightarrow{u} \quad (state 29n)$$

$$\overrightarrow{y} = C \overrightarrow{x} + D \overrightarrow{u} \quad (output 29n)$$

$$\overrightarrow{x} = \begin{pmatrix} \overrightarrow{x}_1 \\ \overrightarrow{x}_2 \end{pmatrix}$$

$$\overrightarrow{x} = \begin{pmatrix} \overrightarrow{x}_1 \\ \overrightarrow{x}_2 \\$$