Q1 Production Logs — 31 Jan 26

Jan 26 logs

1/12 - Drive motor burnout on Conveyor A. Unplanned stoppage: DT - 150 mins

1/20 - Operator ergonomic complaint filed regarding loading height at Sta 2. no DT

1/29 - Sensor misalignment on Pkg Robot. Unplanned stoppage. DT - 50 mins