X Construction Sdn Bhd INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A								
Report NO : 161057								
Investigation Team								
1. AnasSHO (Leader)								
2. Amir								
3. Hilmi								
Terms of Reference								
1. Site Of Incident	REF-20240521-HDOAJO							
2. Copy Of HIRARC	REF-20240521-LJWVVS							
3. Interview Victims or Witness	\odot							
Category of Incident : Fatal								
	ategory of Incident : Fatal 'hen and Where did the Incident Occur?							
The incident occurred on 21-05-2	2025 at 13:12:00. It occurre	ed at Sarawak.						
Description of the incident :								
A fifth-grade student died after being struck by a goalpost while hanging from it.								
Description of property damage (if any) :								
Goalpost has broken.								
How did the incident occur :								
REF-20240521-QBB4XW								
Kid was hanging on a broken and rusty goalpost which eventually broke and cause the fall.								
Findings of the investigation :								
The goalpost is already rusty and	d on the end of being broke	n.						
Reported By :								
Z								
AnacSHO								

Hazard Identification				Risk Assess	sm	en		Risk Control			
N	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Respo
1	Material management	Obstruct Material		+short briefing before work +use proper PPE	2	3	6	М			Superv
2	Erection & and installation of false work/ temporary structure	Pinch point	Minor Injury	+toolbox briefing +use trained workers +short briefing before work +use proper PPE	2	2	4	L			Superv
3	Cont	Falling Material	+physical injury +material damage	workers	3	3	9	М			Superv

Rev No:

Issue Date:2024-04-11

Hazard Identification			fication	Risk Assessment						Risk Control		
	No	Job Sequence	Hazard	Risk	Current Control	L	s	Score	Index	Opportunity	New Control (Suggestions)	Responsi
	4	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	М			Superviso

Rev No:

Issue Date:2024-04-11