X Construction Sdn Bhd INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A							
Report NO: 161057							
Investigation Team							
1. AnasSHO (Leader)							
2. Amir							
3. Hilmi							
Terms of Reference							
1. Site Of Incident	REF-20240521-M4L3VM						
2. Copy Of HIRARC	REF-20240521-VZBWV7						
3. Interview Victims or Witness	\bigcirc						
Category of Incident : Fatal							
When and Where did the Incider	nt Occur?						
The incident occurred on 21-05-2	2025 at 13:12:00. It occurre	ed at Sarawak.					
Description of the incident :							
A fifth-grade student died after being struck by a goalpost while hanging from it.							
Description of property damage (if any) :							
Goalpost has broken.							
How did the incident occur :							
REF-20240521-S2XG2Y							
Kid was hanging on a broken and rusty goalpost which eventually broke and cause the fall.							
Findings of the investigation :							
The goalpost is already rusty and on the end of being broken.							
Reported By :							
mage not found or type unknown							
AnacSHO							

Hazard Identification				Risk Assess	sm	en	Risk Control				
N	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Respo
1	Material management	Obstruct Material		+short briefing before work +use proper PPE	2	3	6	М			Superv
2	Erection & and installation of false work/ temporary structure	Pinch point	Minor Injury	+toolbox briefing +use trained workers +short briefing before work +use proper PPE	2	2	4	L			Superv
3	Cont	Falling Material	+physical injury +material damage	workers	3	3	9	М			Superv

Rev No:

Issue Date:2024-04-11

X Construction Sdn Bhd INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A							
Report NO: 161057							
Investigation Team							
1. AnasSHO (Leader)							
2. Amir							
3. Hilmi							
Terms of Reference							
1. Site Of Incident	REF-20240521-M4L3VM						
2. Copy Of HIRARC	REF-20240521-VZBWV7						
3. Interview Victims or Witness	\bigcirc						
Category of Incident : Fatal							
When and Where did the Incider	nt Occur?						
The incident occurred on 21-05-2	2025 at 13:12:00. It occurre	ed at Sarawak.					
Description of the incident :							
A fifth-grade student died after being struck by a goalpost while hanging from it.							
Description of property damage (if any) :							
Goalpost has broken.							
How did the incident occur :							
REF-20240521-S2XG2Y							
Kid was hanging on a broken and rusty goalpost which eventually broke and cause the fall.							
Findings of the investigation :							
The goalpost is already rusty and on the end of being broken.							
Reported By :							
mage not found or type unknown							
AnacSHO							

Ha	zard Identi	fication	Risk Assessment					Risk Control			
No	Job Sequence	Hazard	Risk	Current Control	L	s	Score	Index	Opportunity	New Control (Suggestions)	Responsi
4	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	М			Superviso

Rev No:

Issue Date:2024-04-11