

X Construction Sdn Bhd
INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A	
Report NO : 161057	
Investigation Team	
1. AnasSHO (Leader)	
2. Amir	
3. Hilmi	
Terms of Reference	
1. Site Of Incident	REF-20240521-ASDHEM
2. Copy Of HIRARC	REF-20240521-9C7ANI
3. Interview Victims or Witness	<input checked="" type="checkbox"/>
Category of Incident : Fatal	
When and Where did the Incident Occur?	
The incident occurred on 21-05-2025 at 13:12:00. It occurred at Sarawak.	
Description of the incident :	
A fifth-grade student died after being struck by a goalpost while hanging from it.	
Description of property damage (if any) :	
Goalpost has broken.	
How did the incident occur :	
REF-20240521-ICCMB1	
Kid was hanging on a broken and rusty goalpost which eventually broke and cause the fall.	
Findings of the investigation :	
The goalpost is already rusty and on the end of being broken.	
Reported By :	
 AnasSHO	

X Construction Sdn Bhd
INCIDENT/ACCIDENT INVESTIGATION REPORT

PART B

Report NO : 161057

Need For Corrective Actions:

1. Revise the maintenance schedule to ensure more frequent and thorough checks
2. Implement a new monitoring system to track adherence to the maintenance schedule and provide alerts for upcoming tasks
3. Implement a new monitoring system to track adherence to the maintenance schedule and provide alerts for upcoming task

Mitigative Actions:

1. Develop a contingency plan to minimize production downtime in case of machine failure.
2. Create a budget allocation for emergency repairs to ensure quick financial response.
3. Conduct regular safety drills and simulations to ensure that employees are prepared to handle emergencies efficiently and effectively

Mitigative Actions:

1. Develop and implement a comprehensive training program focused on machine operation and maintenance to ensure all employees are adequately trained on new and ex
2. Conduct regular safety drills and simulations to ensure that employees are prepared to handle emergencies efficiently and effectively

Penalty:

1. John Doe will receive a formal written warning for failing to adhere to the safety procedures.
2. Jane Smith will be suspended for three days without pay for failing to enforce safety procedures during her shift.

The results has been communicated to the following personnel:

Safety Committee	<input checked="" type="checkbox"/>
Project Manager	<input checked="" type="checkbox"/>
Staffs	<input checked="" type="checkbox"/>
Others	<input type="checkbox"/>

Signature (SHO) :



Name : AnasSHO

Date : 2024-05-20

ATTACHMENTS

Date:

Rev Number:REF-20240521-ASDHEM



جامعة
Teknologi
MARA



Figure 1. Leaf blight symptoms of *Pestalotiopsis microspora* initially observed





ATTACHMENTS

Date:

Rev Number:REF-20240521-ICCMB1



X Construction Sdn Bhd
HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ : X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM 	Hirarc No : Page : 1 of 2
Location: Jayyid	Verified By: AnasSHO 	Approved By: AnasPM 	Date : 21/05/2024

Hazard Identification			Risk Assessment					Risk Control			
No	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
1	Material management	Obstruct Material	Tripping by obstruct material	+short briefing before work +use proper PPE	2	3	6	M			Supervisor
2	Erection & and installation of false work/ temporary structure	Pinch point	Minor Injury	+toolbox briefing +use trained workers +short briefing before work +use proper PPE	2	2	4	L			Supervisor
3	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	M			Supervisor

Rev No: REF-20240521-9C7ANI

Issue Date:2024-04-11

X Construction Sdn Bhd
HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ : X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM 	Hirarc No : Page : 2 of 2
Location: Jayyid	Verified By: AnasSHO 	Approved By: AnasPM 	Date : 21/05/2024

Hazard Identification			Risk Assessment					Risk Control			
No	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
4	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	M			Supervisor

Rev No: REF-20240521-9C7ANI

Issue Date:2024-04-11