X Construction Sdn Bhd INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A						
Report NO : 744815						
Investigation Team						
1. AnasSV (Leader)						
2. AnasSHO						
Terms of Reference						
1. Site Of Incident	REF-20240523-HVF78L					
2. Copy Of HIRARC	REF-20240523-S5LWKM					
3. Interview Victims or Witness	\odot					
Category of Incident :						
Fatal						
When and Where did the Incider	nt Occur?					
Illum sunt molesti						
Description of the incident :						
Ex suscipit atque ma						
Description of property damage	(if any) :					
Quia ipsa fugiat et						
How did the incident occur :						
REV NO : REF-20240523-DA10	BU2					
Incidunt fugit odi						
Findings of the investigation :						
Quas consequatur acc						
Reported By :						
Jan 1						
Name: AnasSV						

X Construction Sdn Bhd INCIDENT/ACCIDENT INVESTIGATION REPORT

PART B							
Report NO: 744815							
Need For Corrective Actions:							
1. Tenetur voluptatem e							
2. Harum ea aut laborio							
Mitigative Actions:							
1. Cillum omnis ipsum							
2. Laboriosam minim au							
Mitigative Actions:							
1. Et dolore ducimus a							
Penalty:							
1. Provident duis quis							
The results has been communicated to the following personnel:							
Safety Committee							
Project Manager							
Staffs							
Others							
Signature (SHO) :							
Image not found or type unknown							
Name : AnasSV							
Date :							

ATTACHMENTS

Date:

Rev Number: REF-20240523-HVF78L

Union

Vs

Intersection





ATTACHMENTS

Date: Rev Number:REF-20240523-DA1GU2





X Construction Sdn Bhd HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ: X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM	Hirarc No :
Location: Jayyid	Verified By: AnasSHO	\sim	Date: 23/05/2024

	Hazard Identificat	tion	Risk Assessment				Risk Control				
No	Job Sequence	Hazard	Risk	Current Control	L	s	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
1	Material management	Obstruct Material	Tripping by obstruct material	+short briefing before work +use proper PPE	2	3	6	M			Supervisor
2	Erection & and installation of false work/ temporary structure	Pinch point	Minor Injury	+toolbox briefing +use trained workers +short briefing before work +use proper PPE	2	2	4	L			Supervisor
3	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	M			Supervisor

Rev No: REF-20240523-S5LWKM

Issue Date:2024-04-11

X Construction Sdn Bhd HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ: X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM	Hirarc No : Page : 2 of 2
Location: Jayyid	Verified By: AnasSHO	Approved By: AnasPM	Date: 23/05/2024

Hazard Identification			Risk Assessment					Risk Control			
N	Job Sequence	Hazard	Risk	Current Control	L	s	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
4	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure		3		M			Supervisor

Rev No: REF-20240523-S5LWKM

Issue Date:2024-04-11