

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LSD-47	USS RUSHMORE		38E9347404		A01

TITLE:

SRBOC MK5 MOD4 RSL NO.2 and NO.3 on 06 Level; repair

JOB SPECIFICATION

Anticipated Award Date: 8/13/2026		Production Completion Date: 2/12/2027		PREPARING ACTIVITY: SASEBO	
POP Start Date: 10/12/2026		POP End Date: 7/31/2027			
PREPARED BY: K.KOMATSU			CODE H KO	DATE 2/25/2026	
APPROVED BY: S.MURAKAMI <i>Sm</i>			CODE S225		
CONCURRED BY: S.MOROOKA <i>SMA</i>			CODE S231		
ASSIST PLANNER'S NAME:			CODE		
ASSIST PLANNER'S NAME:			CODE		
ASSIST PLANNER'S NAME:			CODE		
DESCRIPTION:					
JSN(S): OW03-2622, OW03-2621			CASREP #		
S/F CONTACT: GM2 STUBBS / GM1 REED			CWP #	CCNS #	
Approved by S300/S900 <i>S. Amin Jones</i>			Date: 3-14-26	AVL: 701 Y.M. 3/31/26 Y.Mor: 661	
			LWC:		
Work Completed					
S/Force:		Rate:		Date:	
Ship Supt:		Date:		SRF CONTROL NO.: 1301351810	
WORK CERTIFICATION SIGNATURES					
COMPLETION OF WORK REVIEW:		BADGE NO.:	SHOP/CODE:	PHONE:	DATE:

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LSD-47	USS RUSHMORE		38E9347404		A01

TITLE:

SRBOC MK5 MOD4 RSL NO.2 and NO.3 on 06 Level; repair

1. SCOPE:

- 1.1 Title: SRBOC MK5 MOD4 RSL NO.2 and NO.3 on 06 Level; repair
- 1.2 Location of Work:
 - 1.2.1 06 Level Fr.33 Port Side (NO.2 RSL)
 - 1.2.2 06 Level Fr.33 Starboard Side (NO.3 RSL)
- 1.3 Identification: Quantity (2 EA), Ready Service Locker (SRBOC MK5 MOD4, 40 Inch Width by 56 Inch Depth by 62 Inch Height, Aluminum Alloy Body) NO.2 and NO.3, Located in 1.2.1 and 1.2.2
 - 1.3.1 A Total of (6) Linear Inch Length of Knife Edge

2. REFERENCES:

- 2.1 Standard Items (FY26) *27 Y.M 3/31/26 Y.Mori*
- 2.2 53711-6296845 Rev K, Locker, Ready-Service MK 5 MOD 4

3. REQUIREMENTS:

3.1 Conduct chalk test existing knife edge and gasket of each NO.2 and NO.3 ready service locker listed in 1.3 to ensure that condition cause of water leakage through the sealing of the door and determine location to be welded repair, using 2.2 for guidance.

3.1.1 Grind and weld build up the knife edge listed in 1.3.1 of each NO.2 and NO.3 ready service locker.

3.1.2 Grind smooth each built up knife edge and prepare seating surface for maintaining watertight as ammunition storage locker.

3.2 Remove existing, cut, and install each new gasket on door panel of ready service locker listed in 1.3 out of 1/2 inch thickness rubber strip (MIL-R-900, 45 Durometer) with adhesive.

3.2.1 Accomplish the requirements of **009-25** of 2.1 for a chalk test of each NO.2 and NO.3 ready service locker listed in 1.3.

3.3 Accomplish the requirements of **009-32** of 2.1 for cleaning and preservation of each new and disturbed surfaces to match surrounding areas.

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN: 38E9347404	Rev:	Key Op: A01
LSD-47	USS RUSHMORE				

TITLE:

SRBOC MK5 MOD4 RSL NO.2 and NO.3 on 06 Level; repair

4. NOTES:

4.1 Initial Condition - Jagged knife edge have been revealed by inspection and requested repair of ready service lockers NO.2 and NO.3 on 06 level weather deck.

5. GOVERNMENT FURNISHED MATERIAL (GFM) :

5.1 Government Furnished Material as follows.

MATERIAL LIST

MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA. NO.
001			M	GASKET, RUBBER, 35" W X 56" L X 1/2" T, 45 DUROMETER	9B 5330 013110013	N		1/EA	3.2