

USE OF OTHER THAN FULL AND OPEN COMPETITION SAT

1. Identification of Agency and Contracting Activity

Requiring activity is USS Manchester. Contracting Activity is NAVSUP FLCSD.

2. Nature and/or Description of the Action Being Approved

The vertical sheave assembly being requested is manufactured by OEM Trident Maritime systems. P/N (F183153) is a direct replacement for the faulty sheave that is onboard Manchester, the vertical sheave assembly is a rigging component with a grooved wheel (sheave) on a vertical axle, used to guide or redirect wire ropes/cables in applications winches, and steering systems, featuring robust construction (cast steel/aluminum), sealed bearings, and mounting bases for stability, ensuring smooth rope movement for lift loads. Key assembly aspects involve mounting securely, aligning sheaves properly, ensuring adequate bearing lubrication, and tensioning belts/ropes according to manufacturer efficient operation. Currently platform is OOC. operability of platform required for laser alignment and weight test. If operability is not restored, ship is down primary mission

3. Description of Supplies/Services to Meet the Agency's Needs Including Estimated Value

Replacement of vertical sheave assembly required. The vertical sheave assembly is an essential component of the ship's lifting and rigging systems. It functions to guide rope enabling the smooth and safe operation of crucial equipment such as cranes, davits, and mooring winches. By managing the direction and tension of these lines, the sheave ensures the precise control required for a variety of shipboard tasks, from cargo handling to emergency procedures. Cost is \$17,853.12 Trident Maritime systems is the OEM manufacturer the vertical sheave assembly being requested PN (F183153).

Is the requested material or service represents the minimum requirements of the Government Estimated Dollar?

Estimated Dollar Value:

FY/Option/Ordering Period	R
FY2026	

4. Statutory Authority Permitting Other Than Full and Open Competition

10 U.S.C. 3406(c)(5) as implemented by FAR

Additional Information Regarding Statutory Authority if Applicable

This part is exclusively manufactured as part of the contract for the platform lift. There are no other companies contracted to manufacture this part.

Procurement Request/Solicitation/Purchase Order Number: R200955325A199

Control Number:

I. Background

- 1. FAR 13.106-1(b)(1)(i) states for purchases not exceeding the simplified acquisition threshold, Contracting Officers may solicit from one source if the Contracting Officer determines the circumstances of the contract action deem only one source reasonably available (e.g., urgency, exclusive licensing agreements, brand-name or industrial mobilization).
- 2. As required by FAR 13.106-3(b)(3)(i), this memorandum explains the absence of competition for this acquisition, as only one source will be solicited for this requirement (of the requirement) and the requirement is not expected to exceed the simplified acquisition threshold.

II. DESCRIPTION OF ITEM OR SERVICE

Provide a description of the item or service required, to include its intended use, the name of the required source or brand name, the estimated cost/price, and the required date/period of performance

Please reference item 3 above (Description of Supplies/Services to Meet the Agency's Needs Including Estimated Value)

III. THE DETERMINATION FOR USE OF OTHER THAN FULL AND OPEN COMPETITION IS BASED ON THE FOLLOWING:

A. ONLY ONE RESPONSIBLE SOURCE	No	
1. Restrictive Rights	No	The source has established proprietary rights, limited rights in data, patent rights, copyright processes in the item or service required.
2. Exclusive Licensing Agreements	No	The item or service is only available from the Original Equipment Manufacturer (OEM), or the authorized distributor or technical representative for the OEM.
3. Other Reasons	No	Provide details on mission impact if requirement is not solicited from only one source
B. BRAND NAME	No	

Item required must be a brand name product, or feature of a product, particular to one manufacturer. Discuss why you are precluding consideration of a product made by another company. Describe how the particular brand name, product, or feature is essential to the Government's requirements and why a "brand name or equal" purchase cannot be used (see FAR 11.104). Describe how market research indicates other companies' similar products or products lacking the particular feature do not meet, or are modified to meet, the agency's needs

C. UNUSUAL AND COMPELLING URGENCY**Yes**

The supplies or services are of such unusual and compelling urgency that the Government would be seriously injured unless the agency is permitted to limit the number from which it solicits bids or proposals. Urgent requirements are supplies or services that will result in a work stoppage, or are mission critical and the routine process result in injury to the Government. The determination that the procurement for the above item/service is an urgent and compelling requirement is based on the following:

Discuss why you are precluding consideration of a product manufactured by another company. Describe how the particular brand name, product, or feature is essential to the Government's requirements and why a "brand name or equal" purchase description cannot be used (see FAR 11.1014). Describe how market research indicates other similar products and products lacking the particular feature do not meet, or cannot be modified to meet, the agency's need.

Urgent request due to Immediate Dangers of a Broken Assembly

A broken vertical sheave assembly presents a significant and immediate threat to the safety of the crew, the vessel, and its cargo. The primary risks include:

- **Catastrophic Load Failure:** A compromised sheave can lead to the sudden and uncontrolled release of a load. This could result in severe injury or death to personnel, as well as significant damage to the ship's structure and any cargo being handled.
- **Whipping and Snapping Lines:** A damaged sheave can cause ropes and cables to chafe, fray, and ultimately snap. A parted line under tension will whip back and forth, creating a life-threatening hazard to anyone in the vicinity.
- **Equipment Damage:** The uncontrolled movement of lines due to a broken sheave can cause extensive damage to the associated machinery, such as winches and pulleys, leading to further operational failures and costly repairs.

1. Date on which the requirement was first identified:

09/25/2025

2. Required delivery date/period of performance:

12/10/2025 to 12/10/2025

3. Explanation of why delivery/commencement of services by the date mentioned above is required: Explain the impact to the mission if the date above is not met, and the circumstances or conditions that exist which validate the requirement as "urgent," estimated production lead time for the item, etc.

The failure of a vertical sheave assembly can severely hamper the ship's operational capabilities. Depending on the system it is a part of, a broken sheave could:

- **Hinder Mooring and Anchoring:** An inoperable sheave on a mooring winch can prevent the vessel from securely berthing or anchoring, creating a dangerous situation at port or in crowded waterways.
- **Disrupt Cargo Operations:** A broken crane sheave will halt all cargo handling activities, leading to significant delays and potential contractual penalties.
- **Impede Emergency Response:** The inability to launch lifeboats or other emergency equipment due to a faulty sheave assembly could have devastating consequences in a crisis.

Regulatory Compliance and Seaworthiness

International maritime regulations, such as the International Convention for the Safety of Life at Sea (SOLAS), mandate that all shipboard equipment must be maintained in working order. A broken vertical sheave assembly could be considered a deficiency that renders the vessel unseaworthy, potentially leading to detention by port state authorities and costly fines.

4. If appropriate, include any additional pertinent information:

Given the severe safety risks, the potential for catastrophic equipment failure, and the significant impact on the vessel's operational capabilities and regulatory compliance, the immediate replacement of the broken vertical sheave assembly is of the utmost urgency. Delaying this critical repair would constitute a serious and unacceptable risk to the vessel and its crew. Regular inspection and maintenance, including lubrication and checking for wear, are also crucial to prevent future failures. The possibility of substantial cost would be due to the expediting of the product and decreasing the 98-day lead time. The vertical sheave is a crucial part of the platform lift assembly and is needed for the platform lift to return to operability.

CERTIFICATIONS/APPROVALS:**TECHNICAL CERTIFICATION**

I certify that the facts and representations under my cognizance which are included in this Exception to Fair Opportunity and its supporting acquisition planning documents noted herein, are complete and accurate to the best of my knowledge and belief.


Technical Cognizance

I certify that the facts and representations under my cognizance which are included in this Exception to Fair Opportunity and its supporting acquisition planning documents

CONTRACTING OFFICER CERTIFICATION

I certify that this Exception to Fair Opportunity is accurate and complete to the best of my knowledge and belief. The Contracting Officer's signature below represents approval of this document.

Contracting Officer's Signature



document.

rov

Level Above the Contracting Officer

LEGAL SUFFICIENCY REVIEW

I have determined this Justification is legally sufficient.

Legal Sufficiency Review

CONTRACTING ACTIVITY COMPETITION ADVOCATE REVIEW

Contracting Activity Approval

HEAD OF CONTRACTING ACTIVITY APPROVAL

Upon the basis of the above justification, I hereby approve, as Head of Contracting Activity, the solicitation of the proposed procurement described herein using other than competition, pursuant to the authority of (Placeholder for US code citation)

HCA Approval