

AN/ALQ-161A Electronic Countermeasures System Parts

The 408th Supply Chain Management Squadron (SCMS) is seeking information regarding potential sources for the repair or replacement of 30 electronic modules integral to the AN/ALQ-161A Electronic Countermeasures System. This requirement stems from the recent loss of repair support from the incumbent vendor, which had provided services for these items since 2002.

The former vendor was not the Original Equipment Manufacturer (OEM) for these modules, which were originally designed and produced in the early 1980s. The proprietary manufacturing data and intellectual property reside with the original manufacturers. For many years, the vendor maintained a high repair success rate by subcontracting the repair of critical, hermetically sealed components to the OEMs and other specialized suppliers.

However, after 2019, these external suppliers ceased offering repair services, citing the obsolescence of required parts and the discontinuation of support for the aging technology. This directly impacted on the vendor's ability to service the modules, causing their repair success rate to fall from over 90% to 48%, with many items being declared Beyond Economical Repair (BER).

The vendor's ability to continue support was critically limited by the lack of manufacturing documentation and the widespread unavailability of necessary components, which prevented them from performing the repairs independently. Consequently, when the service contract came up for renewal, the vendor concluded that they could no longer provide a sustainable or effective repair solution and declined to bid. They suggested that the most viable long-term solution may be a complete redesign of the modules using modern, available components to ensure future support of the program.

NSN	AAC	P/N(s)	Noun	Notes	FY26	FY27	FY28	FY29	FY30
5996-01-173-0599	C	CM572502, 435420-3	Amplifier, Radio Frequency		0.61	0.6	0.6	0.6	0.6
5895-01-174-5740	V	A10049-1, 435515-1	IF Controller-A		0	0	0	0	0
5996-01-172-9392	V	XM572502, DXAS20146, 435682-2	Amplifier, Repeater, Radio Frequency		0	0	0	0	0
5996-01-196-0016	C	5D585501, SD588501, 435430-1 (Part Target) See note	Preamplifier/Filter	PDM does not return results when searching NSN, but searching PCCN spreadsheet (separate document) does show item associated with 435430-1 and NSN - 0016 with P/N SD585501 which does return results in PDM (IPB)	0.96	0.96	0.96	0.96	0.96
5996-01-179-1743	C	SD633401, 435740-1	Amplifier, Band 4/5		4.13	4.08	4.08	4.08	4.08
5996-01-217-7512	C	442351-1	Preamplifier/Filter Assembly		9.48	9.48	9.48	9.48	9.48
5996-01-277-3912	C	XM573503, DXAS20131, 435420-12	Amplifier, Radio Frequency		4.56	4.56	4.56	4.56	4.56
5895-01-338-0629	V	WJ-C35-1, 435515-1	IF Controller-A		2.28	2.28	2.28	2.28	2.28
5996-01-174-4849	C	445054-000, **Specification Control Drawing 435682-3 or 435682-4 per IPB	Repeater, Radio Frequency Amplifier		0	0	0	0	0
5996-01-173-0600	C	DXAS20129, XM573401, 435420-4	Amplifier, Radio Frequency		0	0	0	0	0
5996-01-175-4056	C	A10048, 435537-2	Sector Summer Assembly		0.48	0.48	0.48	0.48	0.48
5996-01-396-6990	C	CM572503, 435420-10	Amplifier, Radio Frequency		1.2	1.2	1.2	1.2	1.2
5895-01-175-9723	C	A10054, 435340-2	RF Amplifier/Detector Assembly, Band 4 and 5		0.48	0.48	0.48	0.48	0.48
5996-01-268-4645	C	439855-1	Electronics Components Assembly (contains Sector Summer)		2.52	2.52	2.52	2.52	2.52
5865-01-332-8578	C	WJ-C36-2, 435516-2	IF Controller-B		1.8	1.8	1.8	1.8	1.8
5895-01-174-5741	C	A10052, 435518-1	IF Controller-D		2.76	2.76	2.76	2.76	2.76
5996-01-178-0513	C	A10047, 435537-1	Sector Summer Assembly		0.6	0.6	0.6	0.6	0.6
5996-01-175-4057	C	SD631301, 435742-1	Amplifier, Post BD 4/5		3.96	3.96	3.96	3.96	3.96
5996-01-268-4644	C	439854-1	Electronics Components Assembly , Sector Summer Assembly		0.24	0.24	0.24	0.24	0.24
5996-01-268-5700	C	439258-1	Amplifier Assembly, Band 4/5		0	0	0	0	0
5996-01-252-4105	C	DXAS20123, 435365-1	Amplifier, Radio Frequency		0	0	0	0	0
5865-01-335-8345	C	WJ-C35-2, 435515-2	IF Controller-A		0.96	0.96	0.96	0.96	0.96
5996-01-396-6993	C	XM573402, 435420-11	Amplifier, Radio Frequency		3.6	3.6	3.6	3.6	3.6
5895-01-175-4231	C	A10056, A10074 **Specification Control Drawing 435340-3 or 435340-1 per IPB	RF Amplifier/Detector Assembly, Band 4 and 5		0	0	0	0	0
5865-01-332-8579	C	WJ-C36-3, 435516-3	IF Controller-B		0.24	0.24	0.24	0.24	0.24
5996-01-269-4143	C	443641-4	Amplifier Assembly, Radio Frequency		0	0	0	0	0
5865-01-335-8346	C	WJ-C35-3, 435515-3	IF Controller-A		2.04	2.04	2.04	2.04	2.04
5895-01-176-2221	C	A10051, 435517-1	IF Controller-C		1.44	1.44	1.44	1.44	1.44
5895-01-183-2051	C	A10050-1, 435516-1	IF Controller-B		2.04	2.04	2.04	2.04	2.04
5865-01-266-7006	C	A10050-2, 435516-2	IF Controller-B		0	0	0	0	0