

Appendix B

Quality Assurance Surveillance Plan (QASP)

This Quality Assurance Surveillance Plan (QASP) includes performance standards. The Government will use these standards to determine contractor performance and shall complete contractor performance to the Acceptable Quality Level (AQL). The COR will use this document to rate contractor. Rating will be either SAT or UNSAT. Any UNSAT rating will be explained in the notes block.

PWS Paragraph	Task	Performance Standard	Acceptable Quality Levels (AQL)	Surveillance Method / By Whom	Performance Rating Sat / Unsat
6.3.	The contractor shall clean all additional machines added to Appendix A.	The contractor shall coordinate arrival with COR and perform coolant cleaning successfully.	0 (zero) failures to respond to the agreed upon arrival date or perform successful cleaning.	100% Inspection – COR will review inspect.	
6.5	The contractor shall perform continual maintenance of machine coolant.	The contractor shall supply the COR with clean-out data sheet within 10 days of completion of maintenance.	2 (two) failure to supply data sheet within 10 days.	100% Inspection – COR will review inspect.	
6.6. – 6.8	The contractor shall track coolant performance (if Hocut 795 not utilized).	The contractor shall supply COR with coolant laboratory analysis within 10 days of completion of maintenance.	2 (two) failures to supply laboratory analysis within 10 days.	100% Inspection – COR will inspect.	
Notes: 6.2 Forklift operator must always have a spotter. 6.2.1 Per NNSY OSHE, forklift operation requires a spotter with a whistle while in transit.					

APPENDIX B
Deliverables Schedule

Deliverable	Frequency	Copies	Medium/Format	Submit To
6.5.3. Clean-Out Data Sheet (CDRL A001)	Within 10 calendar days after each machine maintenance	2	As specified/ Electronic	COR
6.7.4. Coolant Laboratory Analysis (CDRL A002)	Within 10 calendar days after each coolant sample	2	As specified/ Electronic	COR