

SOURCE PRE-QUALIFICATION REQUIREMENTS

RMSC C: The part requires engineering source approval by the design control activity in order to maintain the quality of the part. Existing unique engineering skills, and repair knowledge by the qualified source(s) require repair of the part by the approved source(s). The approved source(s) retain repair knowledge, or technical data that are not economically available to the government, and the data or knowledge is essential to maintaining the quality of the part. An alternate source must qualify in accordance with the design control activity's procedures, as approved by the cognizant government engineering activity, AFLCMC/WLSEAB (C-5 Galaxy Division).

SECTION A: ITEM IDENTIFICATION

Stock Number (NSN)	Part Number	Nomenclature
1680-01-164-0384	5903-105J (4C95003-105J)	Flap Asymmetry Brake
1680-01-525-8920	5903-105L (4C95003-105L)	Flap Asymmetry Brake

SECTION B: JUSTIFICATION FOR ESTABLISHING A QUALIFICATION REQUIREMENT

The C-5M Flap Asymmetry brake is used when an asymmetrical condition in the flap system is detected to stop the system to prevent asymmetrical aerodynamic loads and prevent further damage to the system. The two flap asymmetry brakes are capable of preventing the entire flap system from moving. These parts are critical to the emergency shutdown of the flap system on the C-5M aircraft.

C-5M Flap Asymmetry brake repair requires strict control of processes to ensure adherence to quality control and testing requirements. Special tooling is required for the repair capability and special equipment is required for testing the flap asymmetry brake once repaired, consistent repair processes are needed to ensure that the flap asymmetry brake is repaired and will be operable and reliable in the event of an asymmetrical condition in the flap system in flight.

Failure of the flap asymmetry brake would either cause the flaps to become inoperable without having an asymmetrical condition, or would allow the flaps to continue operating under an asymmetrical condition which increases the risk of severe damage to the system and unequal aerodynamic loading across the wings, especially in times of flight with high flap usage, like takeoff and landing.

SECTION C: QUALIFICATION REQUIREMENTS

Source approval information: Listed below are the minimum requirements necessary to become a qualified bidder on the equipment listed above. Prospective contractors should report in accordance with MIL-HDBK-831.

SOURCE PRE-QUALIFICATION REQUIREMENTS

- a. Potential bidders shall provide a summary of the company's capabilities, including a detailed facility layout, a list of the machinery, fixtures, tooling and test and inspection equipment.
- b. Potential bidders shall demonstrate the ability and have experience in repair of similar critical aircraft parts, which are currently in use on a large commercial or military transport aircraft. Potential bidders shall provide the following information on the similar items:
 1. Contract Number
 2. Procuring Agency
 3. Contract Value
 4. Number of assets shipped
 5. Drawings and pictures of similar assets from various angles with written explanation of why the parts are similar
 6. Testing requirements
 7. Testing capabilities and demonstrate passing results with repaired items
- c. Potential bidders shall provide a detailed quality plan implementing ISO 9001 (or equivalent). Evidence of independent, 3rd party certification that the quality program satisfies ISO 9001 requirements may be submitted in lieu of the actual quality plan.
- d. Potential bidders shall provide a detailed overhaul process plan within the context of USAF overhaul manual 16C1-4-18-3 describing repair, inspection and testing procedures and shall provide for:
 1. Traceability of batch/lot for repaired material and the certifications that said material meets all heat treatment, composition, and finish requirements as stated on the drawing
 2. Identification of material, plating, and painting sources. Sources for raw materials shall be documented for each type of material utilized in the repair. No material, plating or painting waivers will be granted.
 3. Identification of sources for required tooling identified in T.O. 16C1-4-18-3 Table 2-1 and Table 4-1
 4. Identification of any requested alternate tooling/test equipment for evaluation of suitability, to include specifications, drawings and/or specification sheets as applicable and written justification of why the tooling/test equipment meets or exceeds the capabilities of the tooling within the USAF overhaul manual.
 5. Identification of any process where the potential bidder wishes to deviate from the USAF overhaul manual with a detailed, written justification detailing why the alternate process is equivalent or superior to those within the USAF overhaul manual.
 6. Identification of sources and qualifications for potential outsourced processes
- e. Potential bidders shall perform a minimum of 80% of the repair workload in-house.

SOURCE PRE-QUALIFICATION REQUIREMENTS

- h. Once qualified, bidders shall be subject to first article testing if they have not previously repaired or manufactured this item within the last five years. If first article testing is failed, pre-qualification may be revoked
- i. This qualification process shall be waived for companies who have already passed pre-qualification. The following companies are currently qualified to repair, test, and manufacture:

Thomas Instrument, Incorporated (CAGE 5H860)

- j. The Air Force may not qualify potential bidders who have had quality problems when delivering similar or identical items to the government. Potential bidders who have produced similar items for the commercial market shall also be considered for qualification and shall provide commercial brochures and at least five (5) references with phone numbers.

SECTION D: ESTIMATE OF THE TEST AND EVALUATION COSTS

Not applicable. All costs related to pre-qualification shall be paid by the applicant.

SECTION E: GOVERNMENT CONTRACT

The Government Point of Contact for the technical requirements specified for qualification is Samuel Stahl, AFLCMC/WLSEA, 235 Byron Street Suite 19A, Robins AFB, GA 31098.

SECTION F: SIGNATURE BLOCK

AFLCMC/WLS C-5 Mechanical Systems Engineer

STAHL.SAMUE
L.J.1635639187

Digitally signed by
STAHL.SAMUEL.J.1635639187
Date: 2026.03.13 09:39:38 -04'00'

AFLCMC/WLS C-5 Mechanical Systems Supervisor

BERMUDEZ.ANTO
NIO.M.1017645087

Digitally signed by
BERMUDEZ.ANTONIO.M.10176
45087
Date: 2026.03.16 10:30:55 -04'00'