

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LPD-22	USS SAN DIEGO		38DX223334		A01

TITLE:

2B MPDE Overspeed Governor ASSY; overhaul

JOB SPECIFICATION

Anticipated Award Date: <i>04/16/2026</i>	Production Completion Date: <i>05/27/2026</i>	PREPARING ACTIVITY:	
POP Start Date: <i>04/17/2026</i>	POP End Date: <i>09/30/2026</i>	SASEBO	
PREPARED BY: E. IWAMOTO	CODE M IW	DATE 4/7/2026	
APPROVED BY: S. MURAKAMI <i>SM</i>	CODE S225		
CONCURRED BY: N. SASHI <i>AS</i>	CODE S232		
ASSIST PLANNER'S NAME:	CODE		
ASSIST PLANNER'S NAME:	CODE		
ASSIST PLANNER'S NAME:	CODE		

CRITICAL SYSTEM

ZARATE, M
March 2026 EXCM

DESCRIPTION:

JSN(S): EM02-L105

CASREP #

S/F CONTACT: JACOB J. / CHENG

CWP #

CCNS #

Approved by S300/S900

Date: *09 APR 2026*

AVL: 6C1

C.M. LOUSKY

LWC:

Work Completed

S/Force: Rate: Date:

Ship Supt: Date:

SRF CONTROL NO.: 1301355680

WORK CERTIFICATION SIGNATURES

COMPLETION OF WORK REVIEW:	BADGE NO.:	SHOP/CODE:	PHONE:	DATE:
----------------------------	------------	------------	--------	-------

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN: 38DX223334	Rev:	Key Op: A01
LPD-22	USS SAN DIEGO				

TITLE:

2B MPDE Overspeed Governor ASSY; overhaul

1. SCOPE:

1.1 Title: 2B MPDE Overspeed Governor ASSY; overhaul

1.2 Location of Work:

1.2.1 Main Machinery Room No.2 (7-110-0-E)

1.3 Identification:

1.3.1 Quantity (One EA), 2B Main Propulsion Diesel Engine (MPDE) located in 1.2.1, MFR: Fairbanks Morse Defense, MFR ID: PC2.5V STC LL1, Speed: 520RPM, Rotation: CCW (Viewed from Flywheel), Serial Number: P04-939867LL1, APL: 66A060004V

1.3.1.1 Quantity (One AY), Overspeed Governor Assembly (ASSY) of 2B MPDE, Part No. P12619618, Figure 7-104 of 2.3

2. REFERENCES:

2.1 Standard Items (FY26)

2.2 S9233-DL-HBK-020 Volume 2, Main Propulsion Diesel Engine, Colt Pielstick Model Number PC 2.5V STC, LPD 17 Class Ships; Standardized Maintenance Procedures Handbook Appendices

2.3 S9233-DL-MMM-020 Volume 2 Rev 7, Main Propulsion Diesel Engine Model 16PC2.5V STC

2.4 S9086-HB-STM-010/CH-233 Rev 6, Diesel Engines

3. REQUIREMENTS:

3.1 Accomplish the requirements of 099-906YO of 2.1 for 2B MPDE listed in 1.3.1 as critical system (LPD17 Ship Class MPDE).

3.1.1 Accomplish the requirements of 009-009 of 2.1 for repair/overhaul of each overspeed governor ASSY listed in 1.3.1.1.

3.2 Accomplish the requirements of Appendix L except Paragraphs 1.4.2, 1.4.3, 1.4.5, 1.5.1, 1.5.4 through 1.5.7, 1.7.1 through 1.7.6, 1.7.9, 1.7.10, and 1.8.3 through 1.8.6 of 2.2 for overhaul of each overspeed governor ASSY listed in 1.3.1.1, using Appendix L Paragraphs 1.4.2 and 1.7.9 of 2.2 for guidance. Each (G) Government check point must be witnessed by S280.

3.2.1 Remove each existing and install each new component in place of those identified to be missing or defective.

3.2.2 Verify each record listing result of "EXAMINATION, TEST, AND REPAIR ACTION RECORD" in Appendix L Paragraph 1.10 of 2.2 has been completed

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN: 38DX223334	Rev:	Key Op: A01
LPD-22	USS SAN DIEGO				

TITLE:

2B MPDE Overspeed Governor ASSY; overhaul

and met acceptance criteria. Fill "not applicable" into the record where outside of this work boundary.

(V) "REPORT"

3.2.2.1 Submit one legible copy of the condition report listing results of the requirement of 3.2.2 to SUPERVISOR.

3.3 Accomplish the requirements of 009-032 of 2.1 for each new and disturbed surface.

(V) (G) "OPERATIONAL TEST"

3.4 Accomplish an operational test of each 2B MPDE listed in 1.3.1 to verify correct operation of each overspeed governor ASSY listed in 1.3.1.1 until S280 verifies correct operation at pier side. **-S280**

3.4.1 Accomplish the requirements of Appendix L Paragraph 1.8.4 of 2.2 for dynamic overspeed trip test of the overspeed governor ASSY. Each (G) Government check point must be witnessed by S280.

3.4.1.1 Verify each record listing result of "EXAMINATION, TEST, AND REPAIR ACTION RECORD" in Appendix L Paragraph 1.10 of 2.2 has been completed and met acceptance criteria. Fill "not applicable" into the record where outside of this work boundary.

(V) "REPORT"

3.4.1.2 Submit one legible copy of the condition report listing results of the requirement of 3.4.1.1 to SUPERVISOR.

3.4.2 Verify each disturbed joint free of leaks. Slight weeping of lube oil at each gasket and seal is acceptable in accordance with Paragraph 233-13.13.3.1 of 2.4. Other joints: None.

4. NOTES:

4.1 Initial Condition - During inspection, FTA discovered that the 2B MPDE overspeed has failed and requires overhaul. FTA previously discovered that the spring was allowing the counterweight to trip the governor on overspeed. FTA adjusted the spring, but the issue was not resolved.

4.2 SRF Tool Room will issue each torque wrench and dial indicator when required.

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LPD-22	USS SAN DIEGO		38DX223334		A01

TITLE:

2B MPDE Overspeed Governor ASSY; overhaul

5. GOVERNMENT FURNISHED MATERIAL (GFM) :

5.1 See below MATERIAL LIST.

Each symbol in the row, M/C, below means:

M: Mandatory Material, C: Contingency Material

MATERIAL LIST

MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
001		2.3	M	PIN, PN: 91113460, FIG 7-104-2	9B 5315 011802277	N	6097B061	2/EA	3.2
002		2.3	M	PIN, TAPERED, PLAIN, PN: 91106841N, FIG 7-104-3	9B 5315 011802272	N	6097B062	4/EA	3.2
003		2.3	M	PIN, STRAIGHT, HEADLE, PN: 0N22505.020.6, FIG 7-104-5	9B 5315 011922101	N	6097B064	1/EA	3.2
004		2.3	M	BUSHING, SLEEVE, PN: P12609495, FIG 7-104-7	9B 3120 011843732	N	6097B066	1/EA	3.2
005		2.3	C	KEY, WOODRUFF, PN: 93008966N, FIG 7-104-10	9B 5315 011823051	N	6097B067	1/EA	3.2
006		2.3	M	GASKET, PN: P402636N, FIG 7-104-19	9B 5330 011820567	N	6097B068	2/EA	3.2
007		2.3	M	JOINT, PN: P403411N, FIG 7-104-20	9B 2815 011811796	N	6097B070	1/EA	3.2
008		2.3	M	O-RING, PN: 0N65210.26.63, FIG 7-104-22	9B 5331 005992934	N	6097B071	1/EA	3.2
009		2.3	C	SETSCREW, PN: P12614914, FIG 7-104-24	9B 5305 011824153	N	6097B073	2/EA	3.2
010		2.3	M	SPRING, HELICAL, COMP, PN: P12613734, FIG 7-104-26	9B 5360 011798743	N	6097B074	2/EA	3.2
011		2.3	C	NUT, PLAIN, HEXAGON, PN: P12614913, FIG 7-104-29	9B 5310 011781483	N	6097B075	2/EA	3.2
012		2.3	M	GASKET, PN: 93009020N, FIG 7-104-31	9B 5330 011831307	N	6097B076	1/EA	3.2
013		2.3	M	PIN, STRAIGHT, HEADLE, PN: 0N22503.026.6, FIG 7-104-34	9B 5315 011922100	N	6097B078	2/EA	3.2
014		2.3	M	LOCKPLATE, PN: 0N14010.02.10, FIG 7-104-35	9B 5340 011795100	N	6097B079	4/EA	3.2
015		2.3	M	WASHER, LOCK, PN: 81309762N, FIG 7-104-36	9B 5310 005845272	N	6097B080	1/HD	3.2
016		2.3	C	PIN, STRAIGHT, HEADLE, PN: 91122712N, FIG 7-104-58	9B 5315 011823054	N	6097B082	4/EA	3.2
017		2.3	M	BEARING, BALL, THRUST 15 X 28 X 9 PN: P12601037N, FIG 7-104-113	9B 5310 SA2401195	N	6097CS10	1/EA	3.2
018		2.3	C	PIN, STRAIGHT, HEADLE, PN: 91113945N, FIG 7-104-402	9B 5315 011817372	N	6097B084	2/EA	3.2
019		2.2	M	CLOTH, C, LINT FREE, 10 LB/BX	9Q 7920 000449281	N	6097B060	1/BX	3.2
020		2.2	M	SEALING COMPOUND, LOCTITE 242 OR EQ MIL-S-46163 TY II, 250 ML/BT	9B 8030 010251692	Y	6097B803	1/BT	3.2
021		2.2	M	GREASE, EXTREME PRES, MOLYKOTE G-N, 500 GM/CO	9B 9150 010379016	Y	6097B802	1/CO	3.2