

PRE-SOLICITATION NOTICE - N6264926RA036

Naval Supply Systems Command (NAVSUP) Fleet Logistics Center Yokosuka (FLCY)

Action: Pre-Solicitation Notice

Agency: Department of the Navy

DoDAAC: NAVSUP FLCY (N62649)

Location: Yokosuka, JAPAN

Classification Code: J999 – Non-Nuclear Ship Repair (West)

NAICS Code: 336611 – Ship Building and Repairing

Subject: Ship repair and Maintenance for Forward Deployed Naval Forces (FDNF) - USS RAFAEL PERALTA (DDG-115) FY26 Surface Incremental Availability (SIA) BUNDLE#1

Solicitation Number: N6264926RA036

Description:

This is a pre-solicitation notice for an upcoming requirement by Ship Repair Facility and Japan Regional Maintenance Center (SRF-JRMC) and Naval Supply Systems Command (NAVSUP) Fleet Logistics Center Yokosuka (FLCY) for Ship Repair services. The Government intends to issue a solicitation for a Firm-Fixed-Price (FFP) contract for the repair and continuous maintenance of United States Navy (USN) Surface Ship USS RAFAEL PERALTA (DDG-115). The anticipated scope of work includes, but not limited to the following work items known as Task Group Instructions (TGI):

TGI	Description
38K6112001-A01	Scaffolding for Ship Repair Facility and Japan Regional Maintenance Center (SRF-JRMC) Work; install and remove
38K6112301-A01	FWD Uptake Space; repair
38K6112302-A01	Bilge in 5-300-01-E; inspect, repair, and preserve
38K6112303-A01	Incomplete Weld of Bimetallic Transition Joint for Engine Removal Rail in 02-174-1-Q; repair
38K6112304-A01	1A Gas Turbine Module (GTM) Moisture Separator Bonding Strap; install
38K6112305-A01	Watertight Hatch 02-324-3; overhaul
38K6112306-A01	Watertight Door 03-178-1; replace
38K6112316-A01	No. 3 Ship's Service Gas Turbine Generator (SSGTG) Intake and Exhaust Trunk; preserve
38K6112317-A01	Hook Assembly for Louver Door of No. 3 Ship Service Gas Turbine Generator (SSGTG) Intake; install
38K6112318-A01	Placard to FWD and AFT Gas Turbine Module (GTM) and Ship Service Gas Turbine Generator (SSGTG) Intake Moisture Separator/Blow in Door (BID) Flame; install
38K6112320-A01	Packing Assembly of Stuffing Tube for Cable Assembly, Fuel Tank Level Indicator System for Tank Group-5; replace
38K6112321-A01	Inspection, Repair, and Preservation of IRS Eductor Secondary Air Inlet Trunk; accomplish
38K6112325-A01	Replacement of Watertight Door 01-240-1 and Repair of Defect on Collar Plate, Stuffing Tube, and 02 Level Deck Plating in 01-240-1-A; accomplish

38K6113601-A01	Preservation of Vent Hood and Replacement of Weather Screen in 01 Level Weather Frame 240; accomplish
38K6113602-A01	Bulkhead Plating and Antenna 2-4 Platform, between 01 Level and 05 Level Weather, Frames between 202 and 247, Port and Starboard (Stbd); preserve
38K6113701-A01	Replacement of Nonskid System, Preservation of Stanchion, and Installation of Equipment on 02 Level Weather; accomplish
38K6113702-A01	Forward Exhaust Stack and Sloping Transverse Bulkhead in 03 Level Weather, Frames between 174 and 178, Port and Starboard (Stbd); preserve
38K6113801-A01	Replacement of Peel and Stick Nonskid System and Inspection, Repair, and Preservation of 03 Level Weather, Deck Plating; accomplish
38K6144104-A01	Bond Strap of AM-7641A/U Amplifier Filter Unit No. One for AS-4679/U Antenna 3-10B; replace
38K6145601-A01	Scaffolding for Ship Repair Facility and Japan Regional Maintenance Center (SRF-JRMC) Work; install and remove
38K6151101-A01	Scaffolding for Ship Repair Facility and Japan Regional Maintenance Center (SRF-JRMC) Work; install and remove
38K6152101-A02	Scaffolding for Ship Repair Facility and Japan Regional Maintenance Center (SRF-JRMC) Work; install and remove
38K6154101-A01	Panel of Blast Shield and Bonding Assembly of Kingpost for Fueling At Sea (FAS) Station No. 7 in 02 Level Weather, Starboard (Stbd); replace
38K6154101-T01	Tightness & Operational Test for Fuel Transfer System
38K6154101-T02	Tightness & Operational Test for JP-5 System
38K6154103-A02	Fuel Tank Group-5 and Group-6; dewater
38K6158301-A01	Rope Staple on Life Raft Cradle in 02 Level Weather, Frames between 166 and 169, Port; replace
38K6164401-A01	Transverse Bulkhead Plate Frame 338 in 3-338-10-L; repair
38K6165401-A01	Shore Power Cover on 01 Weather, Frame 240, Port and Starboard; repair
38K6169901-A01	Bonding Strap Assembly for Inclined Ladder in 02 and 03 Level Weather, Port; replace
38K6171101-A01	Nonskid System on Train Platform and Mounting Plate of AFT Close In Weapon System (CIWS); replace
38K6186301-A01	KTR Service Work for Temporary Utility Service; provide

The work will be performed onboard Commander, Fleet Activities Yokosuka (CFAY), located in Yokosuka Naval Base, Japan. The anticipated Period of Performance (POP) is from 18 Jul 2026 to 20 Sep 2026.

Projected Solicitation:

The Government anticipates issuing a Request for Proposal (RFP) on or about 02 Apr 2026. The solicitation and any subsequent amendments will be made available through the System for Award Management (SAM.gov) website.

Competition and Eligibility:

The solicitation upon issuance is intended only for sources duly authorized to operate and do business in Japan, as prescribed by DFARS 252.225-7042. Additionally, to ensure the U.S. Navy receives satisfactory repair effort to Navy ships, boats and crafts, the solicitation will require the offeror to possess a current and active USN Master Ship Repair Agreement (MSRA) or Agreement for Boat Repair (ABR) issued by the U.S. Navy or NAVSUP FLCY.

Non MSRA/ABR holders may request an application for an MSRA or an ABR certification by requesting an application package from: ficy_msra_abr_group@us.navy.mil. Please note that the MSRA/ABR Certification process may require a year to complete.

Set-asides:

No socio-economic set-asides will be used for this acquisition.

Point of Contact (POC):

- Ai Gillard, ai.gillard.ln@us.navy.mil (Contracting Officer)
- Miwa Takahashi, miwa.takahashi2.ln@us.navy.mil (Contract Specialist)

Additional Information:

This notice is NOT a request for proposals. The solicitation, when issued, will be available electronically via the System for Award Management (SAM) website at <https://sam.gov/>. All responsible and eligible sources may submit a quotation, bid, or proposal, as appropriate, in response to the subsequent solicitation, which will be considered by the agency. It is the responsibility of interested parties to monitor this site for the release of the solicitation and any subsequent amendments.

All questions regarding this pre-solicitation notice should be submitted in writing to the POC listed above.