

TASK GROUP INSTRUCTION
AIM REV 20.11.4.0 (OCTOBER 2020)

TGI NO.:	COMPONENT NAME: MAIN WEA STRCT	TYPE: AY	PHASE: A	REPEAT: 0	CHANGE: 1
SHIP/HULL NO.: DDG-76	SHIP/HULL NAME: USS HIGGINS	SYSTEM:		PROJ/WO NO: KB3	CASREP CAT:
CU PHASE TITLE: F/O - REPAIR STRUCTURAL MEMBER IN MAIN DECK WEATHER					
PREPARING ACTIVITY:					
PREPARED BY: KEIGO ABE		CODE 231A	PHONE 315-243-3161	DATE 18-DEC-2025	
APPROVED BY: YUUJI NAKAMURA		CODE 231A	PHONE 315-243-6041	DATE 18-DEC-2025	
CONCURRED BY:		CODE	PHONE	DATE	
CONCURRED BY:		CODE	PHONE	DATE	
CONCURRED BY:		CODE	PHONE	DATE	
CONCURRED BY:		CODE	PHONE	DATE	
REASON FOR WORK/NEED FOR CHANGE: Contractor work start/completion date of 1.6 and 1.7 were missing.					
CHANGE INSTRUCTIONS: CH-1: Add contractor work start/completion date of 1.6 and 1.7.					
SPECIAL REQUIREMENTS: HOT WORK IN MAGAZINE AND ADJACENT SPACES IAW S6740-AA-SAF-010 AND NAVSEA OP 4 TGI CONCURRENCE BY CODE 294 MR. A. Kumagaya, DATED 12/12/2025					

WORK CERTIFICATION SIGNATURES

COMPLETION OF WORK REVIEW:		BADGE NO.:	SHOP/CODE:	PHONE:	DATE:
ACCEPTANCE OF COMPLETED WORK					
PHYSICAL INSPECTION REQUIRED: ☐ YES ☒ NO	PHYSICAL INSPECTION COMPLETED:	BADGE NO.:	SHOP/CODE:	PHONE:	DATE:
RECORDS REVIEW:		BADGE NO.:	SHOP/CODE:	PHONE:	DATE:



LIST OF EFFECTIVE PAGES									
SHT NO.	CHG NO.	SHT NO.	CHG NO.	SHT NO.	CHG NO.	SHT NO.	CHG NO.	SHT NO.	CHG NO.
1-4									
J-1									
M-1									

1. SCOPE/PURPOSE

1.1 Title: Structural Member in Main Deck Weather; repair

1.2 Location of Work:

1.2.1 Main Deck Weather, Frames between 370 and 379, Starboard (Stbd)

1.2.2 Supply Department Storeroom No. 2 (2-370-3-A)

1.2.3 B-Size Module 61 Cell Vertical Launching System (3-338-0-M)

1.3 Identification:

1.3.1 Quantity (One Lot), Structural Member in Main Deck Weather, Frames between 372 and 378, Stbd

JCN: ES01-NALT

1.3.1.1 Quantity (One Lot), Stringer 21 (S) on Fashion Plate (S), Frames between 370 and 378, Stbd

Remarks: See Plan 4-A of 2.3 for material and detail

1.3.1.2 Quantity (One Lot), Tripping Bracket of Stringer 21 (S) and Vertical Stiffener on Fashion Plate (S), Frame 378, Frames between 375 and 377, Stbd

Remarks: See Detail 4-B of 2.3 for material and detail

1.3.1.3 Quantity (One Lot), Stringer 22 (S) on Fashion Plate (S), Frames between 373 and 379, Stbd

Remarks: See Plan 5-A of 2.3 for material and detail

1.3.1.4 Quantity (One Lot), Vertical Stiffener on Fashion Plate (S), Frame 374, Stbd

Remarks: See Plan 5-B of 2.3 for material and detail

1.3.2 Quantity (One EA), Brast Sheild on Watertight Transverse Bulkhead in Main Deck Weather, Frame 370, Stbd

Remarks: See Detail 152A-A of 2.4 for material and detail

1.3.3 Quantity (4 SF), Stringer 21 (S) on Fashion Plate (S), Frames between 370 and 378, Stbd

Remarks: The area where rubber tile is installed.

1.3.4 Quantity (2 SF), Stringer 22 (S) on Fashion Plate (S), Frames between 373 and 379, Stbd

Remarks: The area where rubber tile is installed.

1.3.5 Quantity (8 SF), Vertical Stiffener on Fashion Plate (S), Frame 374, Stbd

2 TGI NO.:

SHIP:

MAIN WEA STRCT	AY	A	0
DDG-76	CHG/VER:	1/0	

Remarks: The area where rubber tile is installed.

1.3.6 Quantity (6 SF), Vertical Stiffener on Fashion Plate (S), Frame 378, Stbd

Remarks: The area where rubber tile is installed.

1.3.7 Quantity (14 SF), Fashion Plate (S), Frames between 372 and 379, Stbd

Remarks: The area where rubber tile is installed.

1.3.8 Quantity (6 SF), Watertight Transverse Bulkhead, Frame 370, Stbd

Remarks: The area where rubber tile is installed.

1.4 Security Classification:

1.4.1 Spaces – 1.2.3

1.5 Initial Condition:

1.5.1 Contact Code 294 VLS SME prior to conducting the work procedure out of sequence in this TGI.

1.5.2 Potential Asbestos Hazard

1.6 Contractor work start date: 29/JUN/2026

1.7 Contractor work completion date: 8/DEC/2026

2. REFERENCES:

REF. NO.	DOCUMENT /DRAWING NUMBER	DOCUMENT/DRAWING TITLE	REV	CHG NO.	COPY REQ'D (Y/N)	SOURCE DOC (Y/N)	PARA	SEC	PG	CHP
1	NSI FY-26	NAVSEA Standard Items	-	1	N					
2	LI FY-26	Local Standard Items	-	ORG	N					
3	PDD 100-ELM-260041	RPR PLAN OF CORRODED STIFFENERS ON STBD FASHION PL (MN DK, FR 372-378)	-		Y				AL L	
4	DWG 611-6221132	FABRICATION OF MISC DECK FITTING - ZONE 3	AK		Y				15 2A	
5	DWG 600-6219304	HULL OUTFIT INSTL DESIGN ZONE 3350 MN DK FR 370 - 410 (WEA)	AD		Y				5C	
6	DWG 100-6218940	UNIT STRL ARR DWG ASSY UNIT 3250	Y		Y				5A -10	

3. APPENDICES:

- 3.1. Appendix "J" TGI Job Summary Information Sheet
- 3.2. Appendix "M" TGI Material List
- 3.3. Appendix "D" Deficiency Form

4. GENERAL REQUIREMENTS:

4.1 Not Applicable.

3 TGI NO.:

SHIP:

MAIN WEA STRCT	AY	A	0
DDG-76	CHG/VER:	1/0	

5. **PROCEDURE:**

5.1 Remove existing, fabricate, and install new each structural member and blast shield listed in 1.3.1 and 1.3.2 in accordance with 2.3 through 2.5, using 2.6 for guidance.

5.1.1 Accomplish the requirements of 009-012 of 2.1, including Table 2, Column(s) A, Lines One through 7.

5.2 Accomplish the requirements of 009-032 of 2.1, including Table 2, Line(s) 46, for each area listed in 1.3.3 through 1.3.8.

5.3 Accomplish the requirements of 009-032 of 2.1 for each new and disturbed surface.

5.4 Notes:

5.4.1 Planner: Code 231A K. Abe, 243-3161

5.4.2 This TGI is in response to CCIMS report No. CCIMS-G1N6-DDG76-067-25 from TGI No. 38KBA11021103.

5.4.3 This TGI clears DFS DDG-76-1023-2025 in its entirety.

5.4.4 Work Integration Manager (WIM): Code 333 T. Yaginuma, 080-6522-9560

5.4.5 Removal and installation of rubber tile on stringer, vertical stiffener, fashion plate, and watertight transverse bulkhead in main deck weather frames between 370 and 379 will be covered by TGI No(s). 38KB313103U01 and 38KB313103R01 (SRF-JRMC TGI).

5.4.6 Prior to commencement of the work, verification by Code 294 is required for work control and oversight relating to above, inside, or below the VLS launcher.

5.4.7 JCNs ES01-NALT, ES01-NALU, and ES01-NALW are related to this TGI.

5.5 Government Furnished Material (GFM):

5.5.1 SRF-JRMC will provide GFM listed in Appendix "M".

5.6 SRF-JRMC will provide the following service work: (TGI No. 38KB313103S02).

5.6.1 [C740] Crane and crane rigging service.

5.6.2 [X99E] Utility service, electrical.

5.6.3 [X99M] Utilities service, including low pressure air supply, water supply, and steam supply.

5.6.4 [C106.1] Safety inspection for SRF-JRMC employees.

5.6.5 [C106.2] Gas free inspection for SRF-JRMC employees.

5.6.6 [C133] QA Inspection for (G) symbol(s).

5.6.7 [C294] Work scope review and verification for VLS relating work prior to commencement of the work.

MAIN WEA STRCT	AY	A	0
DDG-76	CHG/VER:	1/0	

APPENDIX "J"

TGI JOB SUMMARY INFORMATION SHEET

SYSTEM:	PLANT NO.:	COMPONENT NAME: MAIN WEA STRCT	TYPE: AY	PHASE: A	REPEAT: 0	CU PH VERSION: 0	CASREP CAT:
CU PHASE TITLE: F/O - REPAIR STRUCTURAL MEMBER IN MAIN DECK WEATHER							
PRIMARY COMPONENT:							
COMPONENT UNIT LIST (FOR ASSEMBLIES): MAIN DECK EXT STBD MS							
ATTACHMENT LIST:							
ZONE MANAGER: YAGINUMA ,TAKEHIDE		ZONE:	COMPARTMENT:	LEVEL:	FRAME:	SIDE:	
JO: 38KB313103	KO: A01	TOTAL MAN HRS:	TOTAL MAT'L COST	TOTAL DURATION:	PLANNING ACCEPTANCE:		
CU PHASE DESCRIPTION: The purpose of this TGI is to repair structural member in main deck weather. Location of Work: Main Deck Weather, Frames between 370 and 379, (Stbd) Supply Department Storeroom No. 2 (2-370-3-A) B-Size Module 61 Cell Vertical Launching System (3-338-0-M)							

MAIN WEA STRCT	AY	A	0
DDG-76	CHG/VER:	1/0	

APPENDIX "M"
TGI MATERIAL LIST

SYSTEM:	PLANT NO.:	COMPONENT NAME:	TYPE:	PHASE:	REPEAT:	CU PH VERSION:	CASREP CAT:
		MAIN WEA STRCT	AY	A	0	0	

CU PHASE TITLE:
F/O - REPAIR STRUCTURAL MEMBER IN MAIN DECK WEATHER

MATERIAL REFERENCES			
REF NO.	DOCUMENT/DRAWING NUMBER	DOCUMENT/DRAWING TITLE	REV

JOB ORDER:	KEY OP:
38KB313103	A01

MATERIAL LIST												
ITEM NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	GENERIC MATL TYPE	LVL	QA	HAZ MAT	DOC NO.	QTY REQD/ UNIT	QTY USED/ UNIT
001			M	PLATE,ME, ORDER FOR KTR ORIGINATOR C231A K. ABE 243-3161	9B 9515 002375333		NA	4	N	53535127	7/SF	
002			M	PLATE,ME, ORDER FOR KTR ORIGINATOR C231A K. ABE 243-3161	9B 9515 002243086		NA	4	N	53535129	14/SF	

NOTES:

M-1	TGI NO.:	MAIN WEA STRCT	AY	A	0
	SHIP:	DDG-76	CHG/VER:	1/0	

☐ NUCLEAR☐ NON-NUCLEAR

APPENDIX "D"

DEFICIENCY FORM

1. SHIP/HULL NO.:	2a. DL or DR No. (Circle One)	2b. REVISION:	3a. COMPONENT NAME:	3b. TYPE:	3c. PHASE:	3d. REPEAT:
DDG-76			MAIN WEA STRCT	AY	A	0
4a. ICN: 38KB313103		4b. KEY OP: A01	5. LOC SPACE/LVL:	FRAME:	P/S/C:	6. CAUSED BY:

7. DESCRIPTION:

8. ORIGINATOR:	NAME:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.:
----------------	-------	--------	------------	-------	------------

9. CORRECTIVE ACTION:

10. EVALUATOR:	NAME:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.:
----------------	-------	--------	------------	-------	------------

FOR NON-NUCLEAR USE ONLY

11. RFD/RFW REQ'D ☐	LAR REQ'D ☐	SRD/PLAN REV REQ'D ☐
ILS MOD REQ'D ☐	DWG NO.: _____ S/A NO.: _____	

12. ISOLATION SATISFACTORY:	SIGN:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.:
--------------------------------	-------	--------	------------	-------	------------

13. SUBSAFE OQE RECORD?	SIGN:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.
YES ☐ NO ☐					

14. CORRECTIVE ACTION COMPLETE:	SIGN:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.

15. INSPECTION REQ'D?	INSPECTION COMPLETE/SIGN:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.
:YES ☐ NO ☐					

16. RECORDS REVIEW COMPLETE (DR ONLY)	SIGN:	BADGE:	SHOP/CODE:	DATE:	PHONE NO.

DL's ISSUED
(DR ONLY)

☐ NON-NUCLEAR

1. SHIP/HULL NO.:	2a. DL or DR No. (Circle One)	2b. REVISION:	3a. COMPONENT NAME:	3b. TYPE:	3c. PHASE:	3d. REPEAT:
DDG-76			MAIN WEA STRCT	AY	A	0

[illegible]