

Q&A

Question:

- Can you please provide Material of part, the RC Hardness, marked up photos of areas requiring masking or full print showing dimensions and surfaces in which masking is to be applied?

Answer:

- The material is HY-80 per spec NAVSEA TM T9074-BD-GIB-010/0300 (which superseded MIL-S-16216). The Brinell hardness is 200-260 HB.
- The parts shall be plated everywhere except within the spline & keyway. See attached for what should NOT be plated.
- The attached drawing is posted in the SAM notice and labeled as what not to plate