

Inspection Summary

Customer Information

Name Veterans Medical Center OKC

Building Information

Name Oklahoma VA Health Care System

Address 921 NE 13th St, Oklahoma City, OK 73104

Contact Information

Name Nate Eastham

Role Electrical Mechanical Supervisor

E-Mail nathaniel.eastham@va.gov

Phone 4056256464

Account Information

Service Provider Johnson Controls North America

Office Address 2835 S Utah OKC OK 73108

Office Phone 405-200-8476

Office License 442

Inspector Name Robert L Starbuck

Inspector License A14094

Inspection Information

Start Date 02/16/2026

Date 02/17/2026

Inspection Type Joint Commission

Work Order# 60694682

Timezone GMT-06:00

Inspection Summary

The following Tests and Inspections have been covered in this inspection

[EP 2-3 - Duct, Heat, Flame, Optical, Smoke Detectors, Pull Stations](#)

[EP 2-4 - Audible and Visual Notification Appliances, and Door Releasing Devices](#)

[EP 2-5 - Supervising Station Fire Alarm Systems — Transmission Equipment](#)

[EP 2-19 - Air Handler Shut Down Annual](#)

[NFPA 72 - 2010](#)

General Inspection Notes

1. Annual fire alarm test and inspection.

Tested all notification devices with failures listed below.

Tested all initiating devices with failures listed below.

FACP has multiple troubles as listed.

Node 10 3rd floor # 01-A
Node 10 3rd floor # 01-B
Node 11 3rd floor # 01-B
Node 16 5th floor # 02EGND
Node 16 5th floor # 02-A
Node 17 6th floor # 01-B
Node 17 6th floor # 02-A
Node 19 7th floor # CC Phone
Node 7 BB-100 # 02EGND
Node 16 5th floor # 02-EGND
Node 7 BB-100 # 01EGND
Node 22 8th floor # 01EGND
Node 9 4th floor Area A smoke south
Node 4 BLDG 19 main power supply fault
Node 5 BB-100 smoke by 2nd floor 2118 North
Node 5 BB-100 smoke by 2nd floor 2118 South
Node 17 6th floor # 02-A
Node 16 5th floor # 02-A
Node 10 3rd floor # 03-A
Node 9 Main 4th floor # 1 Pull
Node 10 3rd floor # 01-A
Node 18 6th floor # 01-A
Node 11 3rd floor # 01-B
Node 17 6th floor # 01-B
Node 10 3rd floor # 01-B
Node 5 BB-100 above power supply
Node 9 Main 4th floor 6th floor audio relay
Node 5 BB-100 Basement NAC trigger
Node 5 BB-100 GF rm GA102 power supply
Node 9 Main 4th floor 5th floor NAC trigger
Node 9 Main 4th floor 6th floor NAC trigger
Node 5 BB-100 1st floor NAC trigger
Node 5 BB-100 2nd floor NAC trigger
Node 26 BB-100 LCD-SLP 1
Node 22 8th floor # 01-A

System is YELLOW tagged.

DEVICE DEFICIENCIES									
TEST TO PERFORM	LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	INSPECTOR / DATE	IMAGES
EP19	1st Floor	Building 21 Drug Cache Duct Control Relay	N1L1M012	AHU Fan Shutdown	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut down unit.									
EP19	2nd Floor	Building 21 2nd Floor Duct Control Relay	N1L1M013	AHU Fan Shutdown	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut down unit.									
EP19	3rd Floor	3rd Floor AHU-9 Supply Control Relay	N5L2M118	AHU Fan Shutdown	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: AHU FAILED TO SHUTDOWN WHEN DUCT SMOKE DETECTOR WAS TESTED									
EP19	Basement	Basement AHU in BA115 Shutdown	N5L1M083	AHU Fan Shutdown	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut down unit.									
EP19	Basement	Basement AHU in BF155 Shutdown	N5L1M084	AHU Fan Shutdown	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut down unit.									
EP3	1st Floor	Building 21 Drug Cache Duct Detector	N1L1S002	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Dis not shut unit down .									
EP3	2nd Floor	Building 21 2nd Flr Duct Detector	N1L1S003	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut unit down.									
EP3	2nd Floor	2nd Flr. Oncology AHU Return	N5L2S132	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Unit did not shut down.									
EP3	3rd Floor	3rd Flr AHU #7 Exhaust Duct Detector	N5L2S118	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut down unit.									
EP3	Basement	Basement AHU Supply in BA115	N5L1S103	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut unit down.									
EP3	Basement	Basement AHU Supply in BF155	N5L1S104	Duct Detector	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not shut unit down.									
EP3	Ground	STONEWALL/ PARK PLACE FEED TRAILER (south)	ZONE 3	Pull Station	FCI	MS-7ASF	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not report to main FACP.									

DEVICE DEFICIENCIES									
TEST TO PERFORM	LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	INSPECTOR / DATE	IMAGES
EP3	Ground	STONEWALL/ PARK PLACE FEED TRAILER (north)	ZONE 2	Pull Station	FCI	MS-7ASF	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not report to main FACP.									
EP3	Ground	STONEWALL/ PARK PLACE FEED TRAILER (above FACP)	ZONE 1	Smoke Detector	FCI	ASD-PL3-IV	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not report to main FACP.									
EP4	2nd Floor	BY 2B102n	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	2nd Floor	BY 2B121	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	2nd Floor	IN 2B102n	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	3rd Floor	BY 3A150	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	3rd Floor	BY 3A152	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	3rd Floor	BY 3A155	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	5th Floor	MICU RESIDENT 5F110	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	MICU/CICU LOUNGE 5F113	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	DIALYSIS SUITE 5F118 EAST	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	DIALYSIS SUITE 5F118 WEST	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	5th Floor	FAMILY ROOM 5F106A	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BLOOD GAS LAB 5F146	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	PULMONARY FUNCTION LAB 5F130	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	SPECIAL PROCEDURES 5F132	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXERCISE ROOM 5F131	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	TECH ROOM 5F126	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	LOUNGE 5F125	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM PATIENT SCREENING 5A102	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM PATIENT SCREENING 5A103	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A104	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A106	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A107	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	5th Floor	EXAM 5A108	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A110	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	OFFICE 5A111	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A113	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A114	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A116	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A115	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A117	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A118	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A119	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A120	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A120	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EXAM 5A121	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									

DEVICE DEFICIENCIES									
TEST TO PERFORM	LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	INSPECTOR / DATE	IMAGES
EP4	5th Floor	EXAM 5A122	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A123	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A124	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A129	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A127	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A128	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	NURSING OFFICE 5A130	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM PHARMACY 5A131	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	CONSULTATION OFFICE 5A133	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	CONSULTATION OFFICE 5A132	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A134	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A135	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A137	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									

DEVICE DEFICIENCIES									
TEST TO PERFORM	LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	INSPECTOR / DATE	IMAGES
EP4	5th Floor	EXAM 5A136	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	PATIENT SCREENING 5A138	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM 5A141	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	NURSE STATION 5A142	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	EXAM NURSE TRIAGE 5A144	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	STAFF PHYSICIAN 5A158	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	PHARMACY 5A173	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	MEDICAL SERVICE PROGRAM 5A164	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	WARD ADMINISTRATION 5A166	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	NURSING OFFICE 5A165	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	NURSING OFFICE 5A171	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	STAFF BREAK ROOM 5B107	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	5th Floor	WOMENS RESTROOM 5B105D1	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	MENS RESTROOM 5B105A1	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5A119	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5A134	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5A156	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5A171	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5B119	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5B125	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5B134	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5E107	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5E110	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F102	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F105	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									

DEVICE DEFICIENCIES									
TEST TO PERFORM	LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	INSPECTOR / DATE	IMAGES
EP4	5th Floor	BY 5F109h	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F109p	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F109u	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F114	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F117e	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F124	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F128	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F137	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F152	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY 5F153	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY P6 ELEVATOR	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY STAIRWELL 1	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									
EP4	5th Floor	BY STAIRWELL 10	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure,Visual Failure FAILURE REASON: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	5th Floor	BY STAIRWELL 2	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BY STAIRWELL 5	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BY STAIRWELL 7	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BY STAIRWELL 8	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BY STAIRWELL 9	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	EAST OF STAIRWELL 8	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5A139	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5A145	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5A180	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5B138	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5B139	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5E109	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5E110	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure,Visual Failure Failure Reason: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	5th Floor	IN 5F102	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure, Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5F104	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure, Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5F111	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure, Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	IN 5F112	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure, Visual Failure Failure Reason: No strobe.									
EP4	5th Floor	BY 5F142	—	Visible Notification Device	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure, Visual Failure Failure Reason: No strobe.									
EP4	6th Floor	BY 6A101	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	6th Floor	BY 6A131	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	6th Floor	BY STAIRWELL 8	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	9th Floor	BY 9A-123H	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	9th Floor	BY 9A-123J	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	EXAM GF132	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	EXAM GF133	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	EXAM GF138	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	Ground	EXAM GF134	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	Ground	EXAM GF139	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	Ground	EXAM GF152	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM RM 2 GF232	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 1 GF233	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 3 GF236	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 7 GF213	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 4 GD235	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 5 GF216	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 6 GF215	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM ROOM 8 GF212	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	EXAM GF187	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									
EP4	Ground	EXAM GF189	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No strobe.									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	Ground	EXAM GF186	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	EXAM GF185	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	EXAM GF184	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	EXAM GF180	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	WAITING AREA GA137	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	OPTICAL SHOP GA137	—	Speaker/Strobe	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe.									
EP4	Ground	BY ELEVATOR P8 strobe	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No strobe									
EP4	Ground	BY GE101	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	BY GF213	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	BY GF215	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	BY GF217	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	BY GF218	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio.									
EP4	Ground	BY GF220	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: No audio									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
EP4	Ground	BY GF231	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
EP4	Ground	IN PHARMACY #1	—	Speaker	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: No audio.									
NFPA 72	1st Floor	Elevator P14	N3L1M010	Alternate Elevator Recall	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Elevator did not recall to any floor.									
NFPA 72	1st Floor	1G130	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 TROUBLE									
NFPA 72	1st Floor	1A102	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 TROUBLE									
NFPA 72	1st Floor	1E-111 BPS 1-5	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 3 & 4 TROUBLES									
NFPA 72	2nd Floor	2A-100	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 TROUBLE									
NFPA 72	2nd Floor	2E-117 BPS 2-5	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC TROUBLES									
NFPA 72	2nd Floor	2F-153A	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 3 trouble									
NFPA 72	2nd Floor, 3rd Floor, 4th Floor, Ground	Elevator P13	N3L1M031	Primary Elevator Recall	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not recall to any floor.									
NFPA 72	3rd Floor	3E-116 BPS 3S-2	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: TROUBLE LED									
NFPA 72	3rd Floor	3A-101 INX 3-1	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: BATTERY CHARGER TROUBLE									
NFPA 72	3rd Floor	3A-101 INX 3-2	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: BATTERY CHARGER TROUBLE									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
NFPA 72	3rd Floor	3G-105 (3rd fl NAC)	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 1 TROUBLE									
NFPA 72	3rd Floor	3G-105 (4th fl NAC)	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 1 TROUBLE									
NFPA 72	3rd Floor	3A-116 BPS 3-S	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 3 TROUBLE									
NFPA 72	4th Floor	4th Floor 4F106 Fire Curtain Release	N9L1M113	Fire Curtain	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: Door did not close on general alarm.									
NFPA 72	4th Floor	4A-101 BPS-4C	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 3 TROUBLE									
NFPA 72	4th Floor	4E-108 BPS 4-S	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 4 TROUBLE									
NFPA 72	4th Floor	4E-108 E3 series	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: TROUBLE LEDS									
NFPA 72	5th Floor	5A-183 INX 5-2	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: BATTERY TROUBLE									
NFPA 72	5th Floor	5A-183 BPS	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 1 TROUBLE									
NFPA 72	5th Floor	5E-112 BPS 5-S	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 3 & 4 TROUBLE									
NFPA 72	6th Floor	6A-167 INX6-2	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: BATTERY CHARGER TROUBLE									
NFPA 72	6th Floor	6A-167 INX-1	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: BATTERY CHARGER TROUBLE									
NFPA 72	6th Floor	6A-167 BPS6	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
Failure Type: Functional Failure Failure Reason: NAC 1 trouble									

Device Deficiencies									
Test to Perform	Location	Description	Address	Device	Make	Model	Barcode	Inspector / Date	Images
NFPA 72	6th Floor	6E-116 LOWER	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: TROUBLE LED									
NFPA 72	7th Floor	7A-171	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 & 4 TROUBLE									
NFPA 72	7th Floor	7A-171 (INX7-1)	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: DG TROUBLE LED 9									
NFPA 72	8th Floor	8E-102	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 TROUBLE									
NFPA 72	8th Floor	8A-175 (INX8-2)	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: In trouble									
NFPA 72	9th Floor	9A101	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: POWER SUPPLY NOT SUPERVISED									
NFPA 72	Basement	Mail Room (LOGISTICS BE102B)	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 3 TROUBLE									
NFPA 72	Ground	GA-102	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 3 TROUBLE									
NFPA 72	Ground	GE101C1 BOTTOM RIGHT	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1 TROUBLE									
NFPA 72	Ground	GE101C1 TOP LEFT	—	Remote Power Supply	—	—	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: NAC 1-4 IN TROUBLE									
NFPA 72,EP3,EP2	—	BB-100 Gamewell FCI Panel	—	—	—	FCI	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Visual Failure,Functional Failure FAILURE REASON: Multiple troubles on FACP.									
NFPA 72,EP3,EP2	—	STONEWALL/ PARK PLACE FEED TRAILER (north parking lot)	—	—	—	MS-SUD	—	Robert L Starbuck 02/16/2026	—
FAILURE TYPE: Functional Failure FAILURE REASON: Did not report to main FACP. Need monitoring.									

CANNOT INSPECT REPORT									
LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	DATE OF TEST	TYPE	IMAGES
Ground	Elevator P11	N9L2M044	Alternate Elevator Recall	—	—	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Under construction.									
8th Floor	Elevator P11	N9L2M045	Elevator Shunt Trip	—	—	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Under construction.									
1st Floor, 2nd Floor, 3rd Floor, 4th Floor, 5th Floor, 6th Floor, 7th Floor, Basement	Elevator P11	N9L2M043	Primary Elevator Recall	—	—	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Under construction.									
Ground	G.F. Canteen Construction Heat	N5L1S032	Heat Detector	FCI	ATD-L3-IV	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Unable to locate.									
2nd Floor	Smoke by 2nd Floor Rm. 2E118 North	N5L2S041	Smoke Detector	FCI	ASD-PL3-IV	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Under construction.									
2nd Floor	Smoke by 2nd Floor Rm. 2E118 South	N5L2S042	Smoke Detector	FCI	ASD-PL3-IV	—	02/16/2026	Cannot Inspect	—
Reason cannot inspect: Under construction.									