

Attachment 03

- **No Fault Found (NFF) / Could Not Duplicate (CND) / Test, Teardown, & Evaluate (TT&E) (ACL-001A-00, ACH-801A-00, ACH-001A-00, ACH-802A-00)** - The NFF defined as Seller can't duplicate the reported/induced anomaly and TT&E defined as initial test and evaluation by Seller.
 - Perform incoming visual inspection
 - Perform Acceptance Test Procedure (ATP)
 - For the LPHUD (ACH-801A-00) this process should include additional supplier-developed engineering testing developed during the power-on failure investigation
 - In case of unverified failure report, perform all NFF environmental and ESS procedures
- **LAD Minor Repair (ACL-001A-00)** - The repair is classified as Minor if any of the following or a combination occurs:
 - Perform incoming ATP and evaluation
 - Removing / replacement of superficial components such as the TS bezel (PN), left/right bezels (103261D-00 (left), 103262D-00 (right)), bottom bezel (103263C-00), solar guard (PN), touch guards (PN) and installation screws.
 - **Cleaning of Fiber Optics**
 - Adherence to guidelines in technical manual NAVAIR 01-1A-505-4 Change 1 15-August-2021 for Installation and Repair Practices for Aircraft Fiber Optic Cables (Section 8.01, Tables 1-2)
 - Perform additional trouble shooting if required (Vibration and Thermal Testing, 1 cycle per Seller's approved procedure)
 - Perform ATP after repair (part of formal sell-off process using approved procedures)
 - Note: No ESS testing is required for Minor Repairs (part of formal sell-off process)
- **LAD Major Repair (ACL-001A-00)** - The repair is classified as Major if effort applicable to repairing item occurs in any combination of the following:
 - Perform incoming ATP and evaluation
 - Involves opening of the Rear cover or the Display Head Assembly
 - Disconnections of internal wiring harnesses
 - Disconnection, replacement, and repair of Shop Replaceable Assemblies (SRAs)
 - Replacement of Fiber Optics and/or connectors.
 - Perform extensive/multiple trouble shooting (Vibration and Thermal Testing, 1-3 cycles max.).
 - Perform ESS – Part of formal sell-off process using approved procedures.
 - Perform ATP after repair - part of formal sell-off process using approved procedures
 - Any combination of minor and major repairs will fall under the category of a major repair.

Attachment 03

- **LPHUD Minor Repair (ACH-801A-00)** - The repair is classified as Minor if any of the following or a combination occurs:
 - Perform incoming ATP and evaluation
 - Note: If an inducted LPHUD is found to only require repairs to the HCP (ACH-802A-00) or HVC (ACH-001A-00), the repair of those components will fall under a minor repair.
 - Limited to simple repair without disassembly of the Projector Unit (PU). For example, fixing bent pins on externally accessible subassemblies Heads up Display-Control Panel (HUD-CP) (ACH-802A-00), Angle of Attack (AOA) (ACH-804A-00), HUD Video Camera (HVC) (ACH-001A-00), chassis guide pins and plunger replacements.
 - Projector Unit (PU) Repairs to combiner or replacement of combiners (WO combiner Cost)
 - Limited repair to outside of the PU unit. No ESS testing required due to no seals are broken or disassembly of the PU unit
 - Replacement of control panel and or AOA .(WO Panel/AOA Cost)
 - Perform ATP after repair (part of formal sell-off process using approved procedures)
 - Note: No ESS testing is required for Minor Repairs (part of formal sell-off process)
- **LPHUD Major Repair (ACH-801A-00)** - The repair is classified as Major if effort applicable to repairing item occurs in any combination of the following:
 - Perform incoming ATP and evaluation
 - Replacement and repair of electronic unit Assemblies/Circuit Card Assemblies (CCAs).
 - Significant repairs to optical elements/lenses
 - Repairs to Digital Image Source (DIS).
 - Perform extensive/multiple trouble shooting (Vibration and Thermal Testing, 1-3 cycles max.)
 - Perform ESS – Part of formal sell-off process using approved procedures.
 - Perform ATP after repair - part of formal sell-off process using approved procedures
 - Any combination of minor and major repairs will fall under the category of a major repair.
- **Camera, Television Repair (ACH-001A-00)** - The repair is classified as Major if effort applicable to repairing item occurs in any combination of the following:

Attachment 03

- Perform incoming ATP and evaluation
 - Repairs
 - Perform extensive/multiple trouble shooting (Vibration and Thermal Testing, 1-3 cycles max.)
 - Perform ESS – Part of formal sell-off process using approved procedures.
 - Perform ATP after repair - part of formal sell-off process using approved procedures
- **Control Panel, AirCR Repair (ACH-802A-00)** - The repair is classified as Major if effort applicable to repairing item occurs in any combination of the following:
 - Perform incoming ATP and evaluation
 - Repair
 - Perform extensive/multiple trouble shooting (Vibration and Thermal Testing, 1-3 cycles max.)
 - Perform ESS – Part of formal sell-off process using approved procedures.
 - Perform ATP after repair - part of formal sell-off process using approved procedures
- **Beyond Economical Repair (BER) / Beyond Physical Repair BPR (ACL-001A-00, ACH-801A-00, ACH-001A-00, ACH-802A-00):** Seller shall electronically notify Buyer of a Unit recommended to be BER or determined to be BPR to initiate disposition instructions during T&E phase. In the event, during the repair, Seller determines the item is BER/BPR, Seller shall cease work and request Buyer's direction for approval and disposition.