

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA58118		A01

TITLE:

A-Frame Assembly; repair

JOB SPECIFICATION

Anticipated Award Date: 12/04/2025 5/01/2026		Production Completion Date: 11/07/2026 8/29/2026		PREPARING ACTIVITY: SASEBO	
POP Start Date: 2/02/2026 6/01/2026		POP End Date: 11/15/2027 9/30/2026			
PREPARED BY: Y.HAMABE 4/9/2026 Avelino L. Reyes Jr.		CODE H HA	DATE 9/05/2025		
APPROVED BY: S.MURAKAMI <i>SEM</i>		CODE S225			
CONCURRED BY: S.MOROOKA <i>SMO</i>		CODE S231			
ASSIST PLANNER'S NAME:		CODE			
ASSIST PLANNER'S NAME:		CODE			
ASSIST PLANNER'S NAME:		CODE			
DESCRIPTION:					
JSN(S): CU51-2026 and CU51-2016 <i>A</i> CASREP #					
S/F CONTACT: SANCHEZ EN1 / KHULLAR GSCS CWP # CCNS #					
Approved by S300/S900		A. REYES <i>PM S300</i> <i>SR</i>	Date: 9/29/25	Avl: 681	6C2 4/9/2026 Avelino L. Reyes Jr.
LWC:					
Work Completed					
S/Force: Rate: Date:					
Ship Supt: Date: SRF CONTROL NO.: 1301357121					
WORK CERTIFICATION SIGNATURES					
COMPLETION OF WORK REVIEW:		BADGE NO.:	SHOP/CODE:	PHONE:	DATE:

1/4/3

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA58118		A01
TITLE:					
A-Frame Assembly; repair					

1. SCOPE:

- 1.1 Title: A-Frame Assembly; repair
- 1.2 Location of Work:
 - 1.2.1 Vehicle Deck, Frames 66 through 72, Starboard Side
- 1.3 Identification:
 - 1.3.1 A Total of (5 SF) of Pitted Surface on A-Frame Assembly, Located in 1.2.1

2. REFERENCES:

- 2.1 Standard Items (FY26)
- 2.2 520-2889665 Rev D, Anchor Handling Arrangement and Details

3. REQUIREMENTS:

3.1 Grind out and build up each pitted surface listed in 1.3.2, using 2.2 for guidance.

3.1.1 Accomplish the requirements of 009-12 of 2.1, including Table 4, Column A, Lines One through 7 for welding.

3.2 Accomplish the requirements of 009-32 of 2.1 for cleaning and preservation of each new and disturbed surface to match surrounding areas.

(V) (G) "VERIFICATION"

3.3 Inspect and verify completion of this work. -S130

4. NOTES:

4.1 Initial Condition - Degradation was caused by blunt force impact and appears to be primarily cosmetic in nature. Request weld build-up in damaged area as required, and preservation.

4.2 The replacement of reversing sheave and stern anchor handling system operational test will be conducted under ICN 38NBA31109_H01.

4.3 Removal and installation work of stern anchor wire rope assembly will be conducted under 38NBA31109_H02.

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN: 38NBA58118	Rev:	Key Op: A01
LCU-1651	NBU-7				

TITLE:

A-Frame Assembly; repair

5. GOVERNMENT FURNISHED MATERIAL (GFM) :

5.1 See attached MATERIAL LIST.

MATERIAL LIST									
ITEM NO.	PC NO.	REF NO.	M/C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
001			M	ELECTROD, WELDING ROD, 7018M, 3/32"DIA X 14"L, 10LB/CN, MIL-E-22200/10, P/N: 255014102	9G 3439 SA4742861	N		3/CN	3.2
002			M	ELECTROD, WELDING ROD, 7018M, 1/8"DIA X 14"L, 10LB/CN, MIL-E-22200/10, P/N: 255014110	9G 3439 SA4742863	N		3/CN	3.2
003			M	CLEANING COMPOUND,S, SOLVENT, USE FOR CLEANING OF WIRE ROPE, MIL-PRF-680 TYPE III, 5GL/CO	9B 6850 014742320	Y		3/CO	3.1
004			M	CLOTH, CLEANING, WIDTH: 12" TO 14", LENGTH: 16" TO 20", 10LB/BX	9Q 7920 000449281	N		3/BX	3.1
005			M	GREASE,WIRE ROPE-EX, WIRE ROPE-EXPOSED GEAR, CORROSION RESISTIVE, LOW EVAPORATION AND SALT WATER RESISTANT, MIL-PRF-18458, 35LB/CN	9B 9150 005306814	Y		3/CN	3.3