

ASBESTOS INSPECTION REPORT of:

Building # G560

MCB CAMP LEJEUNE



Print Date

Monday, August 18, 2025

INSPECTION SUMMARY

BLDG #: G560

YEAR BUILT: 1977

OCCUPANT: MWR STAFF NCO CLUB

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 3/GREEN [AH JUL2022]
INTERIOR WINDOW GLAZING ACCESSIBLE AND POTENTIAL FOR DISTURBANCE. MONITOR CONDITION.

JAN2014
PVS. ACM REMAINS, NO CHANGE

MAR2010
ADDL SAMPLING/ INSPECTION, ACM INCLUDES:
WINDOW GLAZING MATERIAL
RESIDUAL MASTIC
12" BLACK TILE AND MASTIC
ROOFING SEALANT, BLACK

NOV07
ADDL SAMPLES, NO ACM IDENTIFIED

INSPECT MAY96
NO ASBESTOS CONTAINING MATERIALS IDENTIFIED. UNDER RENOVATION DURING INSPECTION.

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
No friable ACM records found in database			

Non-friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
ROOFING SEALANT, BLACK	NORTH AND SOUTH ROOF, VENT BASE FLASHING PATCHING	3/25/2010	24 LF
WINDOW GLAZING MATERIAL	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	7/20/2022	270 LF
ROOFING SEALANT, BLACK	NORTH AND SOUTH ROOF, VENT BASE FLASHING PATCHING	7/20/2022	24 LF
WINDOW GLAZING MATERIAL	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	3/25/2010	270 LF
WINDOW GLAZING MATERIAL	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	1/15/2014	270 LF
ROOFING SEALANT, BLACK	NORTH AND SOUTH ROOF, VENT BASE FLASHING PATCHING	1/15/2014	24 LF

WINDOW GLAZING MATERIAL	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	6/6/2016	270 LF
ROOFING SEALANT, BLACK	NORTH AND SOUTH ROOF, VENT BASE FLASHING PATCHING	6/6/2016	24 LF

Tested Non ACM or REMOVED Materials

DESCRIPTION	LOCATION	Date
WINDOW GLAZING MATERIAL	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	11/29/2007
FIRE CURTAIN	NORTH WING ROOM DIVIDER CURTAINS BETWEEN SOUTH DINING AND NORTH STAGE/ DANCE FLOOR AREAS	5/1/1996
EXTERIOR CAULKING,	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	11/29/2007
PIPE WRAPPING ON	EXTERIOR SOUTHEAST, HVAC/ AC UNIT PIPING	11/29/2007
INTERIOR CAULKING,	DOORS THROUGHOUT	11/29/2007
JOINT MATERIAL	PATCHING AT DOORWAYS, MIXED THROUGHOUT	11/29/2007
CARPET ADHESIVE	NORTH WING DINING AREA; SOUTH WING THROUGHOUT EXCEPT KITCHEN AREAS	11/29/2007
DRYWALL AND JOINT MATERIAL	INTERIOR WALLS THROUGHOUT	11/29/2007
WALL PANELING MATERIAL	NORTH WING, NORTH EAST AND WEST CLOSETS	11/29/2007
WALL TILE ADHESIVE	SOUTH WING, CENTER WEST ROOM	11/29/2007
2'x2' CEILING TILE,	THROUGHOUT THE BUILDING EXCEPT KITCHEN AND ASSOCIATED ROOMS	5/1/1996
12" CREAM FLOOR TILE AND ADHESIVE	NORTH WING, CENTRAL DANCE FLOOR	5/1/1996
EXTERIOR CAULKING,	METAL WINDOW TRIM	3/25/2010
FLOOR LEVELING COMPOUND	NORTH WING, NORTH END; SOUTHEAST OFFICE, OVER RESIDUAL ACM BLACK MASTIC, UNDER HM21 FLOOR TILE AND CARPET	3/25/2010
12" BLACK FLOOR TILE AND ADHESIVE	SOUTHEAST OFFICE, UNDER CARPET, OVER HM20	3/25/2010
PLASTER MATERIAL	SOUTHWEST KITCHEN AREA WALLS AND CEILINGS	3/25/2010
EXTERIOR CAULKING,	ROOFING SCREW HEADS	3/25/2010
DRYWALL AND JOINT MATERIAL	INTERIOR WALLS THROUGHOUT	3/25/2010
CARPET ADHESIVE	NORTH WING DINING AREA; SOUTH WING THROUGHOUT EXCEPT KITCHEN AREAS	3/25/2010
12" CREAM FLOOR TILE AND ADHESIVE	NORTH WING, CENTRAL DANCE FLOOR	3/25/2010

EXTERIOR CAULKING,	SOUTHSIDE AND NORTH WING EAST/ WEST METAL WINDOWS	3/25/2010
FLOOR LEVELING COMPOUND	NORTH WING, NORTH END; SOUTHEAST OFFICE, OVER RESIDUAL ACM BLACK MASTIC, UNDER HM21 FLOOR TILE AND CARPET	1/15/2014
12" BLACK FLOOR TILE AND ADHESIVE	SOUTHEAST OFFICE, UNDER CARPET, OVER HM20	1/15/2014
FLOOR LEVELING COMPOUND	NORTH WING, NORTH END; SOUTHEAST OFFICE, OVER RESIDUAL ACM BLACK MASTIC, UNDER HM21 FLOOR TILE AND CARPET	6/6/2016

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
G560-01-001	01	2'x2' CEILING TILE,	5/1/1996	NORTH WING, NORTH DANCE FLOOR	0	0	0
G560-01-002	01	2'x2' CEILING TILE,	5/1/1996	NORTH WING, SOUTH DINING AREA	0	0	0
G560-01-003	01	2'x2' CEILING TILE,	5/1/1996	SOUTH BAR AREA	0	0	0
G560-02-004	02	12" CREAM FLOOR TILE w/BROWN FLECKS AND ADHESIVE	5/1/1996	NORTH WING, AT STAGE CLOSET	0	0	0
G560-02-20	02	12" CREAM FLOOR TILE w/BROWN FLECKS AND ADHESIVE	3/25/2010	NORTH WING NORTH, SW EDGE	0	0	0
G560-02-20tem	02	12" CREAM FLOOR TILE w/BROWN FLECKS AND ADHESIVE	3/25/2010	NORTH WING NORTH, SW EDGE	0	0	0
G560-02-21	02	12" CREAM FLOOR TILE w/BROWN FLECKS AND ADHESIVE	3/25/2010	NORTH WING, NE CORNER	0	0	0
G560-03-005	03	FIRE CURTAIN	5/1/1996	NORTH WING, CNTR CURTAIN	0	0	0
G560-10-10	10	EXTERIOR CAULKING, WHITE	11/29/2007	SOTUH CNTR, WEST WINDOW	0	0	0
G560-10-11	10	EXTERIOR CAULKING, WHITE	11/29/2007	SOUTH CNTR, EAST WINDOW	0	0	0
G560-10-20	10	EXTERIOR CAULKING, WHITE	3/25/2010	SOUTHSIDE, EAST WINDOW	0	0	0
G560-10-21	10	EXTERIOR CAULKING, WHITE	3/25/2010	SOUTHSIDE, CNTR WINDOW	0	0	0
G560-11-10	11	PIPE WRAPPING ON WHITE	11/29/2007	SOUTH WING, EAST EXT. AC UNIT	0	0	0
G560-12-10	12	INTERIOR CAULKING, WHITE	11/29/2007	NORTH WING, SW CLOSET DOOR	0	0	0
G560-13-10	13	JOINT MATERIAL	11/29/2007	NORTH WING, SW DOORWAY	0	0	0
G560-13-11	13	JOINT MATERIAL	11/29/2007	NORTH WING, NW DOORWAY	0	0	0
G560-14-10	14	CARPET ADHESIVE YELLOW/ TAN	11/29/2007	NORTH WING, NW	0	0	0
G560-14-11	14	CARPET ADHESIVE YELLOW/ TAN	11/29/2007	NORTH WING, SE	0	0	0
G560-14-20	14	CARPET ADHESIVE YELLOW/ TAN	3/25/2010	NORTH WING, SOUTH CNTR	0	0	0
G560-14-21	14	CARPET ADHESIVE YELLOW/ TAN	3/25/2010	SOUTH CNTR MAIN AREA, SOUTH CNTR	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
G560-15-10	15	DRYWALL AND JOINT MATERIAL		11/29/2007	NORTH WING, NW CLOSET WALL	0	0	0
G560-15-11	15	DRYWALL AND JOINT MATERIAL		11/29/2007	SOUTH WING, CNTR MAIN AREA NW WALL	0	0	0
G560-15-20	15	DRYWALL AND JOINT MATERIAL		3/25/2010	NORTH WING, SW CLOSET	0	0	0
G560-15-21	15	DRYWALL AND JOINT MATERIAL		3/25/2010	SOUTH WING, NE MALE HEAD	0	0	0
G560-16-10	16	WALL PANELING MATERIAL		11/29/2007	NORTH WING, NE CLOSET	0	0	0
G560-17-10	17	WALL TILE ADHESIVE		11/29/2007	SOUTH WING, SW	0	0	0
G560-18-00ri13	18	WINDOW GLAZING MATERIAL	BEIGE	1/15/2014	N/A	9	9	9
G560-18-00ri16	18	WINDOW GLAZING MATERIAL	BEIGE	6/6/2016	N/A	9	9	9
G560-18-10	18	WINDOW GLAZING MATERIAL	BEIGE	11/29/2007	WEST SIDE OF BLDG	0	0	0
G560-18-20	18	WINDOW GLAZING MATERIAL	BEIGE	3/25/2010	SOUTHSIDE, EAST BAR, SOUTH WINDOW	0	0	0
G560-18-21	18	WINDOW GLAZING MATERIAL	BEIGE	3/25/2010	SOUTHSIDE MAIN CNTR ROOM, SOUTH CNTR WINDOW	2	0	0
G560-20-00ri13	20	FLOOR LEVELING COMPOUND	w/RESIDUAL MASTIC	1/15/2014	N/A	9	9	9
G560-20-20	20	FLOOR LEVELING COMPOUND	w/RESIDUAL MASTIC	3/25/2010	NORTH WING, WEST CNTR AT CURTAIN	0	0	0
G560-20-21	20	FLOOR LEVELING COMPOUND	w/RESIDUAL MASTIC	3/25/2010	SE OFFICE, SW CORNER	3	0	0
G560-20-30	20	FLOOR LEVELING COMPOUND	w/RESIDUAL MASTIC	6/6/2016	SE WING, SE AT RENOVATIONS	.1	.1	.1
G560-21-00ri13	21	12" BLACK FLOOR TILE AND ADHESIVE		1/15/2014	N/A	9	9	9
G560-21-20	21	12" BLACK FLOOR TILE AND ADHESIVE		3/25/2010	SE OFFICE, SW CORNER	3	0	0
G560-21-21	21	12" BLACK FLOOR TILE AND ADHESIVE		3/25/2010	SE OFFICE, NE CORNER	2	0	0
G560-21-21tem	21	12" BLACK FLOOR TILE AND ADHESIVE		3/25/2010	SE OFFICE, NE CORNER	7.02	0	0

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
G560-22-20	22	PLASTER MATERIAL	3/25/2010	SW KITCHEN, NORTH CNTR WALL	0	0	0
G560-22-21	22	PLASTER MATERIAL	3/25/2010	SW KITCHEN, SW STORAGE CEILING	0	0	0
G560-23-20	23	EXTERIOR CAULKING, BLACK	3/25/2010	SOUTH ROOF, SE	0	0	0
G560-24-00ri13	24	ROOFING SEALANT, BLACK	1/15/2014	N/A	9	9	9
G560-24-00ri16	24	ROOFING SEALANT, BLACK	6/6/2019	N/A	9	9	9
G560-24-20	24	ROOFING SEALANT, BLACK	3/25/2010	SOUTH ROOF, NE VENT	3	0	0
G560-24-21	24	ROOFING SEALANT, BLACK	3/25/2010	SOUTH ROOF, NW VENT	3	0	0
G560-25-20	25	EXTERIOR CAULKING, GRAY	3/25/2010	SOUTH WING, SOUTH CNTR	0	0	0