

Request For Information (RFI)
For FAR 6.302-1 Acquisition Efforts

10 March 2026

APG-82v1 Radar Power Supply NSN: 6130-01-619-8424FX, P/N: 5231100-100, Common Integrated Sensor Processor (CISP), NSN 5975-01-667-3890FX, P/N 5243222-105, Receiver Exciter (REX), NSN 5985-01-670-0087FX, P/N 5231720-105, Active Electronically Scanned Array (AESA), NSN 5985-01-643-8624FX, P/N 5241600-100

Introduction:

The Government is conducting market research to identify potential sources that possess the expertise, capabilities, and experience to meet qualification requirements for repair of the F-15E APG-82v1 Radar Power Supply (RPS), NSN 6130-01-619- 8424FX, P/N 5231100-100, Common Integrated Sensor Processor (CISP), NSN 5975-01-667-3890FX, P/N 5243222-105, Receiver Exciter (REX), NSN 5985-01-670-0087FX, P/N 5231720-105, and Active Electronically Scanned Array (AESA), NSN 5985-01-643-8624FX, P/N 5241600-100. The Government does not own or have access to the data for these items. The Government has determined that this system is a non-commercial item.

Samples are not available for potential supplier to evaluate.

Contractor shall furnish all material, support equipment, tools, test equipment, and services. The contractor is responsible for providing, maintaining, and calibrating all support equipment required at their facility or a subcontractor's facility. Contractor furnished material or parts used for replacement shall equal or exceed the quality of the original material or parts.

The current sole source for the APG-82V1 (RPS), (CISP), (REX), and (AESA) is Raytheon Technologies.

Contractors/Institutions responding to this market research are placed on notice that participation in this survey may not ensure participation in future solicitations or contract awards. The government will not reimburse participants for any expenses associated with their participation in this survey.

Overview:

1. The document(s) below contain a description of the APG-82V1 (RPS), (CISP), (REX), and (AESA) requirement and a Contractor Capability Survey. The Survey allows Contractors to provide their company's capability.
2. If, after reviewing these documents, you desire to participate in the market research, you should provide documentation that supports your company's capability in meeting these requirements. Failure to provide documentation may result in the government being unable to adequately assess your capabilities. If you lack sufficient experience in a particular area, please provide details explaining how you would overcome the lack of experience/capabilities in order to perform that portion of the requirement (i.e., teaming, subcontracting, etc.)
3. Both large and small businesses are encouraged to participate in this Market Research. Joint ventures or teaming arrangements are encouraged.
4. Questions relative to this market survey should be addressed to Madison Norris (madison.norris@us.af.mil) with copy to Joseph Jones (joseph.jones.81@us.af.mil)

APG-82v1 Radar Power Supply NSN: 6130-01-619-8424FX, P/N: 5231100-100, Common Integrated Sensor Processor (CISP), NSN 5975-01-667-3890FX, P/N 5243222-105, Receiver Exciter (REX), NSN 5985-01-670-0087FX, P/N 5231720-105, Active Electronically Scanned Array (AESA), NSN 5985-01-643-8624FX, P/N 5241600-100

PURPOSE

This market survey is being conducted to identify potential sources that may possess the expertise, capabilities, and experience to meet the requirements for repair of the F-15E APG-82v1 Radar Power Supply, NSN 6130-01-619-8424FX, P/N 5231100-100, Common Integrated Sensor Processor (CISP), NSN 5975-01-667-3890FX, P/N 5243222-105, Receiver Exciter (REX), NSN 5985-01-670-0087FX, P/N 5231720-105, and Active Electronically Scanned Array (AESA), NSN 5985-01-643-8624FX, P/N 5241600-100. The parameters can be found below in the description section. The potential source should have a good knowledge of the specific information required to repair the Radar Power Supply, Common Integrated Sensor Processor, Receiver Exciter and AESA.

Description

The Radar Power Supply (RPS) is a Line Replaceable Units (LRU) on the F-15E. The RPS powers the APG-82(V)1 radar system used on the F-15E. It receives, filters, and converts power from the aircraft's Auto Transformer-Rectifier Units (ATRU) to power to the following Radar Line Replaceable Units (LRU): Active Electronically Scanned Array (AESA), Receiver/Exciter (REX) and Common Integrated Sensor Processor (CISP).

The Active Electronically Scanned Array (AESA) is a type of phased array antenna, which is a computer-controlled antenna array in which the beam of radio waves can be electronically steered to point in different directions without moving the antenna.

The Receiver/Exciter (REX) serves two functions. The exciter provides precision excitation for the antenna. The receiver receives the return signal from the Antenna, performs initial processing, and converts the returned signal to digital form for further processing in the CISP.

The Common Integrated Sensor Processor (CISP) is responsible for radar system management and control, data and signal processing, and system performance monitoring and measurement.

The APG-82(V)1 is currently replacing the APG-70 through modification program. Wright Patterson completed the USAF Depot Source of Repair (DSOR) decision (07-54) which deemed the APG-82(V)1 radar workload to be fully organic. The USAF does not own the required technical data needed to develop a depot repair capability for sustainment of the radar's hardware and OFP software. This technical data is owned solely by Raytheon. The USAF will develop the ability to sustain tactical OFP software, correct false alarms associated with the radars Built-In-Test (BIT) software, and correct Software Deficiency Reports (SDRs).

The RPS, CISP, REX and AESA are currently repaired under the Eagle Eyes Interim Contractor Support (ICS) contract, FA8634-16-C-2653. Boeing (CAGE 0PXV4) is the Eagle Eyes prime contractor; Raytheon Company (referred to as Raytheon throughout this document) is a subcontractor under the Eagle Eyes contract. Boeing subcontracts to Raytheon during ICS for depot hardware/software repair support at their facilities. Raytheon developed and is the AN/APG- 82(V)1 radar Subject Matter Experts (SMEs) for the radar hardware and OFP software.

This survey covers the following items:

NOUN	NSN	P/N
Radar Power Supply	6130-01-619-8424FX	5231100-100
Common Integrated Sensor Processor	5975-01-667-3890FX	5243222-105
Receiver Exciter	5985-01-670-0087FX	5231720-105
Active Electronically Scanned Array	5985-01-643-8624FX	5241600-100

The original equipment manufacturer for these items is Raytheon (CAGE 4U884), which maintains its configuration by part number and software version. The Government does not own any production level technical data in support of this requirement. As a result, Raytheon is the only known source with adequate knowledge of the F-15E's RPS performance requirements and possession of the required technical data and capabilities needed to repair this item and ensure compatibility of the equipment. The RPS, CISP, REX, and AESA must meet all operational requirements currently in place for the F-15E RPS, CISP, REX, and AESA as currently provided by Raytheon. The delivered units must meet all performance tests as described in Raytheon's test requirements documents. Furthermore, the costs associated with qualifying another repair source as well as the verification costs would be prohibitive and significantly delay the timeline to put a repair contract in place.

Interested sources may identify their interest and capability to respond to the requirements. Interested sources must maintain facilities and cleared personnel for repairing, handling, storing, and maintaining information and operating systems with security classifications up to and including Secret.

Interested parties must be capable of providing repair production status on a monthly basis and must be capable of addressing deficiencies through Joint Deficiency Reporting System (JDRS), in accordance with the USAF Deficiency Reporting, Investigation and Resolution Process (ref. T.O. 00-35D-54)

CONTRACTOR CAPABILITY SURVEY

Part I. Business Information

Please provide the following business information for your company/institution and for any teaming or joint venture partners:

- Company/Institute Name:
- Address:
- Point of Contact:
- CAGE Code:
- Phone Number:
- E-mail Address:
- Web Page URL:
- Government Proposed North American Industry Classification System (NAICS) Code: _____
Based on the Government proposed NAICS Code, state whether your company is:
 - Small Business (Yes / No)
 - Woman Owned Small Business (Yes / No)
 - Small Disadvantaged Business (Yes / No)
 - 8(a) Certified (Yes / No)
 - HUBZone Certified (Yes / No)
 - Veteran Owned Small Business (Yes / No)
 - Service Disabled Veteran Small Business (Yes / No)
 - System for Award Management (SAM) (Yes / No)
 - A statement as to whether your company is domestically or foreign owned (if foreign, please indicate the country of ownership).

Responses to the Capability Survey Part I and Part II must be received no later than close of business (enter due date [IAW instructions above](#)). Please ensure data is in a readable electronic format that can be received through a firewall. Attachments shall not to exceed 10 MB per email. Multiple emails are acceptable. Question and responses must be sent via email to the following:

- Madison Norris (madison.norris@us.af.mil)
- Joseph Jones (joseph.jones.81@us.af.mil)

Part II. Capability Survey Questions

A. General Capability Questions:

1. Describe briefly the capabilities of your facility and nature of the goods and/or services you provide. Include a description of your staff composition and management structure.
2. Describe your company's past experience on previous projects similar in complexity to this requirement. Include contract numbers, a brief description of the work performed, period of performance, agency/organization supported, and individual point of contact (Contracting Officer or Program Manager).
3. Describe your company's experience in repairing the Part Number/NSNs listed above that make up the APG-82V1 Radar.
4. Describe your company's capabilities for generating, handling, processing and storing classified material and data.
5. Describe your company's capabilities and experience in generating technical data, engineering drawings and manuals. Identify what software programs are utilized to generate these data products and what formats are available for delivered items.
6. What is your company's current maximum capacity per month for the RPS? Provide information on any facility reserves you may possess to increase capacity in the event of an immediate need do to critical operational mission requirements.
7. What quality assurance processes and test qualification practices does your company employ? Provide a description of your quality program (ISO 9001, AS9100, etc.).
 - a. Provide a detailed quality plan implementing AS9100 (or equivalent).

B. Repair Questions:

1. Describe your capabilities and experience in repairing existing systems/equipment (hardware and software) to solve maintenance and support problems in the depot environment.
2. Describe your capabilities and experience in developing/modifying repair or maintenance procedures. Include associated upgrade of technical orders and preparation of new technical orders.
 - a. State the types of diagnostic and troubleshooting tools utilized for efforts such as this.
3. Demonstrate your ability and experience in repair of the same or similar components, which are currently in use on commercial or military aircraft by providing the following information on the same or similar items:
 - a) Contract Number
 - b) Procuring Agency
 - c) Contract Value
 - d) Number of assets shipped

4. Provide your commercial manual(s) or Acceptance Test Procedures (ATP) and your rights to these manuals and or ATP used in the depot level repair and functional check of these or similar assets for Government Engineer review.
5. Describe your capabilities and experience in test, evaluation, repair or maintenance procedures.
6. Describe your configuration management processes and how you identify and resolve parts obsolescence and diminishing manufacturing sources problems?
7. Discuss your process for addressing any fit, form, and or function issues that may arise out of this effort.
8. Describe your process for maintaining inventory records and reporting on hand/work-in-process balances and repair status to your customer.
9. Include a detailed listing of facilities and equipment, including quantities, required to satisfy the requirements of this effort.
 - a. Provide an outline of the proposed process, including inspections.
 - i. State the type of test procedures are anticipated for this effort.
 - ii. State the type of inspection processes anticipated for this effort.
 1. NDI/T.
 2. Destructive testing/inspection.
10. How will your organization address the absence of drawings, specifications, technical data, test procedures, etc.
11. If the item cannot be repaired in total, state what your organization can repair.
12. State any technology insertion ideas for the item that would be suitable for this effort.
13. Discuss any reverse engineering or item replacement opportunities that may be present.

C. Commerciality Questions:

1. Is there established catalog or market prices for our requirement?
2. If you offer this product and/or service to both U.S. Government and commercial sources, is the same workforce used for both the U.S. Government and general public?
3. Is our requirement offered to both under similar terms and conditions? Briefly describe any differences.
4. Describe your standard warranty and return process for goods and services furnished to the government for items similar in nature to this requirement.

