

ASBESTOS INSPECTION REPORT of:

Building # FC571

MCB CAMP LEJEUNE



Print Date

Thursday, March 19, 2026

INSPECTION SUMMARY

BLDG #: FC571

YEAR BUILT: 1986

OCCUPANT: BEQ

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 3/GREEN [MAR2023]
ROOFING SEALANT

MAR2023
ACM REMAINS

SEPT2019
NO CHANGES, ADDL SAMPLING

JUN2016
ACM REMAINS

DEC2013
ACM ROOFING REMAINS, ADDL SAMPLING, ACM INCLUDES:
RESIDUAL MASTIC

MAY2010
PVS. TILE AND MASTIC REPLACED, CONFIRMATIONS TEM/ PLM. ADDL FULL SAMPLING, ACM IDENTIFIED INCLUDES:
ROOFING SEALANT, GRAY

SEPT05
PVS. ACM TILE AND MASTIC REMAINS.

INSPECT JUL02- AES
HOMO GROUPING, FC525, FC555 PRIMARY FOR AREA BEQS. ACM INCLUDES:
12" BEIGE TILE AND MASTIC

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
No friable ACM records found in database			

Non-friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	12/9/2013	1 SF
ROOFING SEALANT, GRAY	ATTIC [OLD ROOF] PERIMETER PARAPET FLASHINGS	5/18/2010	2,700 SF
ROOFING SEALANT, GRAY	ATTIC [OLD ROOF] PERIMETER PARAPET FLASHINGS	9/18/2019	2,700 SF

RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	9/18/2019	1	SF
ROOFING SEALANT, GRAY	ATTIC [OLD ROOF] PERIMETER PARAPET FLASHINGS	12/9/2013	2,700	SF
ROOFING SEALANT, GRAY	ATTIC [OLD ROOF] PERIMETER PARAPET FLASHINGS	6/9/2016	2,700	SF
RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	6/9/2016	3	SF
ROOFING SEALANT, GRAY	ATTIC [OLD ROOF] PERIMETER PARAPET FLASHINGS	3/28/2023	2,700	SF
RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	3/28/2023	1	SF

Tested Non ACM or REMOVED Materials

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>
TAR PAPER, BLACK	ATTIC [OLD ROOF] PERIMETER FLASHINGS AND MEMBRANE	5/18/2010
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE (UNDER CARPET)	7/18/2002
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	7/18/2002
MUDDERED FITTING(S)	MECHANICAL ROOMS AND CENTER PIPE CHASES	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	THIRD FLOOR LOUNGE	7/18/2002
DUCT SEALANT, RED	MECHANICAL ROOMS AND CENTER PIPE CHASES	7/18/2002
12" CREAM FLOOR TILE AND ADHESIVE	CENTRAL HALLWAYS	9/20/2005
EXTERIOR CAULKING,	DOORS AND BRICK JOINTS	9/20/2005
DUCT SEALANT, GRAY	CHASES AND ATTIC/ OLD ROOF DUCTS THROUGHOUT	9/20/2005
BUILT-UP ROOFING	ATTIC [OLD ROOF] MAIN MEMBRANE	5/18/2010
DUCT SEALANT, TAN	NORTH AND SOUTH WING MECHANICAL ROOMS HVAC DUCTS	5/18/2010
DUCT SEALANT, WHITE	NORTH AND SOUTH WING MECHANICAL ROOMS HVAC DUCTS	5/18/2010
CLOTH EXPANSION JOINT MATERIAL, THIN	NORTH AND SOUTH WING MECHANICAL ROOMS AHU UNITS	5/18/2010
DRYWALL AND JOINT MATERIAL	DORM ROOM CEILINGS AT HEADS THROUGHOUT	5/18/2010
LAGGING PAPER ON FIBERGLASS	FIRST FLOOR NORTH MECHANICAL ROOM TANK	5/18/2010

ROOFING SEALANT, BLACK	ATTIC [OLD ROOF] PERIMETER FLASHINGS	5/18/2010
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (HM01, 02 TILES)	7/18/2002
12" BLACK FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	7/18/2002
12" WHITE FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	7/18/2002
2'x2' CEILING TILE, TAR PAPER, BLACK	OFFICES AND CENTRAL LOUNGES	7/18/2002
	ATTIC [OLD ROOF] PERIMETER FLASHINGS AND MEMBRANE	9/18/2019
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	9/20/2005
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	5/18/2010
EXTERIOR CAULKING, DUCT SEALANT, GRAY	DOORS AND BRICK JOINTS	5/18/2010
	CHASES AND ATTIC/ OLD ROOF DUCTS THROUGHOUT	5/18/2010
12" BEIGE FLOOR TILE AND ADHESIVE	REPLACED HM03 PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (HM01. 02 TILES)	5/18/2010

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-01-01	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-01-02	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-02-03	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-02-04	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-03-05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE FC525	8	0	0
FC525-03-06	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE FC525	8	0	0
FC571-03-00RI0	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/20/2005	N/A	9	9	9
FC525-04-07	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-04-08	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE FC525	0	0	0
FC525-05-09	05	12" BEIGE FLOOR TILE AND ADHESIVE TYPE II	7/18/2002	2ND FL LOUNGE FC525	10	0	0
FC571-05-00RI0	05	12" BEIGE FLOOR TILE AND ADHESIVE TYPE II	9/20/2005	N/A	9	9	9
FC525-06-10	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	7/18/2002	3RD FL LOUNGE FC525	10	0	0
FC571-06-00RI0	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	9/20/2005	N/A	9	9	9
FC571-06-20	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	1ST FL SOUTH, SE ROOM	0	0	0
FC571-06-20tem	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	1ST FL SOUTH, SE ROOM	0	0	0
FC571-06-21	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	1ST FL NORTH, NW ROOM	0	0	0
FC571-06-22	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	2ND FL NORTH, NE ROOM	0	0	0
FC571-06-22tem	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	2ND FL NORTH, NE ROOM	0	0	0
FC571-06-23	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	5/18/2010	2ND FL SOUTH, SW ROOM	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC571-06-24	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	5/18/2010	3RD FL SOUTH, SE ROOM	0	0	0
FC571-06-24tem	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	5/18/2010	3RD FL SOUTH, SE ROOM	0	0	0
FC571-06-25	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	5/18/2010	3RD FL NORTH, NW ROOM	0	0	0
FC525-07-11	07	DUCT SEALANT, RED		7/18/2002	1ST FL MECH ROOM FC525	0	0	0
FC525-08-12	08	MUDDERED FITTING(S)		7/18/2002	1ST FL MECH ROOM FC525	0	0	0
FC525-08-13	08	MUDDERED FITTING(S)		7/18/2002	3RD FL MECH ROOM FC525	0	0	0
FC525-09-14	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC525-09-15	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC571-09-1110	09	TEXTURED CEILING MATERIAL		9/20/2005	1ST FL LAUNDRY	0	0	0
FC571-09-1310	09	TEXTURED CEILING MATERIAL		9/20/2005	2ND FL WEST CNTR RM	0	0	0
FC571-09-20	09	TEXTURED CEILING MATERIAL		5/18/2010	1ST FL SOUTH, SE ROOM	0	0	0
FC571-09-21	09	TEXTURED CEILING MATERIAL		5/18/2010	1ST FL NORTH, NW ROOM	0	0	0
FC571-09-22	09	TEXTURED CEILING MATERIAL		5/18/2010	2ND FL NORTH, NE ROOM	0	0	0
FC571-09-23	09	TEXTURED CEILING MATERIAL		5/18/2010	2ND FL SOUTH, SW ROOM	0	0	0
FC571-09-24	09	TEXTURED CEILING MATERIAL		5/18/2010	3RD FL SOUTH, SE ROOM	0	0	0
FC571-09-25	09	TEXTURED CEILING MATERIAL		5/18/2010	3RD FL NORTH, NW ROOM	0	0	0
FC525-10-10	10	12" CREAM FLOOR TILE AND ADHESIVE		9/20/2005	1ST FL CNTR HALL	0	0	0
FC555-11-10	11	EXTERIOR CAULKING,	GRAY	9/20/2005	DOORS	0	0	0
FC571-11-20	11	EXTERIOR CAULKING,	GRAY	5/18/2010	2ND FL SOUTH, EAST MR DOOR	0	0	0
FC571-11-21	11	EXTERIOR CAULKING,	GRAY	5/18/2010	2ND FL EAST CNTR BRICK JOINT	0	0	0

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC571-11-22	11	EXTERIOR CAULKING, GRAY	5/18/2010	3RD FL EAST CNTR BRICK JOINT	0	0	0
FC571-12-10	12	DUCT SEALANT, GRAY	9/20/2005	PIPE CHASE	0	0	0
FC571-12-20	12	DUCT SEALANT, GRAY	5/18/2010	2ND FL SOUTH CHASE, SOUTH	0	0	0
FC571-12-21	12	DUCT SEALANT, GRAY	5/18/2010	3RD FL NORTH CHASE, NORTH	0	0	0
FC571-20-20	20	DUCT SEALANT, TAN	5/18/2010	1ST FL SOUTH MECH RM	0	0	0
FC571-20-21	20	DUCT SEALANT, TAN	5/18/2010	3RD FL NORTH MECH RM	0	0	0
FC571-21-20	21	DUCT SEALANT, WHITE	5/18/2010	1ST FL SOUTH MECH RM	0	0	0
FC571-21-21	21	DUCT SEALANT, WHITE	5/18/2010	3RD FL NORTH MECH RM	0	0	0
FC571-22-20	22	CLOTH EXPANSION JOINT MATERIAL, THIN BLACK	5/18/2010	1ST FL SOUTH MECH RM	0	0	0
FC571-22-21	22	CLOTH EXPANSION JOINT MATERIAL, THIN BLACK	5/18/2010	3RD FL NORTH MECH RM	0	0	0
FC571-23-20	23	DRYWALL AND JOINT MATERIAL	5/18/2010	1ST FL SOUTH, SE ROOM	0	0	0
FC571-23-21	23	DRYWALL AND JOINT MATERIAL	5/18/2010	1ST FL NORTH, NW ROOM	0	0	0
FC571-23-22	23	DRYWALL AND JOINT MATERIAL	5/18/2010	2ND FL NORTH, NE ROOM	0	0	0
FC571-23-23	23	DRYWALL AND JOINT MATERIAL	5/18/2010	2ND FL SOUTH, SW ROOM	0	0	0
FC571-23-24	23	DRYWALL AND JOINT MATERIAL	5/18/2010	3RD FL SOUTH, SE ROOM	0	0	0
FC571-23-25	23	DRYWALL AND JOINT MATERIAL	5/18/2010	3RD FL NORTH, NW ROOM	0	0	0
FC571-24-20	24	LAGGING PAPER ON FIBERGLASS	5/18/2010	1ST FL NORTH MECH ROOM	0	0	0
FC571-25-00ri13	25	ROOFING SEALANT, GRAY	12/9/2013	N/A	9	9	9
FC571-25-00ri16	25	ROOFING SEALANT, GRAY	6/9/2016	N/A	9	9	9
FC571-25-00ri19	25	ROOFING SEALANT, GRAY	9/18/2019	N/A	9	9	9

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC571-25-00ri23	25	ROOFING SEALANT, GRAY		3/28/2023	N/A	9	9	9
FC571-25-20	25	ROOFING SEALANT, GRAY		5/18/2010	ATTIC/ ROOF, NORTH CNTR	0	0	0
FC571-25-21	25	ROOFING SEALANT, GRAY		5/18/2010	ATTIC/ ROOF, SOUTH CNTR	5	0	0
FC571-26-20	26	ROOFING SEALANT, BLACK		5/18/2010	ATTIC/ ROOF, NORTH CNTR	0	0	0
FC571-26-21	26	ROOFING SEALANT, BLACK		5/18/2010	ATTIC/ ROOF, SOUTH CNTR	0	0	0
FC571-27-20	27	TAR PAPER, BLACK		5/18/2010	ATTIC/ ROOF, NORTH CNTR	0	0	0
FC571-27-21	27	TAR PAPER, BLACK		5/18/2010	ATTIC/ ROOF, SOUTH CNTR	0	0	0
FC571-27-40	27	TAR PAPER, BLACK		9/18/2019	ATTIC, NO. CNTR UNDERLAYMENT	0	0	0
FC571-28-20	28	BUILT-UP ROOFING	BLACK	5/18/2010	ATTIC/ ROOF, NORTH CNTR	0	0	0
FC571-28-21	28	BUILT-UP ROOFING	BLACK	5/18/2010	ATTIC/ ROOF, SOUTH CNTR	0	0	0
FC571-30-00ri16	30	RESIDUAL MASTIC	BLACK	6/9/2016	N/A	9	9	9
FC571-30-00ri19	30	RESIDUAL MASTIC	BLACK	9/18/2019	N/A; 2ND FL NE	9	9	9
FC571-30-00ri23	30	RESIDUAL MASTIC	BLACK	3/28/2023	N/A	9	9	9
FC571-30-30	30	RESIDUAL MASTIC	BLACK	12/9/2013	2ND FL, NE ROOM DOORWAY	2	0	0
FC571-30-40	30	RESIDUAL MASTIC	BLACK	9/18/2019	2ND FL, NO. EAST CNTR	0	0	0
FC571-30-41	30	RESIDUAL MASTIC	BLACK	9/18/2019	3RD FL, SO. WEST CNTR	0	0	0