

**BLADE RADIO REPAIR
STATEMENT OF WORK
28 January 2026**

1. **SCOPE:** Tear down, evaluate, repair and deliver the RT-4110 Blade Radio, (P/N 270-3186-070) to the Utah Test and Training Range (UTTR) Hill Air Force Base, Utah.
2. **GENERAL INFORMATION:** The Utah Test and Training Range (UTTR) utilizes the RT-4110 Blade Radio to support its Air Traffic Control Stations; the radio is a Ground to Air Safety of Flight Item.
 - 2.1 **DELIVERY:** Delivery shall be made to: Utah Test and Training Range (UTTR) 5948 Southgate Road Bldg. 1A. Hill AFB, Utah 84056.
 - 2.2. **HOURS OF OPERATION:** Contractor deliveries will be performed during the following hours: Normal duty hours, which are currently 7:00 A.M. to 4:00 P.M., Monday through Friday, excluding holidays and weekends. All deliveries shall be scheduled with UTTR personnel outlined in this SOW. A minimum of 24 hours' notice is required prior to delivery.
 - 2.3 **EMPLOYEES:** The Government reserves the right to restrict access of any contractor employee, or prospective contractor employee, who is identified as a potential threat to the health, general well-being, safety, security, or operational mission of the installation and its population. A security forces background check will be performed prior to access.
3. **PERIOD OF PERFORMANCE:** Delivery within 120 days of contract award.
4. **REQUIREMENTS:** The contractor shall provide all labor, materials, equipment, and transportation necessary to repair and deliver RT-4110 Blade Radio(s).
5. **REPORTS:** The contract number and delivery date must be clearly visible on all invoices and delivery documents.
6. **POC:** HQ UTTR/A4LL
5948 Southgate Road
Bldg. 1A
Hill AFB, UT 84056
Katie Connelly 801-777-5393
Adam Brown 801-777-2355