

ASBESTOS INSPECTION REPORT of:

Building # FC525

MCB CAMP LEJEUNE



Print Date

Thursday, March 19, 2026

INSPECTION SUMMARY

BLDG #: FC525

YEAR BUILT: 1978

OCCUPANT: BEQ- 2ND SUPPLY

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 3/GREEN [AH MAY2022]
ACM SEALANT AT OLD SHOWER PANS IN MECHANICAL SPACES

SEPT2019
LIMITED ACM REMAINS

JUN2016
ACM REMAINS, ADDL SAMPLING, NO ADDL ACM I'D

DEC2013
ACM TILE AND MASTIC REMAIN, ADDL SAMPLING, ACM INCLUDES:
LIGHT HEAT SHIELDING

NOV2011
PVS. ACM REMAINS

NOV08/ APR09
PVS. ACM TILE REMAINS, VERIFIED TEM, ADDL SAMPLING, ACM INCLUDES:
MISCELLANEOUS SEALANT, BLACK
ROOFING SEALANTS, BLACK

SEP05
PVS. ACM TILE AND MASTIC REMAIN

JUL02 AES
ACM INCLUDES:
12" BEIGE FLOOR TILE AND MASTIC

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
--------------------	-----------------	-------------	-----------------

No friable ACM records found in database

Non-friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
--------------------	-----------------	-------------	-----------------

MISCELLANEOUS SEALANT	UNDER SHOWER STALLS, ACCESSIBLE AT MECHANICAL ROOM CONVERSIONS, LIKELY PRESENT AT ALL SHOWER UNITS	11/4/2008	332 SF
ROOFING MATERIAL,	ROOFING PERIMETER, UNDER EXISTING ON DECK AND SIDEWALL	5/10/2022	

MISCELLANEOUS SEALANT	UNDER SHOWER STALLS AT MECHANICAL ROOMS ONLY	9/17/2019	18 SF
MISCELLANEOUS SEALANT	UNDER SHOWER STALLS, ACCESSIBLE AT MECHANICAL ROOM CONVERSIONS, LIKELY PRESENT AT ALL SHOWER UNITS	11/8/2011	332 SF
MISCELLANEOUS SEALANT	UNDER SHOWER STALLS, ACCESSIBLE AT MECHANICAL ROOM CONVERSIONS, LIKELY PRESENT AT ALL SHOWER UNITS	12/2/2013	332 SF
MISCELLANEOUS SEALANT	UNDER SHOWER STALLS, ACCESSIBLE AT MECHANICAL ROOM CONVERSIONS, LIKELY PRESENT AT ALL SHOWER UNITS	6/9/2016	332 SF

Tested Non ACM or REMOVED Materials

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>
ROOFING SEALANT, BLACK	ROOF, BUCKET OF USED ROOF SEALANT, CENTER SOUTH (SEE ALSO HM28)	11/4/2008
12" BEIGE FLOOR TILE AND ADHESIVE	THIRD FLOOR LOUNGE (SEE ALSO HM03)	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER HM01, 02)	7/18/2002
12" WHITE FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES w/HM01	7/18/2002
JOINT MATERIAL	WALLS AND CEILINGS AT HEAD AREAS THROUGHOUT	11/4/2008
MUDDER FITTING(S)	MECHANICAL ROOMS AND PIPE CHASES, END CAPPING ON FIBERGLASS LINES	7/18/2002
PIPE INSULATION	DORM ROOM HEADS AND PIPE CHASES	11/4/2008
MISCELLANEOUS SEALANT	MECHANICAL ROOMS AND PIPE CHASES AT PIPE AND CONDUIT PENETRATIONS	4/15/2009
BUILT-UP ROOFING	ROOFING SYSTEM, PERIMETER PARAPET WALLS	11/4/2008
DUCT SEALANT, RED	MECHANICAL ROOMS AND PIPE CHASES	7/18/2002
GASKET MATERIAL	PIPE CHASES AND MECHANICAL ROOMS	9/20/2005
INTERIOR CAULKING,	CEILINGS AT PERIMETER AND CENTER JOINTS; BLOCK WALL JOINTS	11/4/2008
CONCRETE EXPANSION JOINT MATERIAL	AROUND EXTERIOR DECKING, HOMOGENOUS BUILDING GROUP	9/20/2005
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE UNDER CARPETING (SEE ALSO HM03)	7/18/2002
INTERIOR CAULKING,	METAL DOORS	11/4/2008

2'x2' CEILING TILE,	CENTRAL OFFICES, LOUNGES	7/18/2002
ROOFING SEALANT, BLACK	ROOF, CENTER VENT FLASHINGS	11/4/2008
BUILT-UP ROOFING	ROOFING SYSTEM MAIN MEMBRANE	11/4/2008
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	7/18/2002
12" BLACK FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES w/HM02	7/18/2002
EXTERIOR CAULKING,	EXTERIOR BRICK WALL EXPANSION JOINTS (w/HM25)	11/4/2008
DUCT SEALANT, GRAY	CHASES AND ATTIC/ OLD ROOF DUCTS THROUGHOUT HOMOGENOUS BUILDING GROUPS	9/20/2005
EXTERIOR CAULKING,	BRICK EXPANSION JOINTS AND BLOCK CORNER JOINTS THROUGHOUT (SEE ALSO HM24, 25)	4/15/2009
CLOTH LAGGING MATERIAL	PIPE CHASES AND MECHANICAL ROOMS	9/20/2005
EXTERIOR CAULKING,	METAL DOORS TO MECHANICAL ROMS AND CHASES THROUGHOUT	9/20/2005
LIGHT FIXTURE HEAT SHIELD	CENTER HALL GEAR LOCKERS, ALL THREE FLOORS	12/2/2013
ROOFING SEALANT, GRAY	[NEW] ROLLED ROOF SEAMS AT PARAPET WALL AND CENTER VENT FLASHINGS	11/8/2011
DUCT SEALANT, RED	PIPE CHASE AND HEAD VENT DUCTS	11/8/2011
CLOTH LAGGING MATERIAL	DOMESTIC HOT LINE PATCHING IN PIPE CHASES	11/8/2011
EXTERIOR CAULKING,	EXTERIOR BRICK WALL EXPANSION JOINTS (w/HM24)	11/4/2008
ADHESIVE	ROOM HEADS, TILE WALLS	11/4/2008
ROOFING SEALANT, BLACK	ROOF, NORTH END DEBRIS AND PATCHING PILE (SEE ALSO HM31)	11/4/2008
FIBERGLASS INSULATION SEALANT	ATTIC, NEW EQUIPMENT	5/10/2022
TEXTURED CEILING MATERIAL	MECHANICAL ROOMS	5/10/2022
CAULKING MATERIAL	MECHANICAL ROOMS AT FORMER WALL LOCATIONS	5/10/2022
MISCELLANEOUS SEALANT	MECHANICAL CENTER CHASES	5/10/2022
ROPE PACKING MATERIAL	CENTRAL CHASES AT DRAIN LINES	6/9/2016
DUCT SEALANT, RED	CENTRAL CHASES ON BATH EXHAUST FAN DUCTING	6/9/2016
12" BEIGE FLOOR TILE AND ADHESIVE	3RD FLOOR LOUNGE	11/4/2008
12" BEIGE FLOOR TILE AND ADHESIVE	THIRD FLOOR LOUNGE (SEE ALSO HM03)	9/20/2005
12" BEIGE FLOOR TILE AND ADHESIVE	PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER HM01, 02)	11/8/2011
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE UNDER CARPETING (SEE ALSO HM03)	11/4/2008

12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	11/4/2008
12" BEIGE FLOOR TILE AND ADHESIVE	PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER HM01, 02)	9/20/2005
12" BEIGE FLOOR TILE AND ADHESIVE	PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER HM01, 02)	12/2/2013
ROOFING SEALANT, BLACK	ROOF, CENTER VENT FLASHINGS	12/2/2013
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE UNDER CARPETING (SEE ALSO HM03)	9/20/2005
LIGHT FIXTURE HEAT SHIELD	CENTER HALL GEAR LOCKERS, ALL THREE FLOORS	6/9/2016
12" BEIGE FLOOR TILE AND ADHESIVE	PRIMARY TILE THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER HM01, 02)	6/9/2016

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-01-01	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC525-01-02	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC525-02-03	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC525-02-04	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC252-03-30tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	11/8/2011	1ST FL WEST CNTR OFFICE	9.1	0	0
FC525-03-00ri05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/21/2005	N/A	9	9	9
FC525-03-00ri13	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	12/2/2013	N/A	9	9	9
FC525-03-00ri16	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	6/9/2016	N/A	9	9	9
FC525-03-05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC525-03-06	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC525-03-20	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	SE DORM ROOM	2	0	0
FC525-03-21	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	NW DORM RM	2	0	0
FC525-03-21tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	NW DORM RM	6.2	0	0
FC525-03-22	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	2ND FL, NW DORM RM	2	0	0
FC525-03-23	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	2ND FL EAST, CNTR DORM RM	5	0	0
FC525-03-23tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	2ND FL EAST, CNTR DORM RM	34.5	0	0
FC525-03-24	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	3RD FL, NW DORM RM	33.4	0	0
FC525-03-24	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	4/15/2009	3RD FL, NW DORM RM	5	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-03-25	03	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE I	4/15/2009	3RD FL NE DORM RM	5	0	0
FC525-03-30	03	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE I	11/8/2011	1ST FL WEST CNTR OFFICE	3	0	0
FC525-04-07	04	2'x2' CEILING TILE,		7/18/2002	1ST FL LOUNGE	0	0	0
FC525-04-08	04	2'x2' CEILING TILE,		7/18/2002	1ST FL LOUNGE	0	0	0
FC525-05-00ri05	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	9/21/2005	N/A	9	9	9
FC525-05-00ri07	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	11/4/2008	N/A	9	9	9
FC525-05-09	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	7/18/2002	2ND FL LOUNGE UNDER CARPET	10	0	0
FC525-06-00ri05	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	9/21/2005	N/A	9	9	9
FC525-06-00ri07	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	11/4/2008	N/A	9	9	9
FC525-06-10	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	7/18/2002	THIRD FLOOR LOUNGE	10	0	0
FC525-07-11	07	DUCT SEALANT, RED		7/18/2002	1ST FL NORTH MECH RM	0	0	0
FC525-07-12	07	DUCT SEALANT, RED		7/18/2002	1ST FL NORTH MECH RM	0	0	0
FC525-08-12	08	MUDDERED FITTING(S)		7/18/2002	1ST FL MECH RM	0	0	0
FC525-08-12	08	MUDDERED FITTING(S)		7/18/2002	1ST FL MECH RM	0	0	0
FC525-08-13	08	MUDDERED FITTING(S)		7/18/2002	3RD FL NORTH CHASE	0	0	0
FC525-09-14	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL SOUTH, NE OFFICE	0	0	0
FC525-09-15	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL SOUTH, NE OFFICE	0	0	0
FC525-10-00	10	CLOTH LAGGING MATERIAL	BLUE/WHITE RUBBERY	9/20/2005	1ST FL HEAD, FC555	0	0	0
FC525-11-00	11	EXTERIOR CAULKING,	GRAY	9/20/2005	SW, FC555	0	0	0
FC525-12-00	12	DUCT SEALANT, GRAY		9/20/2005	CHASE, FC555	0	0	0
FC525-13-00	13	GASKET MATERIAL		9/20/2005	FC565	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-14-00	14	CONCRETE EXPANSION JOINT MATERIAL	GRAY	9/20/2005	CENTER OFFICE, FC555	0	0	0
FC525-14-10	14	CONCRETE EXPANSION JOINT MATERIAL	GRAY	9/20/2005	ROOM 216, BUILDING 565	0	0	0
FC525-20-20	20	INTERIOR CAULKING,	GRAY	11/4/2008	1ST FL SOUTH, NW OFFICE DOOR	0	0	0
FC525-20-21	20	INTERIOR CAULKING,	GRAY	11/4/2008	2ND FL SOUTH CHASE, SOUTH DOOR	0	0	0
FC525-21-00ri11	21	MISCELLANEOUS SEALANT	BLACK	11/8/2011	N/A	9	9	9
FC525-21-00ri13	21	MISCELLANEOUS SEALANT	BLACK	12/2/2013	N/A	9	9	9
FC525-21-00ri16	21	MISCELLANEOUS SEALANT	BLACK	6/9/2016	N/A	9	9	9
FC525-21-00ri19	21	MISCELLANEOUS SEALANT	BLACK	9/17/2019	N/A	9	9	9
FC525-21-20	21	MISCELLANEOUS SEALANT	BLACK	11/4/2008	1ST FL SOUTH, EAST MECH RM	5	0	0
FC525-22-20	22	INTERIOR CAULKING,	WHITE	11/4/2008	1ST FL SOUTH, EAST MECH RM	0	0	0
FC525-22-21	22	INTERIOR CAULKING,	WHITE	11/4/2008	2ND FL SOUTH CHASE	0	0	0
FC525-22-22	22	INTERIOR CAULKING,	WHITE	11/4/2008	3RD FL SOUTH, EAST MECH RM	0	0	0
FC525-23-20	23	JOINT MATERIAL		11/4/2008	1ST FL SOUTH, SE RM	0	0	0
FC525-23-21	23	JOINT MATERIAL		11/4/2008	1ST FL NORTH, NE RM	0	0	0
FC525-23-22	23	JOINT MATERIAL		11/4/2008	2ND FL NORTH, NW RM	0	0	0
FC525-23-23	23	JOINT MATERIAL		11/4/2008	2ND FL SOUTH, SW RM	0	0	0
FC525-23-24	23	JOINT MATERIAL		11/4/2008	2ND FL SOUTH, NE RM	0	0	0
FC525-23-25	23	JOINT MATERIAL		11/4/2008	3RD FL NORTH, NW RM	0	0	0
FC525-23-26	23	JOINT MATERIAL		11/4/2008	3RD FL SOUTH, SW RM	0	0	0
FC525-23-27	23	JOINT MATERIAL		11/4/2008	3RD FL SOUTH, NE RM	0	0	0
FC525-23-28	23	JOINT MATERIAL		11/4/2008	3RD FL NORTH, NE RM	0	0	0
FC525-24-20	24	EXTERIOR CAULKING,	GRAY	11/4/2008	2ND FL EAST CNTR	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-25-20	25	EXTERIOR CAULKING,	WHITE	11/4/2008	2ND FL EAST CNTR	0	0	0
FC525-26-20	26	PIPE INSULATION		11/4/2008	3RD FL NORTH WING, NW	0	0	0
FC525-27-20	27	ADHESIVE	BEIGE	11/4/2008	3RD FL NORTH, EAST MR	0	0	0
FC525-28-20	28	ROOFING SEALANT,	BLACK	11/4/2008	ROOF, NORTH CNTR	10	0	0
FC525-29-20	29	ROOFING SEALANT,	BLACK	11/4/2008	ROOF, CNTR NORTH VENT	10	0	0
FC525-29-40	29	ROOFING SEALANT,	BLACK	12/2/2013	SOUTH ROOF	0	0	0
FC525-29-41	29	ROOFING SEALANT,	BLACK	12/2/2013	NORTH ROOF	0	0	0
FC525-30-20	30	BUILT-UP ROOFING		11/4/2008	ROOF, CNTR SOUTH	0	0	0
FC525-31-20	31	ROOFING SEALANT,	BLACK	11/4/2008	ROOF, CNTR SOUTH	10	0	0
FC525-32-20	32	BUILT-UP ROOFING		11/4/2008	ROOF, EAST CNTR	0	0	0
FC525-33-20	33	MISCELLANEOUS SEALANT	RED	4/15/2009	3RD FLR, NE MECH ROOM	0	0	0
FC525-34-20	34	EXTERIOR CAULKING,	BEIGE	4/15/2009	2ND FLR CNTR STAIRS	0	0	0
FC525-34-21	34	EXTERIOR CAULKING,	BEIGE	4/15/2009	1ST FLR, EAST CENTER	0	0	0
FC525-40-30	40	ROOFING SEALANT,	GRAY	11/8/2011	ROOF, PARAPET NW	0	0	0
FC525-41-30	41	DUCT SEALANT, RED		11/8/2011	3RD FL NORTH CHASE	0	0	0
FC525-41-31	41	DUCT SEALANT, RED		11/8/2011	2ND FL SOUTH CHASE	0	0	0
FC525-42-30	42	CLOTH LAGGING MATERIAL	THIN	11/8/2011	3RD FL NORTH CHASE	0	0	0
FC525-42-31	42	CLOTH LAGGING MATERIAL	THIN	11/8/2011	2ND FL SOUTH CHASE	0	0	0
FC525-50-00ri16	50	LIGHT FIXTURE HEAT SHIELD	SILVER	6/9/2016	N/A	9	9	9
FC525-50-40	50	LIGHT FIXTURE HEAT SHIELD	SILVER	12/2/2013	1ST FL CNTR HALL GEAR LOCKER	60	0	0
FC525-50-41	50	LIGHT FIXTURE HEAT SHIELD	SILVER	12/2/2013	3RD FL CNTR HALL GEAR LOCKER	60	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC525-51-60	51	FIBERGLASS INSULATION SEALANT	BEIGE	5/10/2022	ATTIC, NORTH CNTR	0	0	0
FC525-52-60	52	TEXTURED CEILING MATERIAL		5/10/2022	MECH RM, 1 SOUTH	0	0	0
FC525-52-61	52	TEXTURED CEILING MATERIAL		5/10/2022	MECH RM, 2 SOUTH	0	0	0
FC525-53-60	53	CAULKING MATERIAL	BEIGE	5/10/2022	MECH RM, 1 NORTH	0	0	0
FC525-54-60	54	MISCELLANEOUS SEALANT	FIRESTOP, BROWN	5/10/2022	CHASE, 3 NORTH	0	0	0
FC525-55-50	55	ROPE PACKING MATERIAL		6/9/2016	1ST FL SOUTH CHASE	0	0	0
FC525-55b-60	55b	ROOFING MATERIAL,	UNDERLAYMENT	5/10/2022	ROOF, NORTH CNTR	10	0	0
FC525-56-50	56	DUCT SEALANT, RED		6/9/2016	1ST FL SOUTH CNTR CHASE	0	0	0