

ASBESTOS INSPECTION REPORT of:

Building # FC573

MCB CAMP LEJEUNE



Print Date

Thursday, March 19, 2026

INSPECTION SUMMARY

BLDG #: FC573

YEAR BUILT: 1986

OCCUPANT: BEQ- BARRACKS BUILDING

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 3/GREEN [MAR2023]
RESIDUAL MASTIC

MAR2023
ACM REMAINS

SEPT2019
NO CHANGES, ADDL SAMPLES

JUN2016
ACM REMAINS

DEC2013
PVS. ACM REMAINS, ADDL SAMPLING, ACM INCLUDES:
RESIDUAL MASTIC

JAN2012
PVS. ACM ROOFING SEALANT REMAINS, ADDL SAMPLING, NO ADDL ACM ID'D

JAN2011
PVS. TILE/ MASTIC REMOVED, ADDL SAMPLING, NO ADDL ACM IDENTIFIED, ACM ROOFING MAT'L REMAINS

NOV08
NO CHANGES FROM PREVIOUS, ADDL SAMPLING, ACM INCLUDES:
FLOOR TILE AND MASTIC
ROOFING SEALANTS

SEP05:
ACM TILE AND MASTIC REMAINS
DATA FROM HOMOGENOUS BUILDINGS ADDED

INSPECT JUL02 AES
NON FRIABLE ACM IDENTIFIED INCLUDES:
12" BEIGE FLOOR TILE AND ADHESIVE, MULTIPLE TYPES

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
---------------------------	------------------------	--------------------	------------------------

No friable ACM records found in database

Non-friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
---------------------------	------------------------	--------------------	------------------------

RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	12/9/2013	2 SF
-----------------	---	-----------	------

RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	9/18/2019	2 SF
RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	6/9/2016	3 SF
RESIDUAL MASTIC	REMNANTS OF HM01 MASTIC AT "NEW" DOORWAYS TO ROOMS; POTENTIAL UNDER NEW FLOORING THROUGHOUT	3/28/2023	2 SF

Tested Non ACM or REMOVED Materials

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>
ROOFING SEALANT, BLACK	FLAT ROOF, PATCHING (SEE ALSO HM30)	11/6/2008
ROOFING SEALANT, BLACK	FLAT ROOF, BUCKET OF SEALANT, CENTER NEAR ACCESS	11/6/2008
12" BLACK FLOOR TILE AND ADHESIVE JOINT MATERIAL	CENTRAL LOUNGES WALLS THROUGHOUT	7/18/2002 11/6/2008
ROOFING SEALANT, GRAY	FLAT ROOF, PERIMETER FLASHINGS	11/6/2008
MISCELLANEOUS SEALANT	MECHANICAL ROOMS AND CHASES AT PIPE PENETRATIONS	11/6/2008
CARPET ADHESIVE	CENTRAL LOUNGES AND OFFICE AREAS	11/6/2008
ROOFING SEALANT, BLACK	FLAT ROOF, ROOF VENTS	11/6/2008
ROOFING MATERIAL,	FLAT ROOF, PATCHING	11/6/2008
DUCT SEALANT, BROWN	MECHANICAL ROOMS	11/6/2008
MISCELLANEOUS SEALANT	MECHANICAL ROOMS, HVAC DUCTS	11/6/2008
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE UNDER CARPET (SEE ALSO HM03)	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	THIRD FLOOR LOUNGE (SEE ALSO HM03)	7/18/2002
EXTERIOR CAULKING,	EXTERIOR BRICK EXPANSION JOINTS	11/6/2008
INTERIOR CAULKING,	ROOM VANITIES, LAUNDRY ROOM FAN	11/6/2008
ROOFING SEALANT, BLACK	FLAT ROOF, WALKWAY PADS	11/6/2008
2'x2' CEILING TILE,	OFFICES, LOUNGES	7/18/2002
PITCH POCKET TAR	FLAT ROOF, PITCH POCKET SOUTH CENTER	11/6/2008
MEMBRANE-TYPE ROOFING	FLAT ROOF, PERIMETER FLASHINGS	11/6/2008
BROWN VINYL BASE AND ADHESIVE, 4"	DORM ROOMS w/HM03 TILES THROUGHOUT	11/6/2008
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	7/18/2002
MUDDDED FITTING(S)	MECHANICAL ROOMS, PIPE CHASES	7/18/2002

DUCT SEALANT, GRAY	CHASES AND ATTIC/ OLD ROOF DUCTS THROUGHOUT HOMOGENOUS BUILDINGS	9/20/2005
TEXTURED CEILING MATERIAL	THROUGHOUT HOMOGENOUS BUILDINGS	9/20/2005
CONCRETE EXPANSION JOINT MATERIAL	AROUND EXTERIOR DECKING OF HOMOGENOUS BUILDINGS	9/20/2005
MISCELLANEOUS SEALANT	CENTRAL PIPE CHASES AT CONDUIT/ CABLE PENETRATIONS	11/6/2008
ROOFING SEALANT, BLACK	PATCHING AT ROOF DRAINS AND UNDERCOATING TO MAIN [OLD] ROOF MEMBRANE	1/19/2012
CLOTH LAGGING MATERIAL	THROUGHOUT THIS AND HOMOGENOUS BUILDINGS IN CHASE	9/20/2005
EXTERIOR CAULKING,	DOORS TO CHASES THROUGHOUT	9/20/2005
MISCELLANEOUS SEALANT	MECHANICAL ROOMS AND PIPE CHASES AT CABLE/ CONDUIT/ PIPING PENETRATIONS	1/19/2012
DUCT SEALANT, RED	MECHANICAL ROOMS, PIPE CHASES	7/18/2002
12" WHITE FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	7/18/2002
DUCT SEALANT, GRAY	INTERNAL DUCT LINING, MECHANICAL ROOM CHASES	11/6/2008
12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE	REPLACEMENT OF HM03, 05, 06 TILES THROUGHOUT	1/6/2011
ROOFING SEALANT, BLACK	FLAT ROOF, BUCKET OF SEALANT, CENTER NEAR ACCESS	9/18/2019
12" BEIGE FLOOR TILE AND ADHESIVE		9/21/2005
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	9/20/2005
12" BEIGE FLOOR TILE AND ADHESIVE	3RD FLOOR LOUNGE	11/6/2008
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	11/6/2008
ROOFING SEALANT, GRAY	FLAT ROOF (NOW ATTIC), PERIMETER FLASHINGS	1/6/2011
MEMBRANE-TYPE ROOFING	FLAT ROOF (NOW ATTIC), PERIMETER FLASHINGS	1/6/2011
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	9/24/2009
ROOFING SEALANT, BLACK	FLAT ROOF (NOW ATTIC), BUCKET OF SEALANT, CENTER NEAR ACCESS/ PATCHING FROM BUCKET	1/6/2011
ROOFING SEALANT, BLACK	FLAT ROOF (NOW ATTIC), PATCHING (SEE ALSO HM30)	1/6/2011

ROOFING SEALANT, BLACK	FLAT ROOF, PATCHING (SEE ALSO HM30)	12/9/2013
12" BEIGE FLOOR TILE AND ADHESIVE	2ND FLOOR LOUNGE (UNDER CARPET)	11/6/2008
ROOFING SEALANT, BLACK	FLAT ROOF, PATCHING (SEE ALSO HM30)	1/19/2012
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE UNDER CARPET (SEE ALSO HM03)	9/20/2005
ROOFING SEALANT, BLACK	FLAT ROOF, PATCHING (SEE ALSO HM30)	6/9/2016
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	1/6/2011

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-01-01	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC573-01-02	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC573-02-03	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC573-02-04	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC573-03-00ri05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/21/2005	N/A	9	9	9
FC573-03-00ri07	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	11/6/2008	N/A	9	9	9
FC573-03-05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC573-03-06	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC573-03-20	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	1ST FL NORTH, CNTR EAST RM	3	0	0
FC573-03-20tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	1ST FL NORTH, CNTR EAST RM	0	0	0
FC573-03-21	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	2ND FL NORTH, NW RM	3	0	0
FC573-03-21tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	2ND FL NORTH, NW RM	0	0	0
FC573-03-22	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	3RD FL NORTH, NE RM	3	0	0
FC573-03-22tem	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	3RD FL NORTH, NE RM	0	0	0
FC573-03-23	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2010	3RD FL SOUTH, SW RM	0	0	0
FC573-03-24	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	2ND FL SOUTH, SE RM	3	0	0
FC573-03-25	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/24/2009	1ST FL SOUTH, SW RM	3	0	0
FC573-04-07	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE	0	0	0
FC573-04-08	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-05-00ri05	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	9/21/2005	N/A	9	9	9
FC573-05-00ri07	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	11/6/2008	N/A	9	9	9
FC573-05-09	05	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE II	7/18/2002	2ND FL LOUNGE UNDER CARPET	10	0	0
FC573-06-00ri05	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	9/21/2005	N/A	9	9	9
FC573-06-00ri07	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	11/6/2008	N/A	9	9	9
FC573-06-10	06	12" BEIGE FLOOR TILE AND ADHESIVE	TYPE III	7/18/2002	3RD FL LOUNGE	10	0	0
FC573-07-11	07	DUCT SEALANT, RED		7/18/2002	1ST FL MR	0	0	0
FC573-08-12	08	MUDDERED FITTING(S)		7/18/2002	1ST FL MR	0	0	0
FC573-08-13	08	MUDDERED FITTING(S)		7/18/2002	1ST FL MR	0	0	0
FC573-09-14	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC573-09-15	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC573-09-30	09	TEXTURED CEILING MATERIAL		1/6/2011	1ST FL WEST CNTR LAUNDRY	0	0	0
FC573-09-31	09	TEXTURED CEILING MATERIAL		1/6/2011	1ST FL NORTH, NW RM	0	0	0
FC573-09-32	09	TEXTURED CEILING MATERIAL		1/6/2011	1ST FL SOUTH, SE RM	0	0	0
FC573-09-33	09	TEXTURED CEILING MATERIAL		1/6/2011	2ND FL NORTH, NE RM	0	0	0
FC573-09-34	09	TEXTURED CEILING MATERIAL		1/6/2011	2ND FL SOUTH, SW RM	0	0	0
FC573-09-35	09	TEXTURED CEILING MATERIAL		1/6/2011	3RD FL NORTH, NE RM	0	0	0
FC573-09-36	09	TEXTURED CEILING MATERIAL		1/6/2011	3RD FL SOUTH, SW RM	0	0	0
FC573-10-10	10	CLOTH LAGGING MATERIAL	BLUE/ WHITE RUBBERY	9/20/2005	1ST FL LOUNGE	0	0	0
FC573-11-10	11	EXTERIOR CAULKING, GRAY		9/20/2005	SW RESTROOM	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-12-10	12	DUCT SEALANT, GRAY		9/20/2005	CHASE	0	0	0
FC573-13-10	13	TEXTURED CEILING MATERIAL		9/20/2005	1ST FL OFFICE	0	0	0
FC573-14-10	14	CONCRETE EXPANSION JOINT MATERIAL	GRAY	9/20/2005	CENTER OFFICE ENTRY	0	0	0
FC573-20-20	20	MISCELLANEOUS SEALANT	FIRESTOP, PINK	11/6/2008	CNTR NORTH CHASE	0	0	0
FC573-21-20	21	JOINT MATERIAL		11/6/2008	1ST FL NE ROOM	0	0	0
FC573-21-21	21	JOINT MATERIAL		11/6/2008	1ST FL WE CNTR ROOM	0	0	0
FC573-21-22	21	JOINT MATERIAL		11/6/2008	1ST FL SE ROOM	0	0	0
FC573-21-23	21	JOINT MATERIAL		11/6/2008	2ND FL NW ROOM	0	0	0
FC573-21-24	21	JOINT MATERIAL		11/6/2008	2ND FL SW ROOM	0	0	0
FC573-21-25	21	JOINT MATERIAL		11/6/2008	2ND FL EA CNTR ROOM	0	0	0
FC573-21-26	21	JOINT MATERIAL		11/6/2008	3RD FL EA CNTR ROOM	0	0	0
FC573-21-27	21	JOINT MATERIAL		11/6/2008	3RD FL SE ROOM	0	0	0
FC573-21-28	21	JOINT MATERIAL		11/6/2008	3RD FL NE ROOM	0	0	0
FC573-22-20	22	DUCT SEALANT, BROWN		11/6/2008	1ST FL SOUTH MECH RM	0	0	0
FC573-22-21	22	DUCT SEALANT, BROWN		11/6/2008	3RD FL NORTH MECH RM	0	0	0
FC573-23-20	23	MISCELLANEOUS SEALANT	WHITE	11/6/2008	1ST FL SOUTH MECH RM	0	0	0
FC573-23-21	23	MISCELLANEOUS SEALANT	WHITE	11/6/2008	3RD FL NORTH MECH RM	0	0	0
FC573-24-20	24	BROWN VINYL BASE AND ADHESIVE, 4"		11/6/2008	1ST FL SOUTH, EAST CNTR RM	0	0	0
FC573-24-21	24	BROWN VINYL BASE AND ADHESIVE, 4"		11/6/2008	3RD FL SOUTH, WEST CNTR RM	0	0	0
FC573-25-20	25	INTERIOR CAULKING,	WHITE	11/6/2008	2ND FL WEST CNTR LAUNDRY	0	0	0
FC573-25-21	25	INTERIOR CAULKING,	WHITE	11/6/2008	2ND FL NORTH, NW RM	0	0	0
FC573-26-20	26	MISCELLANEOUS SEALANT	BLACK	11/6/2008	2ND FL NORTH MECH RM	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-27-20	27	CARPET ADHESIVE	YELLOW	11/6/2008	2ND FL CNTR LOUNGE	0	0	0
FC573-28-20	28	EXTERIOR CAULKING,	GRAY	11/6/2008	2ND FL EAST CNTR	0	0	0
FC573-28-21	28	EXTERIOR CAULKING,	GRAY	11/6/2008	3RD FL WEST CNTR	0	0	0
FC573-29-20	29	DUCT SEALANT, GRAY		11/6/2008	3RD FL NORTH MECH RM	0	0	0
FC573-30-00ri10	30	ROOFING SEALANT, BLACK		1/6/2011	N/A	9	9	9
FC573-30-20	30	ROOFING SEALANT, BLACK		11/6/2008	ROOF, CNTR BUCKET	4	0	0
FC573-30-30	30	ROOFING SEALANT, BLACK		1/6/2011	ROOF, NORTH CNTR PERIMETER PATCH	0	0	0
FC573-30-31	30	ROOFING SEALANT, BLACK		1/6/2011	ROOF, SOUTH CNTR PERIMETER	0	0	0
FC573-30-50	30	ROOFING SEALANT, BLACK		9/18/2019	ROOF, ATTIC CENTER	0	0	0
FC573-31-20	31	ROOFING SEALANT, BLACK		11/6/2008	ROOF, NORTH CENTER	0	0	0
FC573-31-21	31	ROOFING SEALANT, BLACK		11/6/2008	ROOF, SOUTH CENTER	0	0	0
FC573-32-20	32	ROOFING SEALANT, GRAY		11/6/2008	ROOF, NE PERIMETER	0	0	0
FC573-32-21	32	ROOFING SEALANT, GRAY		11/6/2008	ROOF, SE PERIMETER	0	0	0
FC573-32-30	32	ROOFING SEALANT, GRAY		1/6/2011	ROOF, NORTH CNTR PERIMETER	0	0	0
FC573-32-31	32	ROOFING SEALANT, GRAY		1/6/2011	ROOF, SOUTH CNTR PERIMETER	0	0	0
FC573-33-20	33	MEMBRANE-TYPE ROOFING		11/6/2008	ROOF, WEST CNTR	0	0	0
FC573-33-21	33	MEMBRANE-TYPE ROOFING		11/6/2008	ROOF, SOUTH STAIRWELL	0	0	0
FC573-33-30	33	MEMBRANE-TYPE ROOFING		1/6/2011	ROOF, NORTH CNTR DECK	0	0	0
FC573-33-31	33	MEMBRANE-TYPE ROOFING		1/6/2011	ROOF, SOUTH CNTR DECK	0	0	0
FC573-34-20	34	ROOFING SEALANT, BLACK	METAL VENTS	11/6/2008	ROOF, NORTH CNTR	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-34-21	34	ROOFING SEALANT, BLACK	METAL VENTS	11/6/2008	ROOF, SOUTH CNTR	0	0	0
FC573-35-20	35	ROOFING MATERIAL, BLACK	BLACK	11/6/2008	ROOF, CNTR NW	0	0	0
FC573-35-21	35	ROOFING MATERIAL, BLACK	BLACK	11/6/2008	ROOF, CNTR SE	0	0	0
FC573-36-00ri10	36	ROOFING SEALANT, BLACK		1/6/2011	N/A	9	9	9
FC573-36-00ri11	36	ROOFING SEALANT, BLACK		1/19/2012	N/A	9	9	9
FC573-36-00ri13	36	ROOFING SEALANT, BLACK		12/9/2013	N/A	9	9	9
FC573-36-00ri16	36	ROOFING SEALANT, BLACK		6/9/2016	N/A	9	9	9
FC573-36-20	36	ROOFING SEALANT, BLACK		11/6/2008	ROOF, WEST CNTR PATCH	5	0	0
FC573-36-21	36	ROOFING SEALANT, BLACK		11/6/2008	ROOF, SW CORNER PATCH	0	0	0
FC573-37-20	37	PITCH POCKET TAR	BLACK	11/6/2008	ROOF, SOUTH CNTR WEST	0	0	0
FC573-40-30	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	1ST FL NORTH, NW RM	0	0	0
FC573-40-31	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	1ST FL SOUTH, SE RM	0	0	0
FC573-40-32	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	2ND FL NORTH, NE RM	0	0	0
FC573-40-33	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	2ND FL SOUTH, SW RM	0	0	0
FC573-40-34	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	3RD FL NORTH, NE RM	0	0	0
FC573-40-35	40	12" GRAY w/ GRAY FLOOR TILE AND ADHESIVE		1/6/2011	3RD FL SOUTH, SW RM	0	0	0
FC573-45-40	45	MISCELLANEOUS SEALANT	BROWN/ RED	1/19/2012	2ND FL NE MECH RM	0	0	0
FC573-45-41	45	MISCELLANEOUS SEALANT	BROWN/ RED	1/19/2012	3RD FL NORTH CHASE	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC573-45-40	46	ROOFING SEALANT, BLACK		1/19/2012	ROOF, CNTR NORTH DRAIN	0	0	0
FC573-45-41	46	ROOFING SEALANT, BLACK		1/19/2012	ROOF, SW UNDERLAYMENT	0	0	0
FC573-50-00ri16	50	RESIDUAL MASTIC	BLACK	6/9/2016	N/A	9	9	9
FC573-50-00ri19	50	RESIDUAL MASTIC	BLACK	9/18/2019	N/A; 2ND SW ROOM	9	9	9
FC573-50-00ri23	50	RESIDUAL MASTIC	BLACK	3/28/2023	N/A	9	9	9
FC573-50-40	50	RESIDUAL MASTIC	BLACK	12/9/2013	2ND FL, SW DOORWAY	3	0	0
FC573-50-50	50	RESIDUAL MASTIC	BLACK	9/18/2019	3RD FL SOUTH, NE ENTRY	0	0	0