

QUESTIONS & ANSWERS

QUESTIONS:

123-11-001

1. A rough estimate of dimensions of crack
2. (3.1) The construction of the provision of the cofferdam will be by contactor?
3. (3.4) A rough estimate of polysulfide quantity
4. (3.4.2) What is the thickness of the steel plate to be repaired? Is it possible to drill it? (bends or close to stiffeners)

256-61-001

- 1 Thickness and material of pipe gaskets?

508-11-001

1. Are scaffolding or ladders necessary for work?
2. Diameter of pipes in pipes regarding 3.1

521-21-001

1. Is alignment required?
2. What is the weight of the motor?

ANSWERS:

123-11-001

1. 8 inches long, 1/64th of an inch wide.
2. No construction of the cofferdam is required. FDRMC Divers have the cofferdam and will install. Only crane support for a waterborne install is required.
3. Polysulfide is available in multiple quantities for purchase. Amount to be purchased is required to cover 2 sqft, plus 20% for wastage.
4. Base metal plate containing the crack is 0.375 inch thick. End point drill of the crack may be inhibited due to the Fire Main pipe interference listed in paragraph 4.

256-61-001

1. Gaskets must be Garlock Blue Guard, 3200, in 1/16th inch

508-11-001

1. Ladders may be required to accomplish work in some locations.
2. The largest diameter pipe is 8 inches in diameter, which equates to approximately 25 inches of circumference.

521-21-001

1. Alignment is required in accordance with paragraph 3.2.7 of the work item.
- Weight is approximately 2,200 lbs.