

SALIENT CHARACTERISTICS

March 2026

Photo Sonics PANDA BCU Evaluation for Repair

These characteristics will satisfy the requirement of needs for the requested equipment. For additional information, please contact Kyle Welliver 805-606-2698 / Tevin Limon 805-605-5669

3 Each PANDA BCU's

- Evaluate 3ea failed PANDA BCU's
- Provide Evaluation report to include at minimum:
 - o List of all failed components or software
 - o If found repairable. Provide costs to proceed with repair for complete chassis.
 - o If found unrepairable. Provide recommended replacement components and or ROM to integrate with currently available components.