

RFI's For WWYK250088 MAC BOA WWYK250088 ~ Repair Interior Walls, B8400

1. Can the government provide guidance on the areas that are needed for deck replacement (minimum SF)?

Government Response: No deck replacement is required. The damaged decking was addressed by the ongoing roof replacement project.

2. Can the government provide as-built data on the existing roofing system?

Government Response: As-built documentation was made available to contractors prior to pre-bid site visit. If, for whatever reason, a contractor did not receive as-built documentation, correspond with the Contracting Specialist / Contracting Officer to request the files.

3. Can the government provide the schedule for design submittals and the submittal requirements (65%,95%,100% and IFC) if necessary.

Government Response: This is a “construction only” project, not a “design-build” project. SOW Section 1.3.3 indicates “Subcontractor firms performing ‘delegated’ design shall be authorized to offer engineering or architectural services in a US State or Territory. An Oklahoma license will not be required for individuals responsible for signing/sealing documents.” The ‘delegated’ design indicated is referenced in SOW Section 3.5, Working Documents.

HO.PETER.HAO.1123729591
O.1123729591

Digitally signed by
HO.PETER.HAO.1123729591
Date: 2026.03.18 07:57:20
-05'00'