


DISTRIBUTION STATEMENT A:
APPROVED FOR
PUBLICATION RELEASE.
DISTRIBUTION IS UNLIMITED.

- A. 304 Assessment for CIP FY26 project.
- B. Equipment at locations need DRMO
- C. Foundation thickness and condition needs assessed.
- D. Utilities(Air & 480V)

1. POST X/Y 65-67, site prep at location only.
2. Machine OC 12675, Post X94, DRMO and site prep.



(Building 3001, F100 Rotor Shop)