

ASBESTOS INSPECTION REPORT of:

Building # HP57

MCB CAMP LEJEUNE



Print Date

Tuesday, November 4, 2025

INSPECTION SUMMARY

BLDG #: HP57

YEAR BUILT: 1976

OCCUPANT: BEQ

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 3/GREEN [DEC2022]
ROOFING SEALANT AND TAR PAPER

DEC2022
ACM REMAINS

OCT2019
NO CHANGES

JUL2016
ACM REMAINS

NOV2013
PVS. ACM REMAINS, NO CHANGES

MAR2010
PVS. SAMPLED MATERIALS CONFIRMED NON ACM, ADDL SAMPLING, ACM INCLUDES:
ROOFING SEALANT, BLACK
TAR PAPER, BLACK
VAPOR BARRIER, SHOWER PANS

INSPECT JUN06
NO ASBESTOS CONTAINING MATERIALS WERE IDENTIFIED.

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
No friable ACM records found in database			

Non-friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
VAPOR BARRIER	UNDER HARD TILES AT SHOWER PANS (ACCESSIBLE ONLY IN MECHANICAL ROOMS), PRESUMED ALL SHOWERS	3/11/2010	160 SF
ROOFING SEALANT, BLACK	ATTIC/ PREVIOUS ROOF; PERIMETER AND PARAPET FLASHINGS	3/11/2010	2,672 SF
VAPOR BARRIER	UNDER HARD TILES AT SHOWER PANS (ACCESSIBLE ONLY IN MECHANICAL ROOMS), PRESUMED ALL SHOWERS	10/31/2019	160 SF
ROOFING SEALANT, BLACK	ATTIC/ PREVIOUS ROOF; PERIMETER AND PARAPET FLASHINGS	10/31/2019	2,672 SF

VAPOR BARRIER	UNDER HARD TILES AT SHOWER PANS (ACCESSIBLE ONLY IN MECHANICAL ROOMS), PRESUMED ALL SHOWERS	11/5/2013	160	SF
ROOFING SEALANT, BLACK	ATTIC/ PREVIOUS ROOF; PERIMETER AND PARAPET FLASHINGS	11/5/2013	2,672	SF
VAPOR BARRIER	UNDER HARD TILES AT SHOWER PANS (ACCESSIBLE ONLY IN MECHANICAL ROOMS), PRESUMED ALL SHOWERS	7/20/2016	160	SF
ROOFING SEALANT, BLACK	ATTIC/ PREVIOUS ROOF; PERIMETER AND PARAPET FLASHINGS	7/20/2016	2,672	SF
VAPOR BARRIER	UNDER HARD TILES AT SHOWER PANS (ACCESSIBLE ONLY IN MECHANICAL ROOMS), PRESUMED ALL SHOWERS	12/14/2022	160	SF
ROOFING SEALANT, BLACK	ATTIC/ PREVIOUS ROOF; PERIMETER AND PARAPET FLASHINGS	12/14/2022	2,672	SF

Tested Non ACM or REMOVED Materials

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>
DRYWALL AND JOINT MATERIAL	DORM ROOMS THROUGHOUT	6/28/2006
12" TAN FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	6/28/2006
PIPE INSULATION SEALANT	CENTRAL AREA LAUNDRIES	6/28/2006
MISCELLANEOUS SEALANT	CENTRAL LAUNDRIES AT PIPE PENETRATIONS/ PATCHING	6/28/2006
EXTERIOR CAULKING,	THROUGHOUT BUILDING	6/28/2006
TEXTURED CEILING MATERIAL	DORM ROOMS THROUGHOUT, ON CONCRETE	6/28/2006
12" TAN FLOOR TILE AND ADHESIVE	DORM ROOMS THROUGHOUT (PRIMARY TILE, SUPERCEDED BY HM01)	6/28/2006
2'x2' CEILING TILE,	CENTRAL LOUNGES	6/28/2006
MISCELLANEOUS SEALANT	MECHANICAL ROOM PIPE PENETRATIONS THROUGH BLOCK WALLS	6/28/2006
BROWN VINYL BASE AND ADHESIVE, 4"	CENTRAL LOUNGES AND HALLS	6/28/2006
BROWN VINYL BASE AND ADHESIVE, 4"	DORM ROOMS THROUGHOUT	6/28/2006
MISCELLANEOUS SEALANT	MECHANICAL ROOM AND CENTRAL PIPE CHASE DUCTS	6/28/2006
PIPE INSULATION	MECHANICAL ROOM SUPPLY AND RETURN LINES	6/28/2006
INTERIOR CAULKING,	ATTIC/ PREVIOUS ROOF; PERIMETER PARAPET WALL BASE	3/11/2010
LAGGING PAPER ON FIBERGLASS	CENTRAL PIPE CHASES	3/11/2010
RESIDUAL MASTIC	FIRST FLOOR CENTER HALLWAY	3/11/2010
EXTERIOR CAULKING,	BRICK WALL EXPANSION JOINTS	3/11/2010

CONCRETE EXPANSION JOINT MATERIAL	FIRST FLOOR BRICK/ CONCRETE SLAB JOINT PERIMETER	3/11/2010
FIBERGLASS INSULATION SEALANT	PIPE CHASES AND MECHANICAL ROOMS	3/11/2010
EXTERIOR CAULKING,	METAL WINDOWS	3/11/2010
ROOFING MATERIAL,	ATTIC/ ROOF, MAIN COVERING RESIDUAL	3/11/2010
TAR PAPER, BLACK	ATTIC/ ROOF, PREVIOUS ROOFING VAPOR BARRIER THROUGHOUT	3/11/2010
ELECTRICAL WRAPPED WIRING	NORTHEAST EXTERIOR GROUND AT DITCH	3/11/2010
TAR PAPER, BLACK	ATTIC/ ROOF, PREVIOUS ROOFING VAPOR BARRIER THROUGHOUT	10/31/2019
MISCELLANEOUS SEALANT	MECHANICAL ROOM AND CENTRAL PIPE CHASE DUCTS	10/31/2019
12" TAN FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES AND OFFICE AREAS, DORM ROOMS THROUGHOUT	3/11/2010
TEXTURED CEILING MATERIAL	DORM ROOMS THROUGHOUT, ON CONCRETE	3/11/2010
DRYWALL AND JOINT MATERIAL	DORM ROOMS THROUGHOUT	3/11/2010
MISCELLANEOUS SEALANT	MECHANICAL ROOM AND CENTRAL PIPE CHASE DUCTS	3/11/2010
MISCELLANEOUS SEALANT	MECHANICAL ROOM AND CENTRAL PIPE CHASE DUCTS	7/20/2016

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-01-01	01	12" TAN FLOOR TILE	w/ WHITE	6/28/2006	1ST FL LOUNGE	0	0	0
		AND ADHESIVE						
HP57-01-02	01	12" TAN FLOOR TILE	w/ WHITE	6/28/2006	1ST FL LOUNGE	0	0	0
		AND ADHESIVE						
HP57-01-10	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	1ST FL CNTR OFFICE	0	0	0
		AND ADHESIVE						
HP57-01-11	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	1ST FL WEST WING, SOUTH	0	0	0
		AND ADHESIVE			CNTR RM			
HP57-01-11tem	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	1ST FL WEST WING, SOUTH	0	0	0
		AND ADHESIVE			CNTR			
HP57-01-12	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	1ST FL EAST WING, NW RM	0	0	0
		AND ADHESIVE						
HP57-01-13	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	1ST FL EAST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-14	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	2ND FL EAST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-14tem	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	2ND FL EAST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-15	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	2ND FL WEST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-16	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	2ND FL EAST WING, SE RM	0	0	0
		AND ADHESIVE						
HP57-01-17	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	3RD FL CNTR LOUNGE	0	0	0
		AND ADHESIVE						
HP57-01-18	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	3RD FL WEST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-18tem	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	3RD FL WEST WING, NE RM	0	0	0
		AND ADHESIVE						
HP57-01-19	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	3RD FL WEST WING, SE RM	0	0	0
		AND ADHESIVE						
HP57-01-20	01	12" TAN FLOOR TILE	w/ WHITE	3/11/2010	3RD FL EAST WING, SE RM	0	0	0
		AND ADHESIVE						
HP57-02-01	02	2'x2' CEILING TILE,		6/28/2006	1ST FL LOUNGE	0	0	0
HP57-02-02	02	2'x2' CEILING TILE,		6/28/2006	1ST FL LOUNGE	0	0	0
HP57-03-01	03	BROWN VINYL BASE		6/28/2006	1ST FL LOUNGE	0	0	0
		AND ADHESIVE, 4"						

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-03-02	03	BROWN VINYL BASE AND ADHESIVE, 4"		6/28/2006	3RD FL LOUNGE	0	0	0
HP57-04-01	04	PIPE INSULATION SEALANT	WHITE	6/28/2006	1ST FL LAUNDRY	0	0	0
HP57-04-02	04	PIPE INSULATION SEALANT	WHITE	6/28/2006	2ND FL LAUNDRY	0	0	0
HP57-05-01	05	MISCELLANEOUS SEALANT	GREEN	6/28/2006	1ST FL LAUNDRY	0	0	0
HP57-05-02	05	MISCELLANEOUS SEALANT	GREEN	6/28/2006	1ST FL LAUNDRY	0	0	0
HP57-06-01	06	EXTERIOR CAULKING,	GRAY	6/28/2006	1ST FL NORTH CNTR ROOM	0	0	0
HP57-06-02	06	EXTERIOR CAULKING,	GRAY	6/28/2006	2ND FL NORTH CNTR ROOM	0	0	0
HP57-07-01	07	TEXTURED CEILING MATERIAL		6/28/2006	1ST FL EAST WING, NW RM 119	0	0	0
HP57-07-02	07	TEXTURED CEILING MATERIAL		6/28/2006	1ST FL WEST WING, NW RM 122	0	0	0
HP57-07-03	07	TEXTURED CEILING MATERIAL		6/28/2006	2ND FL EAST WING, SW RM 208	0	0	0
HP57-07-04	07	TEXTURED CEILING MATERIAL		6/28/2006	2ND FL WEST WING, SE RM 207	0	0	0
HP57-07-05	07	TEXTURED CEILING MATERIAL		6/28/2006	3RD FL WEST WING, SE RM328	0	0	0
HP57-07-06	07	TEXTURED CEILING MATERIAL		6/28/2006	3RD FL EAST WING, SE RM 319	0	0	0
HP57-07-07	07	TEXTURED CEILING MATERIAL		6/28/2006	3RD FL EAST WING, SOUTH CNTR RM 317	0	0	0
HP57-07-10	07	TEXTURED CEILING MATERIAL		3/11/2010	1ST FL CNTR HALL	0	0	0
HP57-07-11	07	TEXTURED CEILING MATERIAL		3/11/2010	1ST FL WEST WING, SE RM	0	0	0
HP57-07-12	07	TEXTURED CEILING MATERIAL		3/11/2010	1ST FL EAST WING, SW RM	0	0	0
HP57-07-13	07	TEXTURED CEILING MATERIAL		3/11/2010	1ST FL EAST WING, NORTH CNTR RM	0	0	0
HP57-07-14	07	TEXTURED CEILING MATERIAL		3/11/2010	2ND FL EAST WING, NE RM	0	0	0
HP57-07-15	07	TEXTURED CEILING MATERIAL		3/11/2010	2ND FL WEST WING, NE RM	0	0	0

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-07-16	07	TEXTURED CEILING MATERIAL	3/11/2010	2ND FL EAST WING, SE RM	0	0	0
HP57-07-17	07	TEXTURED CEILING MATERIAL	3/11/2010	3RD FL WEST WING, NE RM	0	0	0
HP57-07-18	07	TEXTURED CEILING MATERIAL	3/11/2010	3RD FL WEST WING, SE RM	0	0	0
HP57-07-19	07	TEXTURED CEILING MATERIAL	3/11/2010	3RD FL EAST WING, SE RM	0	0	0
HP57-08-01	08	DRYWALL AND JOINT MATERIAL	6/28/2006	1ST FL EAST WING, NW RM 119	0	0	0
HP57-08-02	08	DRYWALL AND JOINT MATERIAL	6/28/2006	1ST FL WEST WING, WEST WING, NW RM 122	0	0	0
HP57-08-03	08	DRYWALL AND JOINT MATERIAL	6/28/2006	2ND FL EAST WING, SW RM 208	0	0	0
HP57-08-04	08	DRYWALL AND JOINT MATERIAL	6/28/2006	2ND FL WEST WING, SE RM 207	0	0	0
HP57-08-05	08	DRYWALL AND JOINT MATERIAL	6/28/2006	3RD FL WEST WING, SE RM 320	0	0	0
HP57-08-10	08	DRYWALL AND JOINT MATERIAL	3/11/2010	1ST FL WEST WING, SOUTH CNTR RM	.1	.1	.1
HP57-08-11	08	DRYWALL AND JOINT MATERIAL	3/11/2010	1ST FL WEST WING, SE RM	0	0	0
HP57-08-12	08	DRYWALL AND JOINT MATERIAL	3/11/2010	1ST FL EAST WING, SW RM	0	0	0
HP57-08-13	08	DRYWALL AND JOINT MATERIAL	3/11/2010	1ST FL WEST WING, NE RM	0	0	0
HP57-08-14	08	DRYWALL AND JOINT MATERIAL	3/11/2010	2ND FL EAST WING, NE RM	0	0	0
HP57-08-15	08	DRYWALL AND JOINT MATERIAL	3/11/2010	2ND FL WEST WING, NE RM	0	0	0
HP57-08-17	08	DRYWALL AND JOINT MATERIAL	3/11/2010	3RD FL WEST WING, NE RM	0	0	0
HP57-08-18	08	DRYWALL AND JOINT MATERIAL	3/11/2010	3RD FL WEST WING, SOUTH CNTR RM	0	0	0
HP57-08-19	08	DRYWALL AND JOINT MATERIAL	3/11/2010	3RD FL WEST WING, SE RM	0	0	0
HP57-08-20	08	DRYWALL AND JOINT MATERIAL	3/11/2010	3RD FL EAST WING, SE RM	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-09-01	09	12" TAN FLOOR TILE AND ADHESIVE	w/WHITE	6/28/2006	1ST FL EAST WING, NW RM 119	0	0	0
HP57-09-02	09	12" TAN FLOOR TILE AND ADHESIVE	w/WHITE	6/28/2006	1ST FL WEST WING, NW RM122	0	0	0
HP57-10-02	10	BROWN VINYL BASE AND ADHESIVE, 4"		6/28/2006	1ST FL WEST WING, NW RM 122	0	0	0
HP57-11-01	11	MISCELLANEOUS SEALANT	RED	6/28/2006	1ST FL MECH RM 1	0	0	0
HP57-11-02	11	MISCELLANEOUS SEALANT	RED	6/28/2006	2ND FL MECH RM 4	0	0	0
HP57-11-10	11	MISCELLANEOUS SEALANT	RED	3/11/2010	1ST FL WEST MECH RM, SOUTH	0	0	0
HP57-11-11	11	MISCELLANEOUS SEALANT	RED	3/11/2010	2ND FL WEST MECH RM, SOUTH	0	0	0
HP57-11-12	11	MISCELLANEOUS SEALANT	RED	3/11/2010	3RD FL WEST MECH RM, SOUTH	0	0	0
HP57-11-30	11	MISCELLANEOUS SEALANT	RED	7/20/2016	ATTIC, CNTR DUCT WEST	0	0	0
HP57-11-40	11	MISCELLANEOUS SEALANT	RED	7/20/2016	ATTIC, CNTR DUCT WEST	0	0	0
HP57-12-01	12	PIPE INSULATION	FIBERGLASS	6/28/2006	1ST FL MECH RM 1	0	0	0
HP57-12-02	12	PIPE INSULATION	FIBERGLASS	6/28/2006	2ND FL MECH RM 2	0	0	0
HP57-13-01	13	MISCELLANEOUS SEALANT	RED	6/28/2006	2ND FL MECH RM #3	0	0	0
HP57-13-02	13	MISCELLANEOUS SEALANT	RED	6/28/2006	3RD FL MECH RM #5	0	0	0
HP57-20-10	20	LAGGING PAPER ON FIBERGLASS		3/11/2010	1ST FL WEST CHASE, EAST END	0	0	0
HP57-20-11	20	LAGGING PAPER ON FIBERGLASS		3/11/2010	2ND FL WEST CHASE, EAST END	0	0	0
HP57-20-12	20	LAGGING PAPER ON FIBERGLASS		3/11/2010	3RD FL WEST CHASE, EAST END	0	0	0
HP57-21-10	21	RESIDUAL MASTIC	BLACK	3/11/2010	1ST FL CNTR HALL NORTH	0	0	0
HP57-22-10	22	EXTERIOR CAULKING,	GRAY	3/11/2010	1ST FL WEST END	0	0	0
HP57-22-11	22	EXTERIOR CAULKING,	GRAY	3/11/2010	2ND FL EAST END	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-22-12	22	EXTERIOR CAULKING,	GRAY	3/11/2010	3RD FL WEST END	0	0	0
HP57-23-10	23	CONCRETE EXPANSION JOINT MATERIAL	BLACK	3/11/2010	1ST FL WEST END, CNTR	0	0	0
HP57-24-00ri13	24	VAPOR BARRIER	BLACK	11/5/2013	N/A	9	9	9
HP57-24-00ri16	24	VAPOR BARRIER	BLACK	7/20/2016	N/A	9	9	9
HP57-24-00ri19	24	VAPOR BARRIER	BLACK	10/31/2019	N/A	9	9	9
HP57-24-00ri22	24	VAPOR BARRIER	BLACK	12/14/2022	N/A	9	9	9
HP57-24-10	24	VAPOR BARRIER	BLACK	3/11/2010	1ST FL WEST WING, SOUTH CNTR MECH RM	3	0	0
HP57-24-11	24	VAPOR BARRIER	BLACK	3/11/2010	2ND FL WEST WING, SOUTH CNTR MECH RM	0	0	0
HP57-24-12	24	VAPOR BARRIER	BLACK	3/11/2010	3RD FL WEST WING, SOUTH CNTR MECH RM	0	0	0
HP57-25-10	25	EXTERIOR CAULKING,	GRAY	3/11/2010	1ST FL WEST WING, SE RM	0	0	0
HP57-25-11	25	EXTERIOR CAULKING,	GRAY	3/11/2010	2ND FL EAST WING, NE RM	0	0	0
HP57-25-12	25	EXTERIOR CAULKING,	GRAY	3/11/2010	3RD FL WEST WING, NE RM	0	0	0
HP57-26-10	26	FIBERGLASS INSULATION SEALANT	WHITE	3/11/2010	3RD FL CNTR CHASE WEST	0	0	0
HP57-22-00ri23	27	ROOFING SEALANT, BLACK		12/14/2022	N/A	9	9	9
HP57-27-00ri13	27	ROOFING SEALANT, BLACK		11/5/2013	N/A	9	9	9
HP57-27-00ri16	27	ROOFING SEALANT, BLACK		7/20/2016	N/A	9	9	9
HP57-27-00ri19	27	ROOFING SEALANT, BLACK		10/31/2019	N/A	9	9	9
HP57-27-10	27	ROOFING SEALANT, BLACK		3/11/2010	ATTIC/ ROOF, WEST END	3	0	0
HP57-27-11	27	ROOFING SEALANT, BLACK		3/11/2010	ATTIC/ ROOF, EAST END	3	0	0
HP57-27-70	27	ROOFING SEALANT, BLACK		12/14/2022	ATTIC, CNTR MEMBRANE/ VAPOR BARRIER	0	0	0
HP57-28-10	28	INTERIOR CAULKING,	WHITE	3/11/2010	ATTIC/ ROOF, WEST END	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP57-28-11	28	INTERIOR CAULKING,	WHITE	3/11/2010	ATTIC/ ROOF, EAST END	0	0	0
HP57-29-10	29	ROOFING MATERIAL,	BLACK	3/11/2010	ATTIC/ ROOF, WEST END	0	0	0
HP57-29-11	29	ROOFING MATERIAL,	BLACK	3/11/2010	ATTIC/ ROOF, EAST END	0	0	0
HP57-30-10	30	TAR PAPER, BLACK		3/11/2010	ATTIC/ ROOF, WEST END	0	0	0
HP57-30-11	30	TAR PAPER, BLACK		3/11/2010	ATTIC/ ROOF, EAST END	0	0	0
HP57-30-40	30	TAR PAPER, BLACK		10/31/2019	ATTIC, WEST CNTR [as HP57-41-40]	0	0	0
HP57-41-40	30	TAR PAPER, BLACK		10/31/2019	SEE HP57-30-40	0	0	0
HP57-31-10	31	ELECTRICAL WRAPPED WIRING	BLACK	3/11/2010	NE EXT. GROUND	0	0	0