Transfer funciton of 4th order Butterworth Filter at 50 Hz 10^{-2} 10^{-5} 10^{-8} 10^{-11} 100 Phase / ° o -100 10° 10^1 10^{2} Frequency / Hz