Workflow description


XIQ Access Point import to XIQ-SE

This workflow addresses the need to use XIQ-SE Control for XIQ cloud AP's. The XIQ AP's gets imported to XIQ-SE, discovered and added to the Control.

Prerequisite


XIQ

The XIQ network policy must contain SNMP settings for the AP's to enable XIQ-SE for discovering and classifying later on the AP. Als is required to define the Radius settings for the SSID where you intend to server 802.1x authneticaion.




XIQ-SE


The XIQ location should be appropriate mapped to the XIQ-SE site paths.



As well the Site actions




And Access Control settings



XIQ-SE Workflow parameter

During execution of the workflow you have to provide the parameter relevant for the success.



Troubleshooting

Please note, they is no Extreme Networks GTAC for any workflow.

Before reporting an issue via GitHub or the creator of the workflow, please ensure that the workflow is configured for **DEBUG** mode. The data and debug LOG files can then be found on the XIQ-SE file system under /dev/shm/<Execution-ID>_<Workflow-Name>/. Note that only the last six execution debug logs will be held. The actual path can also be found in the each workflow activity log.

```
Output

Script Name: XIQ AP import_XIQ
Date and Time: 2025-03-24T16:11:49.248
XIQ-SE User: mnikulski
XIQ-SE User Domain:
IP:
16:12:06 INFO
16:12:08 INFO
LOG file /dev/shm/2281_Workflows_CTC-Production_XIQ-AP-import/XIQ.log
learn AP 20.0.203.70 'CTC-410C-3/45' (AIP)
```

When SSH to XIQ-SE, the following log files should be present in the folder.

Please include all log files when reporting an issue.