WSJT Keyboard Shortcuts

F1	List keyboard shortcuts	
Shift+F1	List special mouse commands	
Ctrl+F1	About WSJT	
F2	Options	
F3	Tx Mute	
F4	Clear "To Radio"	
F5	What message to send?	
F6	Open next file in directory	
Shift+F6	Decode all wave files in directory	
F7	Set FSK441 mode	
Shift+F7	Set JT6M mode	
F8	Set JT65A mode	
Shift+F8	Set JT65B mode	
Ctrl+F8	Set JT65C mode	
Shift+Ctrl+F8	Set CW mode	
F10	Show SpecJT	
Shift+F10	Show astronomical data	
F11	Decrement Freeze DF	
F12	Increment Freeze DF	
Alt+1 to Alt+6	Tx1 to Tx6	
Alt+A	Toggle Auto On/Off	
Alt+D	Decode	
Ctrl+D	Force Decode	
Shift+Ctrl+D	Force Decode, no JT65 shorthands	
Alt+E	Erase	
Alt+F	Toggle Freeze	
Alt+G	Generate Standard Messages	
Ctrl+G	Generate Alternate JT65 Messages	
Alt+I	Include	
Alt+L	Lookup	
Ctrl+L	Lookup, then Generate Standard Messages	
Alt+M	Monitor	
Alt+O	Tx Stop	
Alt+Q	Log QSO	
Alt+S	Stop Monitoring or Decoding	
Alt+V	Save Last	

Exclude

Toggle Zap

Alt+X

Alt+Z

Special Mouse Commands

Click on	Action
Waterfall	FSK441/JT6M: Click to decode ping JT65: Click to set DF for Freeze Double-click to Freeze and Decode
Main screen, graphics area	FSK441/JT6M: Click to decode ping JT65: Click to set DF for Freeze Double-click to Freeze and Decode
Main screen, text area	Double-click on callsign sets Tx messages with shorthands, and sets Auto On Right-double-click on callsign sets Tx messages with dB signal reports, and sets Auto On
Sync, Clip, Tol,	<pre>Left/Right click to increase/decrease values</pre>

Recommended Message Sequences for Minimal JT65 QSOs

Station #1	Station #2	
CQ K1JT FN20	K1JT DL3XYZ JO61	
DL3XYZ K1JT FN20 000	RO	
RRR	73	
	73	
CQ K1JT FN20		
VK7ABC K1JT -22	K1JT VK7ABC QE37	
	K1JT VK7ABC R-23	
VK7ABC K1JT RRR	TNX JOE 73	