Package 'referenceIntervals'

April 18, 2020

Type Package

Version 1.2.0

Title Reference Intervals

Author Daniel Finnegan
Maintainer Daniel Finnegan <dan.finnegan@gmail.com></dan.finnegan@gmail.com>
Imports boot, extremevalues, car, outliers
LazyData no
Description This is a collection of tools to allow the medical professional to calculate appropriate reference ranges (intervals) with confidence intervals around the limits for diagnostic purposes.
License GPL-3
NeedsCompilation no
Repository CRAN
Date/Publication 2020-04-18 05:10:03 UTC
R topics documented:
referenceIntervals-package cook.outliers dixon.outliers horn.outliers nonparRanks nonparRI plot.interval print.interval print.interval.sub

Index	17
	vanderLoo.outliers
	singleRefLimit
	set50

referenceIntervals-package

This package calculates reference intervals from a dataset using either parametric, non-parametric, or robust methods.

Description

This package also calculates the confidence intervals around the calculated reference intervals in order to provide a metric for how precise the calculations are. This package also contains four outlier detection functions.

Details

Package: referenceIntervals

Type: Package
Version: 1.2.0
Date: 2020-04-17
License: GPL-3

Author(s)

Daniel Finnegan

Maintainer: Daniel Finnegan dan.finnegan@gmail.com

References

~~ Literature or other references for background information ~~

```
refLimit(set50, out.rm = TRUE, out.method = "cook")
refLimit(set200, out.method = "horn", RI = "n", refConf = 0.90, limitConf = 0.80)
horn.outliers(set120)
dixon.outliers(set20)

refLimit(set50, out.method = "vanderLoo", out.rm = TRUE, RI = "r", bootStat = "perc")
frame = data.frame(one = rnorm(30, m = 5, sd = 2), two = rnorm(30, m = 7, sd = 1),
three = rnorm(30, m = 2, sd = 0.5))
```

cook.outliers 3

```
result = refLimit(frame)
plot(result)
```

cook.outliers

Determines outliers using Cook's Distance

Description

A linear regression model is calculated for the data (which is the mean for one-dimensional data. From that, using the Cook Distances of each data point, outliers are determined and returned.

Usage

```
cook.outliers(data)
```

Arguments

data

A vector of data points.

Value

Returns a list containing a vector of outliers and a vector of the cleaned data (subset).

outliers A vector of outliers from the data set

subset A vector containing the remaining data, cleaned of outliers

Author(s)

Daniel Finnegan

```
cook.outliers(set50)
plot(cook.outliers(set50)$subset)
```

4 dixon.outliers

div	kon	α	+1	i	arc
u_{\perp}	X OH	. Ot	11.1	1 6	-1 5

Determines outliers using Dixon's Q Test method

Description

This determines outliers of the dataset by calculating Dixon's Q statistic and comparing it to a standardized table of statistics. This method can only determine outliers for datasets of size 3 <= n <= 30. This function requires the outliers package.

Usage

```
dixon.outliers(data)
```

Arguments

data

A vector of data points.

Value

Returns a list containing a vector of outliers and a vector of the cleaned data (subset).

outliers A vector of outliers from the data set

subset A vector containing the remaining data, cleaned of outliers

Author(s)

Daniel Finnegan

References

Statistical treatment for rejection of deviant values: critical values of Dixon's "Q" parameter and related subrange ratios at the 95 (2), pp 139-146 DOI: 10.1021/ac00002a010. Publication Date: January 1991

One-sided and Two-sided Critical Values for Dixon's Outlier Test for Sample Sizes up to n = 30. Economic Quality Control, Vol 23(2008), No. 1, 5-13.

```
dixon.outliers(set20)
summary(dixon.outliers(set20)$subset)
```

horn.outliers 5

horn.outliers	Determines outliers using Horn's method and Tukey's interquartile fences on a Box-Cox transformation of the data.

Description

This function determines outliers in a Box-Cox transformed dataset using Horn's method of outlier detection using Tukey's interquartile fences. If a data point lies outside 1.5 * IQR from the 1st or 3rd quartile point, it is an outlier.

Usage

```
horn.outliers(data)
```

Arguments

data A vector of data points.

Value

Returns a list containing a vector of outliers and a vector of the cleaned data (subset).

outliers A vector of outliers from the data set

subset A vector containing the remaining data, cleaned of outliers

Author(s)

Daniel Finnegan

References

ASVCP reference interval guidelines: determination of de novo reference intervals in veterinary species and other related topics. Vet Clin Pathol 41/4 (2012) 441-453, 2012 American Society for Veterinary Clinical Pathology

Horn, P. S., Feng, L., Li, Y., & Pesce, A. J. (2001). Effect of outliers and nonhealthy individuals on reference interval estimation. Clinical Chemistry, 47(12), 2137-2145.

Examples

horn.outliers(set200)

6 nonparRI

nonparRanks	Table that dictate the ranks for the confidence intervals around the calculated reference interval.

Description

This is a table that dictate the ranks for the confidence intervals around the calculated reference interval. This method is available when $120 \le n \le 1000$.

Usage

nonparRanks

Format

A data frame with 882 observations on the following 3 variables.

```
SampleSize a numeric vector
Lower a numeric vector
Upper a numeric vector
```

References

Defining, Establishing, and Verifying Reference Intervals in the Clinical Laboratory; Approved Guideline - 3rd Edition (C28-A3)

Examples

data(nonparRanks)

nonparRI

Determines the reference interval using non-parametric means

Description

This function uses the appropriate percentiles as determined by refConf to return the non-parametric reference interval. This is written as a boot function to use within the function refLimit.

Usage

```
nonparRI(data, indices = 1:length(data), refConf = 0.95)
```

plot.interval 7

Arguments

data is a vector of sample values.

indices The indices of data to be used in the calculations. The default is to use the whole

set.

refConf is a measure of the range covered by the calculation. Most often, as is

the default, 95

Value

Returns a vector of two values, the lower and upper limits of the reference interval.

Author(s)

Daniel Finnegan

References

Defining, Establishing, and Verifying Reference Intervals in the Clinical Laboratory; Approved Guideline - 3rd Edition (C28-A3)

Examples

```
nonparRI(set50)
nonparRI(set50, refConf = 0.9)
```

plot.interval

Overload of plot function to include the ability to plot the results of refLimit

Description

Plots the reference interval and confidence intervals around the limits of the reference interval.

Usage

```
## S3 method for class 'interval'
plot(x, main, ...)
```

Arguments

x Object x is of type "interval".

main Title of plot.

... Arguments to be passed to methods, such as graphical parameters (see 'par').

8 print.interval

Value

No return value.

Author(s)

Daniel Finnegan

Examples

```
result = refLimit(set200)
plot(result)
```

print.interval

Overload of print in order to concisely print the results of refLimit

Description

This function allows for the pretty-printing of a large list object created by calling the refLimit function.

Usage

```
## S3 method for class 'interval'
print(x, digits = 4L, quote = TRUE, prefix = "", ...)
```

Arguments

x x is an object of type "interval"

digits minimal number of _significant_ digits. See 'print.default'.

quote logical, indicating whether or not strings should be printed with surrounding

quotes.

prefix Option to specify a formatting prefix.

. . . further arguments passed to or from other methods.

Value

No return value.

Author(s)

Daniel Finnegan

print.interval.sub 9

Examples

```
result = refLimit(set120)
result
```

print.interval.sub

Overload of print in order to concisely print the results of refLimit

Description

This function allows for the pretty-printing of a large list object created by calling the refLimit function.

Usage

```
## S3 method for class 'interval.sub'
print(x, digits = 4L, quote = TRUE, prefix = "", ...)
```

Arguments

x x is an object of type "interval"
 digits minimal number of _significant_ digits. See 'print.default'.
 quote logical, indicating whether or not strings should be printed with surrounding quotes.
 prefix Option to specify a formatting prefix.
 further arguments passed to or from other methods.

Value

No return value.

Author(s)

Daniel Finnegan

10 refLimit

refLimit	Calculates and returns reference and confidence intervals for a dataset

Description

This function calculates a reference interval from a dataset using parametric, non-parametric, or robust methods.

Usage

```
refLimit(data, out.method = "horn", out.rm = FALSE, RI = "p", CI = "p",
refConf = 0.95, limitConf = 0.9, bootStat = "basic")
```

Arguments

data	A vector of data points.	
out.method	The outlier detection method. Valid options include "horn", "cook", "dixon", and "vanderLoo".	
out.rm	Remove outliers. If value is TRUE, outliers will be automatically removed prior to calculations. If FALSE (default), outliers will be detected but not removed.	
RI	Method for reference interval calculations. Valid options include "p" (default) for parametric, "n" for non-parametric, and "r" for robust method.	
CI	Method for confidence interval calculations. Valid options include "p" for parametric (default), "n" for non-parametric, and "boot" for bootstrapping method. The minimum samplesize for non-parametric confidence interval calculations is 120. With smaller samples, bootstrapping methods are used.	
refConf	Desired coverage for the calculated reference interval. The default is a 95 interval.	
limitConf	Desired confidence interval level. The default is a 90 reference interval limits.	
bootStat	Method for calculating confidence intervals from package <i>boot</i> . Valid arguments include "basic" (basic bootstrap method), "perc" (bootstrap percentile method), "norm" (normal approximation method), "stud" (studentized bootstrap method), and "bca" (adjusted bootstrap percentile method).	

Details

A confidence interval around each limit of the reference interval is calculated as a metric for determining the validity of the result. Outliers can be detected in one of four different methods and automatically eliminated.

To determine the most appropriate calculation for confidence intervals using the bootstrapping method, please consult chapter 5 of Davison and Hinkley's "Bootstrap Methods and their Applications."

robust 11

Value

Returns a list of necessary information.

size Size of dataset dname Name of dataset

out.method Outlier detection method

out.rm Boolean indicating whether outliers are automatically removed

outliers Vector of detected outliers

methodRI Method for reference interval calculations (p, n, or r)
methodCI Method for confidence interval calculations (p, n, boot)

norm Results of running Shapiro-Wilk and Kolmorgorov-Smirnov normacy tests

refConf Desired coverage of reference interval limitConf Desired confidence interval level

Ref_Int List containing the reference interval and confidence interval values

Author(s)

Daniel Finnegan

References

ASVCP reference interval guidelines: determination of de novo reference intervals in veterinary species and other related topics. *Vet Clin Pathol* 41/4 (2012) 441-453, 2012. American Society for Veterinary Clinical Pathology

Davison, A.C. and Hinkley, D.V. (1997) *Bootstrap Methods and Their Application*, Chapter 5. Cambridge University Press.

Examples

```
refLimit(set20, out.method = "dixon")
refLimit(set200, out.method = "cook", out.rm = TRUE, RI = "n", refConf = 0.9)
refLimit(set50, out.method = "vanderLoo", out.rm = TRUE, RI = "r", bootStat = "perc")
```

robust Algorithm that implements the robust method for reference interval calculations

Description

The robust method is an iterative method that determines the most appropriate weighted mean of the data and then calculates the desired reference interval.

12 set120

Usage

```
robust(data, indices = c(1:length(data)), refConf = 0.95)
```

Arguments

data Vector of data.

indices Indices of data to use for calculations.

refConf Desired coverage of the reference interval. Default is 95 interval.

Value

Returns a vector containing the lower and upper limits of the reference interval.

Author(s)

Daniel Finnegan

References

Defining, Establishing, and Verifying Reference Intervals in the Clinical Laboratory; Approved Guideline - 3rd Edition (C28-A3)

Examples

```
robust(set50)
robust(horn.outliers(set20)$subset)
```

set120

Dataset containing 120 values

Description

Small dataset containing 120 samples. The mean is centered on 27 with a standard deviation of 7.

Usage

set120

Format

The format is: num [1:120] 38.1 12.6 31.3 35.5 22.6 ...

Source

```
rnorm(120, m = 27, sd = 7)
```

set20 13

Examples

```
data(set120)
```

set20

Small dataset containing 20 samples

Description

Small dataset containing 20 samples. The mean is centered on 42 with a standard deviation of 5.

Usage

set20

Format

The format is: num [1:20] 35 32.9 43.6 44.6 35.9 ...

Source

```
rnorm(20, m = 42, sd = 6)
```

Examples

data(set20)

set200

Dataset containing 200 values

Description

Small dataset containing 200 samples. The mean is centered on 5 with a standard deviation of 1.

Usage

set200

Format

The format is: num [1:200] 3.95 5.16 5.32 3.86 3.54 ...

Source

```
rnorm(200, m = 5, sd = 1)
```

```
data(set200)
```

14 singleRefLimit

~~	⊢ I	┏.	ഹ
9		7	vı

Dataset containing 50 values

Description

Small dataset containing 50 samples. The mean is centered on 14 with a standard deviation of 3.

Usage

set50

Format

The format is: num [1:50] 16.61 20.43 7.91 15.19 14.77 ...

Source

```
rnorm(50, m = 14, sd = 3)
```

Examples

data(set50)

singleRefLimit

This is the workhorse of the refLimit function

Description

This is the function called to work on each individual vector of data.

Usage

```
singleRefLimit(data, dname = "default", out.method = "horn", out.rm = FALSE,
RI = "p", CI = "p", refConf = 0.95, limitConf = 0.9, bootStat = "basic")
```

Arguments

data	A vector of data points.
dname	Name of dataset.
out.method	The outlier detection method. Valid options include "horn", "cook", "dixon", and "vanderLoo".
out.rm	Remove outliers. If value is TRUE, outliers will be automatically removed prior to calculations. If FALSE (default), outliers will be detected but not removed.
RI	Method for reference interval calculations. Valid options include "p" (default) for parametric, "n" for non-parametric, and "r" for robust method.

singleRefLimit 15

CI Method for confidence interval calculations. Valid options include "p" for para-

metric (default), "n" for non-parametric, and "boot" for bootstrapping method. The minimum sample size for non-parametric confidence interval calculations

is 120. With smaller samples, bootstrapping methods are used.

refConf Desired coverage for the calculated reference interval. The default is a 95

limitConf Desired confidence interval level. The default is a 90 confidence interval around

the reference interval limits.

bootStat Method for calculating confidence intervals from package boot. Valid arguments

include "basic" (basic bootstrap method), "perc" (bootstrap percentile method), "norm" (normal approximation method), "stud" (studentized bootstrap method),

and "bca" (adjusted bootstrap percentile method).

Value

Returns a list of necessary information.

size Size of dataset

dname Name of dataset

out.method Method of outlier detection

out.rm Boolean indicating whether outliers are automatically removed

outliers Vector of detected outliers

methodRI Method for reference interval calculations (p, n, or r)

methodCI Method for confidence interval calculations (p, n, boot)

norm Results of running Shapiro-Wilk and Kolmorgorov-Smirnov normacy tests

refConf Desired coverage of reference interval

limitConf Desired confidence interval level

Ref_Int List containing the reference interval and confidence interval values

Author(s)

Daniel Finnegan

```
singleRefLimit(set200, out.method = "horn", out.rm = TRUE)
```

16 vanderLoo.outliers

vanderLoo.outliers	Mark van der Loo's outlier detection method in the extremevalues
	package

Description

Separates data into vectors of outliers and a cleaned subset of the data.

Usage

```
vanderLoo.outliers(data)
```

Arguments

data

Vector of data values.

Value

Returns a list containing a vector of outliers and a vector of the cleaned data (subset).

outliers A vector of outliers from the data set

subset A vector containing the remaining data, cleaned of outliers

Note

Requires extremevalues package.

Author(s)

Daniel Finnegan

References

http://cran.r-project.org/web/packages/extremevalues/extremevalues.pdf

```
vanderLoo.outliers(set50)
vanderLoo.outliers(set200)
```

Index

*Topic ~Cook	*Topic package
cook.outliers, 3	referenceIntervals-package, 2
*Topic ~Dixon	*Topic print
dixon.outliers,4	print.interval.sub,9
*Topic ~Horn	
horn.outliers, 5	cook.outliers,3
*Topic ~interval	J
nonparRI, 6	dixon.outliers,4
print.interval, 8	horn.outliers,5
refLimit, 10	norm. oddiici 3, 5
robust, 11	nonparRanks, 6
singleRefLimit, 14	nonparRI, 6
*Topic ~nonparametric	,
nonparRI, 6	plot.interval,7
*Topic ~outliers	print.interval, 8
vanderLoo.outliers, 16	print.interval.sub,9
*Topic ~outlier	
cook.outliers, 3	referenceIntervals
dixon.outliers,4	(referenceIntervals-package), 2
horn.outliers, 5	referenceIntervals-package, 2
*Topic ~print	refLimit, 10
print.interval, 8	robust, 11
*Topic ~range	set120, <u>12</u>
nonparRI, 6	set20, 12
*Topic ~reference	set200, 13
refLimit, 10	set50, 14
singleRefLimit, 14	singleRefLimit, 14
*Topic ~robust	Jingiener Limit, 11
robust, 11	vanderLoo.outliers, 16
*Topic ~vanderLoo	
vanderLoo.outliers, 16	
*Topic datasets	
nonparRanks, 6	
set120, 12	
set20, 13	
set200, 13	
set50, 14	
*Topic methods	
plot.interval, 7	