## Defender Bottle Jack Introduction



Models LD - Defender

Title Defender Bottle Jack Introduction

Last Modified 11-SEP-2008 12:19

**Category Chassis** 

Symptom 307000 Jack/Tool & Spare

Issue: Introduction of Bottle Jack for all

Defender variants.

Cause: The method of stowage for the Pillar type Jack along the bulkhead

tended to produce a rattle type noise over

irregular road surfaces. The introduction Content of the Bottle Jack and 3 piece handle

allows storage of the all the Jacking components under the Left Hand Seat for

an improved stowage installation.

Action: No action required. This is a notification of change of supplied condition from vin. 9A768482.