



Models LD - Defender

Title Defender Steering Box Parts return

Last Modified 06-NOV-2008 12:03

Category Chassis

Symptom 303000 Steering/Handling

<u>Issue:</u> Change to Steering Box parts supply & condition of returned units under warranty.

<u>Cause:</u> To reduce complexity of replacement Steering Box supplied conditions. All Defender new (outright) and exchange Steering boxes will be supplied complete with Drop Arm fitted. From June 2008 onwards.

Action: Please ensure that the Drop Arm is not removed from the original Steering Box when the part is returned via warranty. If the Steering Box is Content returned with the arm removed this may invalidate the warranty. If you currently have a new (outright) or exchange Steering Box in stock that does not have a Drop Arm fitted, it will be necessary to order a new Drop Arm prior to fitment which can be claimed with the warranty submission.

IMPORTANT

For both a new (outright) or exchange unit, also ensure that the steering box adjustment is not disturbed, or any other fixings on the steering box assembly not related to it's removal/installation when returned via a warranty claim.