Models LD - Defender

Title Defender 07 My on Vacuum Pump replacement procedure change

Last Modified 22-MAY-2009 08:55

**Category Chassis** 

Symptom 301000 Service Brake System

Issue: Changes to service process Defender 2007my

Methods engineers at Land Rover have recently studied the service process for renewal of the brake vacuum pump for Defender (LD) 2007MY onwards models (2.4 Puma).

In the new procedure the coolant fan is no longer removed and the battery is not disconnected.

Content Should it become necessary to renew the brake vacuum pump on Defender (LD) 2007MY onwards models (2.4 Puma), refer to the updated procedure on GTR section 206-07: Power Brake Actuation.

## Old Repair Time

70.50.19 – Vacuum pump – brake booster – renew - 0.70hrs

## **New Repair Time**

70.50.19 - Vacuum pump - brake booster renew - 0.40hrs